

RSIWMSL VDR/TNPCB/2023-24/017
Dated: 18th April, 2023



To
The Member Secretary
Tamil Nadu Pollution Control Board
No.76, Anna Salai,
Chennai-600032

Subject: RSIWMSL-CHWTSDF-Submission of Form 4 of 2022-2023 Regarding


Respected Sir

Please find enclosed herewith Form-4 of Re Sustainability IWM Solutions Limited, Common Hazardous Waste Treatment Storage and Disposal Facility situated at Undurmikidakulam, Tiruchuli taluk, Virudhunagar district for the period from April 2022 to March 2023 as per Hazardous and Other Waste (Management and Transboundary Movement) Rules, 2016.

Kindly acknowledge the receipt of the same

Thanking You.

Yours sincerely,
For Re Sustainability IWM Solutions Limited,


Authorized Signatory

Enclosure

- Form 4 of 2022-2023
- Form 3 of 2022-2023

cc: 1. District Environment Engineer, Virudhunagar

Re Sustainability IWM Solutions Limited.
(Formerly known as Tamil Nadu Waste Management Limited and
Ramky Industrial Waste Management Solutions Limited)

Site Address:
SF No-135-140,143-148 & 152,
Undurmikidakulam, A.Mukkulam PO, Thiruchuli
Taluk, Virudhunagar - 620 611, Tamilnadu, India

Registered Office:
Re Sustainability Limited,
(Formerly known as Ramky Enviro Engineers Limited)
Level 118, Aurobindo Galaxy,
Hyderabad Knowledge City,
111, Park Street, Hyderabad-500 081

Certificate Reg No: 44 100 20392865 (ISO 9001: 2015)
Certificate Reg No: 44 104 20392865 (ISO 14001: 2015)
Certificate Reg No: 44 126 20392865 (ISO 45001: 2018)



T: +91 99400 12676

E: mbd@reusl.com / info@reusl.com

FORM 4

[See rules 6(5), 13(8), 16(6) and 20 (2)]

FORM FOR FILING ANNUAL RETURNS

[For the period of April to March 2022-23]

1.	Name and address of facility:	RE SUSTAINABILITY IWM SOLUTIONS LTD., S.F. No – 137 to 140,143 to 148,152 Undurmikidakulam,, Tiruchuli-TK Virudhunagar Dt.-630611 Tamilnadu - State.
2.	Authorization No. and Date of issue:	16HFC6540415 dated 09/12/2016
3.	Name of the authorized person and full address with telephone, fax number and e-mail:	Udayakumar.E 7708111449 udayakumar@resustainability.com
4.	Production during the year (product wise), wherever applicable:	NA

Part A. To be filled by hazardous waste generators

1.	Total quantity of waste generated category wise	NA	
2.	Quantity dispatched	(i) to disposal facility	NA
		(ii) to recycler or co-processors or pre-processor	NA
		(iii) others	NA
3.	Quantity utilized in-house, if any	NA	
4.	Quantity in storage at the end of the year	NA	

Part B. To be filled by Treatment, storage and disposal facility operators

1.	Total quantity received	18678.66 MT
2.	Quantity in stock at the beginning of the year	0 MT
3.	Quantity treated	14198.50 MT
4.	Quantity disposed in landfills as such and after treatment	18678.66 MT
5.	Quantity incinerated (if applicable)	NA
6.	Quantity processed other than specified above	NA
7.	Quantity in storage at the end of the year	0 MT

Part C. To be filled by recyclers or co-processors or other users

1.	Quantity of waste received during the year (i) domestic sources (ii) Imported (if applicable)	NA NA
2.	Quantity in stock at the beginning of the year	NA
3.	Quantity recycled or co-processed or used	NA
4.	Quantity of products dispatched (wherever applicable)	NA
5.	Quantity of waste generated	NA
6.	Quantity of waste disposed	NA
7.	Quantity re-exported (wherever applicable)	NA
8.	Quantity in storage at the end of the year	NA

NA- Not Applicable

All the Quantities in M.Tons

Signature of the Operator of the disposal facility

Date: 18.04.2023

Place: Virudhunagar


Authorized Signatory

RE Sustainability IWM Solutions Ltd.- Undurmikidakulam, Virudhunagar Dist.

FORM - 3

Waste Received Details - April-22 to Mar-23

SI No	Date of receipt	Manifest No	Manifest Date	Truck No.	Name of the Industry	Location	Waste Category	Waste Name	Quantity in MT	Disposal Method
1	01.04.2022	000503	31.03.2022	TN38BR9255	Jayachandran alloys (P) Ltd.	Perundurai	9.1	Waste slag	18.16	LAT-147
2	01.04.2022	000504	31.03.2022	TN38CE0694	Jayachandran alloys (P) Ltd.	Perundurai	9.1	Waste slag	18.08	LAT-147
3	04.04.2022	000505	03.04.2022	TN38BW0249	Jayachandran alloys (P) Ltd.	Perundurai	9.1	Waste slag	18.05	LAT-147
4	04.04.2022	000506	03.04.2022	TN38BR9255	Jayachandran alloys (P) Ltd.	Perundurai	9.1	Waste slag	18.1	LAT-147
5	04.04.2022	007238	04.04.2022	TN59CA4795	K.P.R. MILL Ltd.	Perundurai	35.3	ETP Residual waste	17.82	LAT-75
6	04.04.2022	007528	04.04.2022	TN23BL5836	K.P.R. MILL Ltd.	Perundurai	35.3	ETP Residual waste	17.61	LAT-75
7	04.04.2022	007437	04.04.2022	TN67BJ2452	K.P.R. MILL Ltd.	Perundurai	35.3	ETP Residual waste	19.55	LAT-75
8	04.04.2022	007504	04.04.2022	TN59CA5614	K.P.R. MILL Ltd.	Perundurai	35.3	ETP Residual waste	18.73	LAT-75
9	04.04.2022	007456	04.04.2022	TN59CB8706	K.P.R. MILL Ltd.	Perundurai	35.3	ETP Residual waste	18	LAT-75
10	04.04.2022	007331	04.04.2022	TN67BJ6163	K.P.R. MILL Ltd.	Perundurai	35.3	ETP Residual waste	19.71	LAT-75
11	04.04.2022	007380	04.04.2022	TN67BJ6181	K.P.R. MILL Ltd.	Perundurai	35.3	ETP Residual waste	19.41	LAT-75
12	04.04.2022	007470	04.04.2022	TN67BJ6024	K.P.R. MILL Ltd.	Perundurai	35.3	ETP Residual waste	20.42	LAT-75
13	05.04.2022	007493	05.04.2022	TN59CA5675	Sundaram Fasteners Limited	Virudhunagar	35.3	Salt	18.77	LAT-75
14	05.04.2022	007471	05.04.2022	TN67BJ6024	Sundaram Fasteners Limited	Virudhunagar	35.3	Salt	19.48	LAT-75
15	05.04.2022	007494	05.04.2022	TN59CA5675	Sundaram Fasteners Limited	Virudhunagar	35.3	Salt	19.83	LAT-75
16	05.04.2022	007472	05.04.2022	TN67BJ6024	Sundaram Fasteners Limited	Virudhunagar	35.3	Salt	20.43	LAT-75
17	05.04.2022	007482	05.04.2022	TN59CA4752	Zirconium Complex (Unit of NFC)	Tuticorin	37.1	Neutralised Slit	17.72	LAT-75
18	05.04.2022	007529	05.04.2022	TN23BL5836	Zirconium Complex (Unit of NFC)	Tuticorin	Schedule -II, Class-C	Washed & Dried Slit	15.96	LAT-93
19	05.04.2022	007369	05.04.2022	TN11-K-1747	Zirconium Complex (Unit of NFC)	Tuticorin	Schedule -II, Class-C	Neutralised Slit	16.62	LAT-75
20	05.04.2022	007428	05.04.2022	TN66E9714	Zirconium Complex (Unit of NFC)	Tuticorin	Schedule -II, Class-C	Washed & Dried Slit	16.95	LAT-93
21	06.04.2022	007457	06.04.2022	TN59CB8706	Sundaram Fasteners Limited	Virudhunagar	35.3	Salt	20.2	LAT-75
22	06.04.2022	007370	06.04.2022	TN11-K-1747	Sundaram Fasteners Limited	Virudhunagar	35.3	Salt	19.47	LAT-75
23	06.04.2022	007381	06.04.2022	TN67BJ6181	Sither metal Industry	Tuticorin	9.1	Lead slag	23.47	DLF
24	06.04.2022	007473	06.04.2022	TN67BJ6024	Sither metal Industry	Tuticorin	9.1	Lead slag	24.14	DLF
25	06.04.2022	007458	06.04.2022	TN59CB8706	Sundaram Fasteners Limited	Virudhunagar	35.3	Salt	18.6	LAT-75
26	06.04.2022	007540	06.04.2022	TN11-K-1747	Sundaram Fasteners Limited	Virudhunagar	35.3	Salt	18.92	LAT-75
27	07.04.2022	007382	07.04.2022	TN67BJ6181	Sundaram Fasteners Limited	Virudhunagar	35.3	ETP sludge	17.38	LAT-9
28	07.04.2022	007444	07.04.2022	TN59CA4795	Sundaram Fasteners Limited	Virudhunagar	35.3	ETP sludge	16.61	LAT-9
29	07.04.2022	007446	07.04.2022	TN67BJ6181	Sundaram Fasteners Limited	Virudhunagar	35.3	ETP sludge	18.72	LAT-9
30	07.04.2022	007445	07.04.2022	TN59CA4795	Sundaram Fasteners Limited	Virudhunagar	35.3	ETP sludge	17.15	LAT-9
31	07.04.2022	007541	07.04.2022	TN11K1747	Zirconium Complex (Unit of NFC)	Tuticorin	37.1	Neutralised Slit	17.83	LAT-75
32	07.04.2022	007495	07.04.2022	TN59CA5675	Zirconium Complex (Unit of NFC)	Tuticorin	Schedule -II, Class-C	Washed & Dried Slit	17.8	LAT-93
33	07.04.2022	007531	07.04.2022	TN23BL5836	Zirconium Complex (Unit of NFC)	Tuticorin	Schedule -II, Class-C	Washed & Dried Slit	18.63	LAT-93
34	07.04.2022	007483	07.04.2022	TN59CA4752	Zirconium Complex (Unit of NFC)	Tuticorin	37.1	Neutralised Slit	17.2	LAT-75
35	08.04.2022	000507	05.04.2022	TN38BR9255	Jayachandran alloys (P) Ltd.	Perundurai	9.1	Waste slag	18.46	LAT-147
36	08.04.2022	007439	08.04.2022	TN67BJ2452	Sundaram Fasteners Limited	Virudhunagar	35.3	ETP sludge	17.92	LAT-9
37	08.04.2022	007459	08.04.2022	TN59CB8706	Sundaram Fasteners Limited	Virudhunagar	35.3	ETP sludge	18.24	LAT-9
38	08.04.2022	007440	08.04.2022	TN67BJ2452	Sundaram Fasteners Limited	Virudhunagar	35.3	ETP sludge	17.69	LAT-9
39	08.04.2022	007460	08.04.2022	TN59CB8706	Sundaram Fasteners Limited	Virudhunagar	35.3	ETP sludge	17.94	LAT-9
40	08.04.2022	007532	08.04.2022	TN23BL5836	Zirconium Complex (Unit of NFC)	Tuticorin	37.1	Neutralised Slit	17.86	LAT-75
41	08.04.2022	007542	08.04.2022	TN11K1747	Zirconium Complex (Unit of NFC)	Tuticorin	37.1	Neutralised Slit	18.01	LAT-75
42	08.04.2022	007208	08.04.2022	TN66E9184	Zirconium Complex (Unit of NFC)	Tuticorin	37.1	Neutralised Slit	17.71	LAT-75
43	08.04.2022	007506	08.04.2022	TN59CA5614	Zirconium Complex (Unit of NFC)	Tuticorin	Schedule -II, Class-C	Washed & Dried Slit	17.26	LAT-93
44	09.04.2022	007475	09.04.2022	TN67BJ6181	K.P.R. MILL Ltd.	Perundurai	35.3	ETP Residual waste	20.3	LAT-75
45	09.04.2022	007333	09.04.2022	TN67BJ6163	K.P.R. MILL Ltd.	Perundurai	35.3	ETP Residual waste	19.41	LAT-75
46	09.04.2022	007543	09.04.2022	TN11-K-1747	K.P.R. MILL Ltd.	Perundurai	35.3	ETP Residual waste	18.91	LAT-75
47	09.04.2022	007474	09.04.2022	TN67BJ6024	K.P.R. MILL Ltd.	Perundurai	35.3	ETP Residual waste	20.6	LAT-75
48	09.04.2022	007507	09.04.2022	TN59CA5614	K.P.R. MILL Ltd.	Perundurai	35.3	ETP Residual waste	18.93	LAT-75
49	09.04.2022	007484	09.04.2022	TN59CA4752	K.P.R. MILL Ltd.	Perundurai	35.3	ETP Residual waste	17.54	LAT-75
50	12.04.2022	000508	10.04.2022	TN38CE0694	Jayachandran alloys (P) Ltd.	Perundurai	9.1	Waste slag	18.56	LAT-147
51	12.04.2022	000509	10.04.2022	TN38BW0249	Jayachandran alloys (P) Ltd.	Perundurai	9.1	Waste slag	18.52	LAT-147
52	15.04.2022	000510	14.04.2022	TN38CE0694	Jayachandran alloys (P) Ltd.	Perundurai	9.1	Waste slag	18.23	LAT-147
53	15.04.2022	000511	14.04.2022	TN38BW0249	Jayachandran alloys (P) Ltd.	Perundurai	9.1	Waste slag	18.56	LAT-147
54	15.04.2022	007476	15.04.2022	TN67BJ6024	Sither metal Industry	Tuticorin	9.1	Lead slag	22.31	DLF
55	15.04.2022	007563	15.04.2022	TN67BJ6181	Sither metal Industry	Tuticorin	9.1	Lead slag	22.78	DLF
56	15.04.2022	007449	15.04.2022	TN59CA4795	Rane Brake Lining Ltd	Trichy	35.1	Gas cleaning residue	15.36	LAT-1

57	16.04.2022	007508	15.04.2022	TN59CA5614	Rane Brake Lining Ltd	Trichy	35.1	Gas cleaning residue	15.41	LAT-1
58	16.04.2022	000512	15.04.2022	TN38BR9255	Jayachandran alloys (P) Ltd.	Perundurai	9.1	Waste slag	18.2	LAT-147
59	18.04.2022	000513	17.04.2022	TN38CE0694	Jayachandran alloys (P) Ltd.	Perundurai	9.1	Waste slag	18.46	LAT-147
60	18.04.2022	000514	17.04.2022	TN38BW0249	Jayachandran alloys (P) Ltd.	Perundurai	9.1	Waste slag	18.14	LAT-147
61	19.04.2022	007544	18.04.2022	TN11K1747	Imperrial textile dyers	Erode	35.3	Sludge	16.38	LAT-10
62	19.04.2022	007564	18.04.2022	TN67BJ6181	Imperrial textile dyers	Erode	35.3	Sludge	16.5	LAT-10
63	19.04.2022	007429	19.04.2022	TN66E9714	Zirconium Complex (Unit of NFC)	Tuticorin	37.1	Neutralised Slit	17.43	LAT-75
64	19.04.2022	007486	19.04.2022	TN59CA4752	Zirconium Complex (Unit of NFC)	Tuticorin	37.1	Neutralised Slit	18.9	LAT-75
65	19.04.2022	007575	19.04.2022	TN67BJ6163	Zirconium Complex (Unit of NFC)	Tuticorin	Schedule -II, Class-C	Washed & Dried Slit	17.51	LAT-93
66	19.04.2022	007497	19.04.2022	TN59CA5675	Zirconium Complex (Unit of NFC)	Tuticorin	Schedule -II, Class-C	Washed & Dried Slit	17.85	LAT-93
67	20.04.2022	000515	19.04.2022	TN38BR9255	Jayachandran alloys (P) Ltd.	Perundurai	9.1	Waste slag	18.33	LAT-147
68	20.04.2022	000516	19.04.2022	TN38CE0694	Jayachandran alloys (P) Ltd.	Perundurai	9.1	Waste slag	18.06	LAT-147
69	20.04.2022	17	19.04.2022	TN38BW0249	Jayachandran Industries Pvt Ltd	Coimbatore	35.3	ETP sludge	12.65	LAT-88
70	20.04.2022	007209	20.04.2022	TN66E9184	Sundaram Fasteners Limited	Virudhunagar	35.3	Salt	23.19	LAT-75
71	20.04.2022	007487	20.04.2022	TN59CA4752	Sundaram Fasteners Limited	Virudhunagar	35.3	ETP sludge	16.8	LAT-9
72	20.04.2022	007488	20.04.2022	TN59CA4752	Sundaram Fasteners Limited	Virudhunagar	35.3	ETP sludge	17.72	LAT-9
73	20.04.2022	007210	20.04.2022	TN66E9184	Sundaram Fasteners Limited	Virudhunagar	35.3	ETP sludge	19.08	LAT-9
74	20.04.2022	007620	20.04.2022	TN67BJ2452	Zirconium Complex (Unit of NFC)	Tuticorin	37.1	Neutralised Slit	17.79	LAT-75
75	20.04.2022	007621	20.04.2022	TN59CA5614	Zirconium Complex (Unit of NFC)	Tuticorin	37.1	Neutralised Slit	18.49	LAT-75
76	20.04.2022	007619	20.04.2022	TN59CA4795	Zirconium Complex (Unit of NFC)	Tuticorin	Schedule -II, Class-C	Washed & Dried Slit	17.86	LAT-93
77	20.04.2022	007618	20.04.2022	TN11K1747	Zirconium Complex (Unit of NFC)	Tuticorin	Schedule -II, Class-C	Washed & Dried Slit	17.78	LAT-93
78	21.04.2022	007545	21.04.2022	TN11K1747	Rane Engine Valve Ltd (Plant-5)	Pudukottai	35.3	Waste Containing Sludge	22.79	DLF
79	21.04.2022	007533	20.04.2022	TN23BL5836	GTN Exports Ltd (Unit-II)	Tiruppur	35.3	Phosphate Sludge	0.4	LAT-101
80	21.04.2022	007534	20.04.2022	TN23BL5836	GTN Exports Ltd (Unit-II)	Tiruppur	35.3	Chemical Sludge	1.18	LAT-103
81	22.04.2022	000517	21.04.2022	TN38BW0249	Jayachandran alloys (P) Ltd.	Perundurai	9.1	Waste slag	18.39	LAT-147
82	22.04.2022	000518	21.04.2022	TN38CE0694	Jayachandran alloys (P) Ltd.	Perundurai	9.1	Waste slag	18.89	LAT-147
83	22.04.2022	000519	21.04.2022	TN38BR9255	Jayachandran alloys (P) Ltd.	Perundurai	9.1	Waste slag	18.21	LAT-147
84	22.04.2022	007477	21.04.2022	TN67BJ6024	Shri Kara Engineering Pvt Ltd	Coimbatore	35.3	Chemical Sludge	19.18	LAT-103
85	22.04.2022	007614	22.04.2022	TN23BL5836	Zirconium Complex (Unit of NFC)	Tuticorin	Schedule -II, Class-C	Washed & Dried Slit	17.65	LAT-93
86	22.04.2022	007617	22.04.2022	TN66E9714	Zirconium Complex (Unit of NFC)	Tuticorin	37.1	Neutralised Slit	15.88	LAT-75
87	22.04.2022	007616	22.04.2022	TN59CA4795	Zirconium Complex (Unit of NFC)	Tuticorin	37.1	Neutralised Slit	17.93	LAT-75
88	22.04.2022	007615	22.04.2022	TN59CA5675	Zirconium Complex (Unit of NFC)	Tuticorin	37.1	Neutralised Slit	17.93	LAT-75
89	25.04.2022	000520	24.04.2022	TN38BW0249	Jayachandran alloys (P) Ltd.	Perundurai	9.1	Waste slag	18.77	LAT-147
90	25.04.2022	000521	24.04.2022	TN38CE0694	Jayachandran alloys (P) Ltd.	Perundurai	9.1	Waste slag	18.58	LAT-147
91	25.04.2022	000522	24.04.2022	TN38BR9255	Jayachandran alloys (P) Ltd.	Perundurai	9.1	Waste slag	17.9	LAT-147
92	26.04.2022	007451	26.04.2022	TN59CA4795	Rane Brake Lining Ltd	Trichy	35.1	Gas cleaning residue	14.55	LAT-1
93	27.04.2022	007211	26.04.2022	TN66E9184	Rane Brake Lining Ltd	Trichy	35.1	Gas cleaning residue	14.55	LAT-1
94	27.04.2022	000523	26.04.2022	TN38CE0694	Jayachandran alloys (P) Ltd.	Perundurai	9.1	Waste slag	18.84	LAT-147
95	27.04.2022	000524	26.04.2022	TN38BR9255	Jayachandran alloys (P) Ltd.	Perundurai	9.1	Waste slag	18.55	LAT-147
96	27.04.2022	000525	26.04.2022	TN38BW0249	Jayachandran alloys (P) Ltd.	Perundurai	9.1	Waste slag	17.82	LAT-147
97	27.04.2022	007334	27.04.2022	TN67BJ6163	Navarang Dye Works	Karur	35.3	Salt from SEP	18.18	LAT-75
98	27.04.2022	007478	27.04.2022	TN67BJ6024	Navarang Dye Works	Karur	35.3	Salt from SEP	18.45	LAT-75
99	28.04.2022	007452	28.04.2022	TN59CA4795	Sither metal Industry	Tuticorin	9.1	Lead slag	18.48	DLF
100	28.04.2022	007588	28.04.2022	TN67BJ2452	Sither metal Industry	Tuticorin	9.1	Lead slag	22.97	DLF
101	29.04.2022	007510	28.04.2022	TN59CA5614	Imperrial textile dyers	Erode	35.3	Sludge	18.16	LAT-10
102	29.04.2022	007430	28.04.2022	TN66E9714	Imperrial textile dyers	Erode	35.3	Sludge	16.85	LAT-10
103	29.04.2022	000527	28.04.2022	TN38BW0249	Jayachandran alloys (P) Ltd.	Perundurai	9.1	Waste slag	18.49	LAT-147
104	29.04.2022	000526	28.04.2022	TN38CE0694	Jayachandran alloys (P) Ltd.	Perundurai	9.1	Waste slag	18.41	LAT-147
105	29.04.2022	007635	28.04.2022	TN67BJ6024	Chemplast Sanmar Limited(Plant-III)	Salem	16.3	Brine Sludge	17.27	DLF
106	29.04.2022	007576	28.04.2022	TN67BJ6163	Chemplast Sanmar Limited(Plant-III)	Salem	16.3	Brine Sludge	17.2	DLF
107	29.04.2022	007547	28.04.2022	TN11K1747	Chemplast Sanmar Limited(Plant-III)	Salem	16.3	Brine Sludge	16.87	DLF
108	29.04.2022	007489	28.04.2022	TN59CA4752	Chemplast Sanmar Limited(Plant-III)	Salem	16.3	Brine Sludge	17.79	DLF
109	30.04.2022	007589	29.04.2022	TN67BJ2452	Cabot Sanmar Limited	Salem	17.1	Process Acidic Residue	17.83	DLF
110	30.04.2022	007566	29.04.2022	TN67BJ6181	Medicare Enviro Systems	Thanjavur	37.2	Incineration Ash	12.06	DLF
111	30.04.2022	007498	29.04.2022	TN59CA 5675	Green Era Recyclers	Coimbatore	B1110	FL Tubes	3.07	LAT-197
112	30.04.2022	000528	29.04.2022	TN38BR9255	Jayachandran alloys (P) Ltd.	Perundurai	9.1	Waste slag	18.42	LAT-147
113	02.05.2022	000529	01.05.2022	TN38BW0249	Jayachandran alloys (P) Ltd.	Perundurai	9.1	Waste Slag	18.02	LAT-147
114	02.05.2022	000530	01.05.2022	TN38BR9255	Jayachandran alloys (P) Ltd.	Perundurai	9.1	Waste Slag	18.38	LAT-147
115	02.05.2022	007548	02.05.2022	TN11K1747	AGPL Rotary Printing	Tiruppur	35.3	ETP Chemical Sludge	16.72	LAT-134
116	02.05.2022	007490	02.05.2022	TN59CA4752	Zirconium Complex (Unit of NFC)	Tuticorin	Schedule -II, Class-C	Washed & Dried Slit	17.94	LAT-93

117	02.05.2022	007590	02.05.2022	TN67BJ2452	Zirconium Complex (Unit of NFC)	Tuticorin	37.1	Neutralised Slit	17.66	LAT-75
118	02.05.2022	007212	02.05.2022	TN66E9184	Zirconium Complex (Unit of NFC)	Tuticorin	Schedule -II, Class-C	Washed & Dried Slit	16.88	LAT-93
119	02.05.2022	007509	02.05.2022	TN59CA5614	Chemplast Sanmar Limited(Plant-III)	Salem	16.3	Brine Sludge	18.36	DLF
120	02.05.2022	007499	02.05.2022	TN59CA5675	Zirconium Complex (Unit of NFC)	Tuticorin	Schedule -II, Class-C	Washed & Dried Slit	18.53	LAT-93
121	02.05.2022	007453	02.05.2022	TN59CA4795	Chemplast Sanmar Limited(Plant-III)	Salem	16.3	Brine Sludge	18.01	DLF
122	02.05.2022	007567	02.05.2022	TN67BJ6181	Chemplast Sanmar Limited(Plant-III)	Salem	16.3	Brine Sludge	17.2	DLF
123	02.05.2022	007636	02.05.2022	TN67BJ6024	Chemplast Sanmar Limited(Plant-III)	Salem	16.3	Brine Sludge	17.29	DLF
124	03.05.2022	007464	02.05.2022	TN59CB8706	Golden Textile dyers	Erode	35.3	Sludge	17.74	LAT-49
125	03.05.2022	007535	02.05.2022	TN23BL5836	Premier Textile dyers	Erode	35.3	Sludge	14.23	LAT-1
126	04.05.2022	000531	03.05.2022	TN38BR9255	Jayachandran alloys (P) Ltd.	Perundurai	9.1	Waste Slag	18.49	LAT-147
127	05.05.2022	000532	04.05.2022	TN38BW0249	Jayachandran alloys (P) Ltd.	Perundurai	9.1	Waste Slag	17.99	LAT-147
128	05.05.2022	007684	05.05.2022	TN59CA5675	Zirconium Complex (Unit of NFC)	Tuticorin	Schedule -II, Class-C	Washed & Dried Slit	17.96	LAT-93
129	05.05.2022	007685	05.05.2022	TN59CA4752	Zirconium Complex (Unit of NFC)	Tuticorin	37.1	Neutralised Slit	17.37	LAT-75
130	05.05.2022	007686	05.05.2022	TN59CA4795	Zirconium Complex (Unit of NFC)	Tuticorin	37.1	Neutralised Slit	18.11	LAT-75
131	05.05.2022	007683	05.05.2022	TN67BJ6163	Zirconium Complex (Unit of NFC)	Tuticorin	37.1	Neutralised Slit	16.49	LAT-75
132	06.05.2022	000533	05.05.2022	TN38CE0694	Jayachandran alloys (P) Ltd.	Perundurai	9.1	SLAG WASTE	18.190	LAT-147
133	06.05.2022	007591	06.05.2022	TN67BJ2452	Chemplast Sanmar Limited(Plant-III)	Salem	16.3	Brine Sludge	17.53	DLF
134	06.05.2022	007600	06.05.2022	TN59CA4795	Chemplast Sanmar Limited(Plant-III)	Salem	16.3	Brine Sludge	18.15	DLF
135	06.05.2022	007568	06.05.2022	TN67BJ6181	Chemplast Sanmar Limited(Plant-III)	Salem	16.3	Brine Sludge	17.26	DLF
136	06.05.2022	007647	06.05.2022	TN11K1747	Chemplast Sanmar Limited(Plant-III)	Salem	16.3	Brine Sludge	16.67	DLF
137	06.05.2022	007687	06.05.2022	TN59CA4752	Zirconium Complex (Unit of NFC)	Tuticorin	Schedule -II, Class-C	Washed & Dried Slit	17.42	LAT-93
138	06.05.2022	007688	06.05.2022	TN59CA5675	Zirconium Complex (Unit of NFC)	Tuticorin	Schedule -II, Class-C	Washed & Dried Slit	14.15	LAT-93
139	06.05.2022	007689	06.05.2022	TN59CA5614	Zirconium Complex (Unit of NFC)	Tuticorin	37.1	Neutralised Slit	16.63	LAT-75
140	06.05.2022	007690	06.05.2022	TN67BJ6163	Zirconium Complex (Unit of NFC)	Tuticorin	37.1	Neutralised Slit	16.38	LAT-75
141	06.05.2022	007536	06.05.2022	TN23BL5836	Karpaga VinayagarDyeing	Erode	35.3	ETP sludge	12.96	DLF
142	07.05.2022	000534	06.05.2022	TN38BR9255	Jayachandran alloys (P) Ltd.	Perundurai	9.1	SLAG WASTE	18.480	LAT-147
143	07.05.2022	007671	07.05.2022	TN59CB8706	Sirius Zip fasteners (P) Ltd.	Sivagangai	6.2	Zinc dust	0.089	LAT-103
144	07.05.2022	007466	07.05.2022	TN59CB8706	JK Fenner India Ltd.	Madurai	35.3	Chemical sludge from WWT	0.59	LAT-9
145	08.05.2022	007638	07.05.2022	TN67BJ6024	Chemplast Sanmar Limited(Plant-III)	Salem	16.3	Brine Sludge	17.33	DLF
146	08.05.2022	007592	07.05.2022	TN67BJ2452	Chemplast Sanmar Limited(Plant-III)	Salem	16.3	Brine Sludge	17.26	DLF
147	08.05.2022	007648	07.05.2022	TN11-K-1747	Chemplast Sanmar Limited(Plant-III)	Salem	16.3	Brine Sludge	16.31	DLF
148	08.05.2022	007552	07.05.2022	TN66E9714	Rajapalayam mills Ltd.	Virudhunagar	35.3	Chemical sludge from WWT	16.04	LAT-1
149	09.05.2022	000535	08.05.2022	TN38CE0694	Jayachandran alloys (P) Ltd.	Perundurai	9.1	SLAG WASTE	17.910	LAT-147
150	09.05.2022	000536	08.05.2022	TN38BR9255	Jayachandran alloys (P) Ltd.	Perundurai	9.1	SLAG WASTE	18.710	LAT-147
151	10.05.2022	007500	10.05.2022	TN59CA5675	TVS sri chakra limited	Madurai	35.3	ETP Salt waste	18.02	LAT-75
152	11.05.2022	000537	10.05.2022	TN38CE0694	Jayachandran alloys (P) Ltd.	Perundurai	9.1	SLAG WASTE	18.89	LAT-147
153	12.05.2022	000538	11.05.2022	TN38BR9255	Jayachandran alloys (P) Ltd.	Perundurai	9.1	SLAG WASTE	18.63	LAT-147
154	12.05.2022	007593	12.05.2022	TN67BJ2452	K.P.R. MILL Ltd.	Perundurai	35.3	ETP Waste	20.7	LAT-75
155	12.05.2022	007672	12.05.2022	TN59CB8706	TVS sri chakra limited	Madurai	35.3	ETP Salt waste	18	LAT-75
156	12.05.2022	007601	12.05.2022	TN59CA4795	K.P.R. MILL Ltd.	Perundurai	35.3	ETP Waste	18.12	LAT-75
157	12.05.2022	007649	12.05.2022	TN11-K-1747	K.P.R. MILL Ltd.	Perundurai	35.3	ETP Waste	18.21	LAT-75
158	12.05.2022	007569	12.05.2022	TN67BJ6181	K.P.R. MILL Ltd.	Perundurai	35.3	ETP Waste	20.59	LAT-75
159	12.05.2022	007639	12.05.2022	TN67BJ6024	K.P.R. MILL Ltd.	Perundurai	35.3	ETP Waste	20.64	LAT-75
160	13.05.2022	007213	12.05.2022	TN66E9184	Aseptic systems BMWW company	Tirunelveli	37.2	Incineration Ash	17.34	DLF
161	13.05.2022	000539	12.05.2022	TN38CE0694	Jayachandran alloys (P) Ltd.	Perundurai	9.1	SLAG WASTE	18.22	LAT-147
162	13.05.2022	007650	13.05.2022	TN11K1747	Sundaram Fasteners Limited	Virudhunagar	35.3	Chemical sludge from WWT	18.24	LAT-9
163	13.05.2022	007651	13.05.2022	TN11K1747	Sundaram Fasteners Limited	Virudhunagar	35.3	Chemical sludge from WWT	17.45	LAT-9
164	14.05.2022	007570	13.05.2022	TN67BJ6181	Emaar Lead Company Pvt Ltd	Coimbatore	9.1	SLAG WASTE	18.05	DLF
165	14.05.2022	007512	13.05.2022	TN59CA5614	Emaar Lead Company Pvt Ltd	Coimbatore	9.1	SLAG WASTE	18.8	DLF
166	14.05.2022	007501	14.05.2022	TN59CA5675	Sundaram Fasteners Limited	Virudhunagar	35.3	Chemical sludge from WWT	17.910	LAT-9
167	14.05.2022	007537	14.05.2022	TN23BL5836	K.P.R. MILL Ltd.	Perundurai	35.3	ETP Waste	17.710	LAT-75
168	14.05.2022	007594	14.05.2022	TN67BJ2452	K.P.R. MILL Ltd.	Perundurai	35.3	ETP Waste	20.58	LAT-75
169	14.05.2022	007640	14.05.2022	TN67BJ6024	K.P.R. MILL Ltd.	Perundurai	35.3	ETP Waste	20.32	LAT-75
170	14.05.2022	007652	14.05.2022	TN11K1747	K.P.R. MILL Ltd.	Perundurai	35.3	ETP Waste	18.41	LAT-75
171	14.05.2022	007659	14.05.2022	TN59CA4752	K.P.R. MILL Ltd.	Perundurai	35.3	ETP Waste	17.84	LAT-75
172	14.05.2022	007502	14.05.2022	TN59CA5675	Sundaram Fasteners Limited	Virudhunagar	35.3	Salt	21.96	LAT-75
173	14.05.2022	007578	14.05.2022	TN67BJ6163	Sither Metal Industry	Tuticorin	9.1	Lead Slag	22.76	DLF
174	17.05.2022	000540	16.05.2022	TN38CE0694	Jayachandran alloys (P) Ltd.	Perundurai	9.1	SLAG WASTE	18.2	LAT-147
175	17.05.2022	000541	16.05.2022	TN38BR9255	Jayachandran alloys (P) Ltd.	Perundurai	9.1	SLAG WASTE	18.77	LAT-147
176	17.05.2022	007743	16.05.2022	TN64L5887	Kothari Pytochemicals Internationals	Madurai	35.3	Sludge	1.135	DLF

177	18.05.2022	007214	17.05.2022	TN66E9184	Rane Brake Lining Ltd	Trichy	35.1	Gas Cleaning Residue	15.17	LAT-1
178	18.05.2022	007553	17.05.2022	TN66E9714	Rane Brake Lining Ltd	Trichy	35.1	Gas Cleaning Residue	13.9	LAT-1
179	18.05.2022	007653	18.05.2022	TN11K1747	TVS sri chakra limited	Madurai	35.3	ETP Salt waste	18.59	LAT-75
180	19.05.2022	007580	18.05.2022	TN59CA5614	Rane Brake Lining Ltd	Trichy	35.1	Gas Cleaning Residue	14.49	LAT-1
181	19.05.2022	007579	18.05.2022	TN67BJ6163	Rane Brake Lining Ltd	Trichy	35.1	Gas Cleaning Residue	10.78	LAT-1
182	19.05.2022	007581	18.05.2022	TN67BJ6163	Rane Brake Lining Ltd	Trichy	12.5	Phosphate sludge	3	DLF
183	19.05.2022	007538	18.05.2022	TN23BL5836	Imperial Textile Dyers	Erode	35.3	Sludge	16.94	LAT-10
184	19.05.2022	000542	18.05.2022	TN38CE0694	Jayachandran alloys (P) Ltd.	Perundurai	9.1	SLAG WASTE	18.41	LAT-147
185	19.05.2022	007602	18.05.2022	TN59CA4795	Theni guru krishnan textile mills (P) Ltd	Theni	35.3	sludge	17.79	LAT-75
186	20.05.2022	000543	19.05.2022	TN38BR9255	Jayachandran alloys (P) Ltd.	Perundurai	9.1	SLAG WASTE	18.99	LAT-147
187	20.05.2022	007731	20.05.2022	TN23BL5836	TVS sri chakra limited	Madurai	35.3	ETP Sludge waste	17.44	LAT-75
188	20.05.2022	007603	20.05.2022	TN59CA4795	K.P.R. MILL Ltd.	Perundurai	35.3	ETP Waste	17.86	LAT-75
189	20.05.2022	007641	20.05.2022	TN67BJ6024	K.P.R. MILL Ltd.	Perundurai	35.3	ETP Waste	20.41	LAT-75
190	20.05.2022	007654	20.05.2022	TN11K1747	K.P.R. MILL Ltd.	Perundurai	35.3	ETP Waste	16.79	LAT-75
191	20.05.2022	007571	20.05.2022	TN67BJ6181	K.P.R. MILL Ltd.	Perundurai	35.3	ETP Waste	20.11	LAT-75
192	20.05.2022	007660	20.05.2022	TN59CA4752	K.P.R. MILL Ltd.	Perundurai	35.3	ETP Waste	18.27	LAT-75
193	20.05.2022	007595	20.05.2022	TN67BJ2452	K.P.R. MILL Ltd.	Perundurai	35.3	ETP Waste	20.69	LAT-75
194	20.05.2022	007513	20.05.2022	TN59CA5614	K.P.R. MILL Ltd.	Perundurai	35.3	ETP Waste	18.92	LAT-75
195	21.05.2022	000544	20.05.2022	TN38CE0694	Jayachandran alloys (P) Ltd.	Perundurai	9.1	SLAG WASTE	18.04	LAT-147
196	21.05.2022	007655	21.05.2022	TN11K1747	K.P.R. MILL Ltd.	Perundurai	35.3	ETP Waste	19.19	LAT-75
197	21.05.2022	007661	21.05.2022	TN59CA4752	K.P.R. MILL Ltd.	Perundurai	35.3	ETP Waste	17.68	LAT-75
198	21.05.2022	007572	21.05.2022	TN67BJ6181	K.P.R. MILL Ltd.	Perundurai	35.3	ETP Waste	20.9	LAT-75
199	21.05.2022	007582	21.05.2022	TN67BJ6163	K.P.R. MILL Ltd.	Perundurai	35.3	ETP Waste	20.73	LAT-75
200	21.05.2022	007642	21.05.2022	TN67BJ6024	K.P.R. MILL Ltd.	Perundurai	35.3	ETP Waste	20.55	LAT-75
201	21.05.2022	007604	21.05.2022	TN59CA4795	K.P.R. MILL Ltd.	Perundurai	35.3	ETP Waste	18.1	LAT-75
202	21.05.2022	007514	21.05.2022	TN59CA5614	K.P.R. MILL Ltd.	Perundurai	35.3	ETP Waste	18.37	LAT-75
203	21.05.2022	007732	21.05.2022	TN23BL5836	Ramesh Flowers Pvt Ltd	Tuticorin	35.3	ETP sludge	14.36	DLF
204	21.05.2022	007551	21.05.2022	TN66E9714	Rajapalayam mills Ltd.	Virudhunagar	35.3	Salt	17.05	LAT-75
205	23.05.2022	000545	22.05.2022	TN38CE0694	Jayachandran alloys (P) Ltd.	Perundurai	9.1	SLAG WASTE	18.26	LAT-147
206	23.05.2022	000546	22.05.2022	TN38BR9255	Jayachandran alloys (P) Ltd.	Perundurai	9.1	SLAG WASTE	18.61	LAT-147
207	24.05.2022	007662	23.05.2022	TN59CA4752	Chemplast Sanmar Limited(Plant-III)	Salem	16.3	Brine Sludge	17.68	DLF
208	24.05.2022	007656	23.05.2022	TN11K1747	Chemplast Sanmar Limited(Plant-III)	Salem	16.3	Brine Sludge	16.69	DLF
209	24.05.2022	007583	23.05.2022	TN67BJ6163	Chemplast Sanmar Limited(Plant-III)	Salem	16.3	Brine Sludge	17.02	DLF
210	24.05.2022	007554	23.05.2022	TN66E9714	Sri energy valves(p) ltd	Pudukkottai	11.4	Flue gas dust	6.13	DLF
211	24.05.2022	007643	24.05.2022	TN67BJ6024	Sither Metal Industry	Tuticorin	9.1	Lead Slag	22.06	DLF
212	25.05.2022	007744	24.05.2022	TN59CA5614	Southern petrochemical industries corporation Ltd	Tuticorin	18.1	Iron Catalyst	19.13	DLF
213	25.05.2022	007605	25.05.2022	TN59CA4795	Sundaram Fasteners Limited	Virudhunagar	35.3	Chemical sludge from WWT	18.62	LAT-9
214	25.05.2022	007606	25.05.2022	TN59CA4795	Sundaram Fasteners Limited	Virudhunagar	35.3	Chemical sludge from WWT	18.02	LAT-9
215	25.05.2022	007695	25.05.2022	TN66E9184	Sundaram Fasteners Limited	Virudhunagar	35.3	Salt	23.48	LAT-75
216	25.05.2022	007555	25.05.2022	TN66E9714	Sundaram Fasteners Limited	Virudhunagar	35.3	Salt	20.71	LAT-75
217	26.05.2022	007596	25.05.2022	TN67BJ2452	Chemplast Sanmar Limited(Plant-III)	Salem	16.3	Brine Sludge	17.61	DLF
218	26.05.2022	007673	25.05.2022	TN59CB8706	Chemplast Sanmar Limited(Plant-III)	Salem	16.3	Brine Sludge	18	DLF
219	26.05.2022	007707	25.05.2022	TN59CA5675	Chemplast Sanmar Limited(Plant-III)	Salem	16.3	Brine Sludge	18	DLF
220	26.05.2022	007657	25.05.2022	TN11K1747	Southern petrochemical industries corporation Ltd	Tuticorin	18.1	Iron Catalyst	16.39	DLF
221	26.05.2022	007573	25.05.2022	TN67BJ6181	Southern petrochemical industries corporation Ltd	Tuticorin	18.1	Iron Catalyst	18.9	DLF
222	26.05.2022	000547	25.05.2022	TN38BR9255	Jayachandran alloys (P) Ltd.	Perundurai	9.1	SLAG WASTE	18.58	LAT-147
223	27.05.2022	000548	26.05.2022	TN38CE0694	Jayachandran alloys (P) Ltd.	Perundurai	9.1	SLAG WASTE	18.43	LAT-147
224	27.05.2022	007663	26.05.2022	TN59CA4752	Santhome latex enterprises	Kanniyakumari	35.3	Chemical sludge from WWT	16.71	DLF
225	27.05.2022	007745	26.05.2022	TN59CA5614	Chemplast Sanmar Limited(Plant-III)	Salem	16.3	Brine Sludge	17.95	DLF
226	27.05.2022	007733	26.05.2022	TN23BL5836	Chemplast Sanmar Limited(Plant-III)	Salem	16.3	Brine Sludge	17.65	DLF
227	27.05.2022	007644	26.05.2022	TN67BJ6024	Chemplast Sanmar Limited(Plant-III)	Salem	16.3	Brine Sludge	17.28	DLF
228	27.05.2022	007756	26.05.2022	TN18BZ3957	Chemplast Sanmar Limited Sanmar speciality chemical division	Hosur	35.3	Salt waste	17.93	LAT-11
229	27.05.2022	007757	26.05.2022	TN18AW0651	Chemplast Sanmar Limited Sanmar speciality chemical division	Hosur	35.3	Salt waste	18.34	LAT-11
230	27.05.2022	007755	26.05.2022	TN18AW0616	Chemplast Sanmar Limited Sanmar speciality chemical division	Hosur	35.3	Salt waste	17.76	LAT-11
231	27.05.2022	007759	26.05.2022	TN12R8889	Titan company ltd(jwellery division)	Hosur	35.3	Used powder	17.485	DLF
232	27.05.2022	007758	26.05.2022	TN16B9549	Titan company ltd(jwellery division)	Hosur	35.3	Used powder	18.18	DLF
233	27.05.2022	007574	27.05.2022	TN67BJ6181	Southern petrochemical industries corporation Ltd	Tuticorin	18.1	Iron Catalyst	18.4	DLF

234	27.05.2022	007658	27.05.2022	TN11K1747	Southern petrochemical industries corporation Ltd	Tuticorin	18.1	Iron Catalyst	17.4	DLF
235	27.05.2022	007708	27.05.2022	TN59CA5675	Malar dyeing works	Karur	35.3	ATFD waste	18.32	LAT-75
236	28.05.2022	000549	27.05.2022	TN38BR9255	Jayachandran alloys (P) Ltd.	Perundurai	9.1	SLAG WASTE	18.71	LAT-147
237	30.05.2022	000550	29.05.2022	TN38CE0694	Jayachandran alloys (P) Ltd.	Perundurai	9.1	SLAG WASTE	18.64	LAT-147
238	30.05.2022	000551	29.05.2022	TN38BR9255	Jayachandran alloys (P) Ltd.	Perundurai	9.1	SLAG WASTE	18.87	LAT-147
239	31.05.2022	000552	30.05.2022	TN38BR9255	Jayachandran alloys (P) Ltd.	Perundurai	9.1	SLAG WASTE	18.11	LAT-147
240	31.05.2022	007815	30.05.2022	TN767BJ6181	Southern petrochemical industries corporation Ltd	Tuticorin	18.1	Iron Catalyst	14.14	DLF
241	31.05.2022	007607	30.05.2022	TN59CA4795	Southern petrochemical industries corporation Ltd	Tuticorin	18.1	Iron Catalyst	16.86	DLF
242	31.05.2022	007767	30.05.2022	TN11K1747	Imperrial Textile Dyers	Erode	35.3	Sludge	16.33	LAT-10
243	31.05.2022	007645	30.05.2022	TN67BJ6024	Cabot Sanmar Limited	Salem	17.1	Acidic residue dust filter cake	16.76	DLF
244	01.06.2022	000553	31.05.2022	TN38CE0694	Jayachandran alloys (P) Ltd.	Perundurai	9.1	Waste Slag	18.33	LAT-147
245	02.06.2022	000554	01.06.2022	TN38BR9255	Jayachandran alloys (P) Ltd.	Perundurai	9.1	Waste Slag	18.18	LAT-147
246	02.06.2022	007597	01.06.2022	TN67BJ2452	Chemplast Sanmar Limited(Plant-III)	Salem	16.3	Brine Sludge	17.44	DLF
247	02.06.2022	007768	01.06.2022	TN11K1747	Chemplast Sanmar Limited(Plant-III)	Salem	16.3	Brine Sludge	16.62	DLF
248	02.06.2022	007746	01.06.2022	TN59CA5614	Chemplast Sanmar Limited(Plant-III)	Salem	16.3	Brine Sludge	18.41	DLF
249	03.06.2022	000555	02.06.2022	TN38CE0694	Jayachandran alloys (P) Ltd.	Perundurai	9.1	Waste Slag	18.6	LAT-147
250	03.06.2022	007769	03.06.2022	TN11K1747	Sither metal Industry	Tuticorin	9.1	Lead slag	19.7	DLF
251	03.06.2022	007556	03.06.2022	TN66E9714	Atlas processing mills	Karur	35.3	ATFD salt	15.72	LAT-75
252	04.06.2022	007664	03.06.2022	TN59CA4752	Atlas processing mills	Karur	35.3	ATFD salt	18.685	LAT-75
253	04.06.2022	000556	03.06.2022	TN38BR9255	Jayachandran alloys (P) Ltd.	Perundurai	9.1	Waste Slag	18.73	LAT-147
254	06.06.2022	000557	05.06.2022	TN38CE0694	Jayachandran alloys (P) Ltd.	Perundurai	9.1	Waste Slag	18.38	LAT-147
255	06.06.2022	000558	05.06.2022	TN38BR9255	Jayachandran alloys (P) Ltd.	Perundurai	9.1	Waste Slag	18.37	LAT-147
256	06.06.2022	007747	06.06.2022	TN59CA5614	Rane Brake Lining Ltd	Trichy	35.1	Gas cleaning residue	13.96	LAT-1
257	07.06.2022	007557	06.06.2022	TN66E9714	Rane Brake Lining Ltd	Trichy	35.1	Gas cleaning residue	15.69	LAT-1
258	07.06.2022	007608	06.06.2022	TN59CA4795	Chemplast Sanmar Limited(Plant-III)	Salem	16.3	Brine Sludge	18.11	DLF
259	07.06.2022	007734	06.06.2022	TN23BL5836	Chemplast Sanmar Limited(Plant-III)	Salem	16.3	Brine Sludge	17.33	DLF
260	07.06.2022	007816	06.06.2022	TN67BJ6181	Chemplast Sanmar Limited(Plant-III)	Salem	16.3	Brine Sludge	17.29	DLF
261	07.06.2022	007748	07.06.2022	TN59CA5614	Sundaram Fasteners Limited	Virudhunagar	35.3	Salt(Collectef from ATFD)	21.13	LAT-75
262	07.06.2022	007749	07.06.2022	TN59CA5614	Sundaram Fasteners Limited	Virudhunagar	35.3	Chemical sludge from WWT	18.72	LAT-9
263	08.06.2022	007746	07.06.2022	TN67BJ6024	Premier Textile Dyers	Erode	35.3	Sludge	16.89	LAT-1
264	08.06.2022	007770	07.06.2022	TN11K1747	Golden Textile Dyers	Erode	35.3	Sludge	18.005	LAT-49
265	08.06.2022	000559	07.06.2022	TN38BR9255	Jayachandran alloys (P) Ltd.	Perundurai	9.1	Waste Slag	18.41	LAT-147
266	08.06.2022	007665	08.06.2022	TN59CA4752	Sundaram Fasteners Limited	Virudhunagar	35.3	Chemical sludge from WWT	18.73	LAT-9
267	08.06.2022	007666	08.06.2022	TN59CA4752	Sundaram Fasteners Limited	Virudhunagar	35.3	Chemical sludge from WWT	18.15	LAT-9
268	09.06.2022	007750	08.06.2022	TN59CA5614	Imperrial Textile Dyers	Erode	35.3	Sludge	17.26	LAT-10
269	09.06.2022	000560	08.06.2022	TN40P0275	Jayachandran alloys (P) Ltd.	Perundurai	9.1	Waste Slag	17.77	LAT-147
270	09.06.2022	000561	08.06.2022	TN38CE0694	Jayachandran alloys (P) Ltd.	Perundurai	9.1	Waste Slag	18.98	LAT-147
271	10.06.2022	000562	09.06.2022	TN38BR9255	Jayachandran alloys (P) Ltd.	Perundurai	9.1	Waste Slag	19.27	LAT-147
272	10.06.2022	007584	09.06.2022	TN67BJ6163	Chemplast Sanmar Limited(Plant-III)	Salem	16.3	Brine Sludge	16.95	DLF
273	10.06.2022	007609	09.06.2022	TN59CA4795	Chemplast Sanmar Limited(Plant-III)	Salem	16.3	Brine Sludge	17.84	DLF
274	10.06.2022	007598	09.06.2022	TN67BJ2452	Chemplast Sanmar Limited(Plant-III)	Salem	16.3	Brine Sludge	17.32	DLF
275	10.06.2022	007723	10.06.2022	TN28AB5365	Ramky Energy and Environment Ltd	Virudhunagar	37.2	Incineration ash	0.205	DLF
276	11.06.2022	000563	09.06.2022	TN40P0275	Jayachandran alloys (P) Ltd.	Perundurai	9.1	Waste Slag	17.52	LAT-147
277	11.06.2022	000564	10.06.2022	TN38CE0694	Jayachandran alloys (P) Ltd.	Perundurai	9.1	Waste Slag	18.5	LAT-147
278	11.06.2022	007675	10.06.2022	TN59CB8706	Sibaflor natural decorations pvt ltd	Tuticorin	35.3	Chemical sludge from WWT	11.26	LAT-10
279	11.06.2022	007771	10.06.2022	TN11K1747	Craftsman automation limited(unit-3)Sheet metal division	Coimbatore	12.5	Phosphate sludge	1.28	LAT-161
280	11.06.2022	007772	10.06.2022	TN11K1747	Craftsman automation limited(unit-3)Sheet metal division	Coimbatore	35.3	Chemical sludge from WWT	1.15	LAT-11
281	11.06.2022	007773	10.06.2022	TN11K1747	Craftsman automation limited(unit-3)	Coimbatore	35.3	Chemical sludge from WWT	0.61	LAT-163
282	13.06.2022	000565	12.06.2022	TN38BR9255	Jayachandran alloys (P) Ltd.	Perundurai	9.1	Waste Slag	18.38	LAT-147
283	13.06.2022	000566	12.06.2022	TN40P0275	Jayachandran alloys (P) Ltd.	Perundurai	9.1	Waste Slag	18.82	LAT-147
284	13.06.2022	000567	12.06.2022	TN38CE0694	Jayachandran alloys (P) Ltd.	Perundurai	9.1	Waste Slag	18.15	LAT-147
285	13.06.2022	007827	11.06.2022	TN67BJ6024	Chemplast Sanmar Limited(Plant-III)	Salem	16.3	Brine Sludge	17.66	DLF
286	13.06.2022	007751	11.06.2022	TN59CA5614	Chemplast Sanmar Limited(Plant-III)	Salem	16.3	Brine Sludge	18.71	DLF
287	13.06.2022	007610	11.06.2022	TN59CA4795	Chemplast Sanmar Limited(Plant-III)	Salem	16.3	Brine Sludge	18.07	DLF
288	14.06.2022	007774	13.06.2022	TN11K1747	AGPL rotary printing	Tirupur	35.3	ETP Chemical sludge	17.09	LAT-134
289	14.06.2022	007817	13.06.2022	TN67BJ6181	Green Era recyclers	Coimbatore	A2010	CRT Glass	2.5	LAT-198
290	14.06.2022	007818	13.06.2022	TN67BJ6181	Green Era recyclers	Coimbatore	A2010	FL glass	1.26	LAT-197
291	14.06.2022	007752	14.06.2022	TN59CA5614	TVS sri chakra limited	Madurai	35.3	ETP sludge waste (Salt)	18.56	LAT-75
292	15.06.2022	000568	14.06.2022	TN38BR9255	Jayachandran alloys (P) Ltd.	Perundurai	9.1	Waste Slag	18	LAT-147
293	15.06.2022	000569	14.06.2022	TN40P0275	Jayachandran alloys (P) Ltd.	Perundurai	9.1	Waste Slag	18.34	LAT-147

294	15.06.2022	007775	15.06.2022	TN11K1747	Sundaram Fasteners Limited	Virudhunagar	35.3	Salt/Collectef from ATFD	21.75	LAT-75
295	15.06.2022	007776	15.06.2022	TN11K1747	Sundaram Fasteners Limited	Virudhunagar	35.3	Chemical sludge from WWT	18.14	LAT-9
296	15.06.2022	007753	15.06.2022	TN59CA5614	Atlas processing mills	Karur	35.3	ATFD salt	18.88	LAT-75
297	15.06.2022	007851	15.06.2022	TN67BJ2452	Atlas processing mills	Karur	35.3	ATFD salt	17.905	LAT-75
298	16.06.2022	007828	15.06.2022	TN67BJ6024	Atlas processing mills	Karur	35.3	ATFD salt	17.32	LAT-75
299	16.06.2022	007852	16.06.2022	TN67BJ2452	Atlas processing mills	Karur	35.3	ATFD salt	17.96	LAT-75
300	16.06.2022	007735	15.06.2022	TN23BL5836	Chemplast Sanmar Limited(Plant-III)	Salem	16.3	Brine Sludge	17.67	DLF
301	16.06.2022	007674	15.06.2022	TN59CA4752	Chemplast Sanmar Limited(Plant-III)	Salem	16.3	Brine Sludge	17.83	DLF
302	16.06.2022	007585	15.06.2022	TN67BJ6163	Chemplast Sanmar Limited(Plant-III)	Salem	16.3	Brine Sludge	17.19	DLF
303	17.06.2022	007777	16.06.2022	TN11K1747	Atlas processing mills	Karur	35.3	ATFD salt	16.125	LAT-75
304	17.06.2022	000570	16.06.2022	TN40P0275	Jayachandran alloys (P) Ltd.	Perundurai	9.1	Waste Slag	17.9	LAT-147
305	17.06.2022	007819	16.06.2022	TN67BJ6181	Aseptic systems BMWW company	Tiunelveli	37.2	Incineration ash	15.73	DLF
306	17.06.2022	007676	16.06.2022	TN59CB8706	Jagan knit printer	Tirupur	35.3	Chemical sludge from WWT	2.3	LAT-5
307	17.06.2022	007677	16.06.2022	TN59CB8706	M.S.Prints	Tirupur	35.3	Chemical sludge from WWT	0.84	LAT-72
308	17.06.2022	007678	16.06.2022	TN59CB8706	Rhythm fashion printing unit	Tirupur	35.3	Chemical sludge from WWT	0.15	LAT-134
309	17.06.2022	007679	16.06.2022	TN59CB8706	New Hi-Tech Prints	Tirupur	35.3	Chemical sludge from WWT	0.18	LAT-5
310	17.06.2022	007680	16.06.2022	TN59CB8706	Sindhu tex prints	Tirupur	35.3	Chemical sludge from WWT	1.6	LAT-37
311	17.06.2022	007681	16.06.2022	TN59CB8706	CPS textiles(P)Ltd unit-1	Tirupur	35.3	Chemical sludge from WWT	0.1	LAT-124
312	17.06.2022	007682	16.06.2022	TN59CB8706	KGR knit printings	Tirupur	35.3	Chemical sludge from WWT	0.09	LAT-49
313	17.06.2022	007839	16.06.2022	TN59CB8706	Print harvest	Tirupur	35.3	Chemical sludge from WWT	1.63	LAT-1
314	17.06.2022	007840	16.06.2022	TN59CB8706	Coral printss	Tirupur	35.3	Chemical sludge from WWT	4.36	LAT-10
315	18.06.2022	000571	17.06.2022	TN40P0275	Jayachandran alloys (P) Ltd.	Perundurai	9.1	Waste Slag	18.68	LAT-147
316	18.06.2022	007853	17.06.2022	TN67BJ2452	Trichy metals & alloys	Trichy	9.1	Lead slag	17.59	LAT-9
317	18.06.2022	007899	18.06.2022	TN59CB8706	Sibaflor natural decorations pvt ltd	Tuticorin	35.3	Chemical sludge from WWT	12.2	LAT-10
318	20.06.2022	000572	19.06.2022	TN38BR9255	Jayachandran alloys (P) Ltd.	Perundurai	9.1	Waste Slag	19.15	LAT-147
319	21.06.2022	000573	20.06.2022	TN40P0275	Jayachandran alloys (P) Ltd.	Perundurai	9.1	Waste Slag	18.06	LAT-147
320	21.06.2022	000574	20.06.2022	TN38BR9255	Jayachandran alloys (P) Ltd.	Perundurai	9.1	Waste Slag	18.31	LAT-147
321	21.06.2022	007863	20.06.2022	TN59CA5614	Chemplast Sanmar Limited(Plant-I)	Salem	35.3	Chemical sludge from WWT	8.03	DLF
322	21.06.2022	007754	20.06.2022	TN59CA5614	Chemplast Sanmar Limited(Plant-III)	Salem	35.3	Chemical sludge from WWT	9.88	DLF
323	22.06.2022	000575	21.06.2022	TN38CE0694	Jayachandran alloys (P) Ltd.	Perundurai	9.1	Waste Slag	18.48	LAT-147
324	22.06.2022	000576	21.06.2022	TN40P0275	Jayachandran alloys (P) Ltd.	Perundurai	9.1	Waste Slag	18.13	LAT-147
325	22.06.2022	007558	22.06.2022	TN66E9714	TVS sri chakra limited	Madurai	35.3	ETP sludge waste (Salt)	18.73	LAT-75
326	23.06.2022	000577	22.05.2022	TN40P0275	Jayachandran alloys (P) Ltd.	Perundurai	9.1	Waste Slag	18.11	LAT-147
327	23.06.2022	000578	22.05.2022	TN38CE0694	Jayachandran alloys (P) Ltd.	Perundurai	9.1	Waste Slag	18.2	LAT-147
328	24.06.2022	000579	23.06.2022	TN38BR9255	Jayachandran alloys (P) Ltd.	Perundurai	9.1	Waste Slag	18.16	LAT-147
329	24.06.2022	000580	23.06.2022	TN40P0275	Jayachandran alloys (P) Ltd.	Perundurai	9.1	Waste Slag	17.67	LAT-147
330	25.06.2022	000581	24.06.2022	TN38CE0694	Jayachandran alloys (P) Ltd.	Perundurai	9.1	Waste Slag	18.18	LAT-147
331	25.06.2022	000582	24.06.2022	TN40P0275	Jayachandran alloys (P) Ltd.	Perundurai	9.1	Waste Slag	17.97	LAT-147
332	25.06.2022	007829	24.06.2022	TN67BJ6024	Imperrial Textile Dyers	Erode	35.3	Sludge	17.53	LAT-10
333	25.06.2022	007778	24.06.2022	TN11K1747	Imperrial Textile Dyers	Erode	35.3	Sludge	17.14	LAT-10
334	26.06.2022	000583	25.06.2022	TN38BR9255	Jayachandran alloys (P) Ltd.	Perundurai	9.1	Waste Slag	18.24	LAT-147
335	26.06.2022	000584	25.06.2022	TN38CE0694	Jayachandran alloys (P) Ltd.	Perundurai	9.1	Waste Slag	18.15	LAT-147
336	26.06.2022	007841	25.06.2022	TN59CA4795	Cabot Sanmar Limited	Salem	17.1	Residue dust of filter cake	18.06	DLF
337	26.06.2022	007854	25.06.2022	TN67BJ2452	Rane Brake Lining Ltd	Trichy	35.1	Gas cleaning residue	15.12	LAT-1
338	26.06.2022	007865	25.06.2022	TN59CA5614	Rane Brake Lining Ltd	Trichy	35.1	Gas cleaning residue	14.76	LAT-1
339	27.06.2022	000585	26.06.2022	TN40P0275	Jayachandran alloys (P) Ltd.	Perundurai	9.1	Waste Slag	18.23	LAT-147
340	27.06.2022	000586	26.06.2022	TN38CE0694	Jayachandran alloys (P) Ltd.	Perundurai	9.1	Waste Slag	18.46	LAT-147
341	27.06.2022	007866	27.06.2022	TN59CA5614	Sundaram Fasteners Limited	Virudhunagar	35.3	Chemical sludge from WWT	16.82	LAT-9
342	27.06.2022	007867	27.06.2022	TN59CA5614	Sundaram Fasteners Limited	Virudhunagar	35.3	Chemical sludge from WWT	20.51	LAT-9
343	28.06.2022	000587	27.06.2022	TN38BR9255	Jayachandran alloys (P) Ltd.	Perundurai	9.1	Waste Slag	18.01	LAT-147
344	28.06.2022	000588	27.06.2022	TN38CE0694	Jayachandran alloys (P) Ltd.	Perundurai	9.1	Waste Slag	18.59	LAT-147
345	29.06.2022	000589	28.06.2022	TN38CE0694	Jayachandran alloys (P) Ltd.	Perundurai	9.1	Waste Slag	18.36	LAT-147
346	29.06.2022	000590	28.06.2022	TN40P0275	Jayachandran alloys (P) Ltd.	Perundurai	9.1	Waste Slag	18.48	LAT-147
347	29.06.2022	007830	28.06.2022	TN67BJ6024	Ordnance Factory	Trichy	35.5	Chromium sludge	8.714	LAT-10
348	29.06.2022	007831	28.06.2022	TN67BJ6024	Ordnance Factory	Trichy	12.5	Phosphate sludge	1.26	LAT-20
349	29.06.2022	007832	28.06.2022	TN67BJ6024	Ordnance Factory	Trichy	9.1	Lead waste	0.096	LAT-21
350	29.06.2022	007900	28.06.2022	TN59CB8706	K.A Printers	Tirupur	35.3	Chemical sludge from WWT	0.1	LAT-1
351	29.06.2022	007901	28.06.2022	TN59CB8706	Gayathri screen printing	Tirupur	35.3	Chemical sludge from WWT	0.64	LAT-142
352	29.06.2022	007902	28.06.2022	TN59CB8706	Moorthi printing	Tirupur	35.3	Chemical sludge from WWT	0.09	LAT-49
353	29.06.2022	007903	28.06.2022	TN59CB8706	Jayakumaran exports unit-1	Tirupur	35.3	Chemical sludge from WWT	0.19	LAT-1

354	29.06.2022	007904	28.06.2022	TN59CB8706	Knit fashions print art	Tirupur	35.3	Chemical sludge from WWT	0.29	LAT-10
355	29.06.2022	007905	28.06.2022	TN59CB8706	Supreme printer	Tirupur	35.3	Chemical sludge from WWT	0.27	DLF
356	29.06.2022	007906	28.06.2022	TN59CB8706	Ramya knit printing	Tirupur	35.3	Chemical sludge from WWT	0.18	DLF
357	29.06.2022	007907	28.06.2022	TN59CB8706	Coral printss	Tirupur	35.3	Chemical sludge from WWT	5.49	LAT-10
358	30.06.2022	000591	28.06.2022	TN38BR9255	Jayachandran alloys (P) ltd.	Perundurai	9.1	Waste Slag	18.65	LAT-147
359	30.06.2022	007696	29.06.2022	TN66E9184	ATC Tires Private Littmed	Tirunelveli	35.3	Chemical sludge from ETP	2.55	LAT-10
360	30.06.2022	007697	29.06.2022	TN66E9184	Floor Décor	Tuticorin	35.3	Chemical sludge from ETP	3.3	LAT-1
361	30.06.2022	007698	29.06.2022	TN66E9184	Venus Home Appliances(P)Ltd	Tuticorin	12.5	Phosphate sludge	4.06	DLF
362	30.06.2022	007726	30.06.2022	TN28AB5365	Ramky Energy and Environment Ltd	Virudhunagar	37.2	Incineration ash	7.205	DLF
363	01.07.2022	000592	30.06.2022	TN38CE0694	Jayachandran Alloys Pvt Ltd	Perundurai	9.1	Waste Slag	18.27	LAT-147
364	01.07.2022	000593	30.06.2022	TN38BW0249	Jayachandran Alloys Pvt Ltd	Perundurai	9.1	Waste Slag	18.86	LAT-147
365	01.07.2022	000018	30.06.2022	TN40P0275	Jayachandran Industry Pvt Ltd	Coimbatore	35.3	ETP Sludge	15.825	LAT-88
366	01.07.2022	007888	01.07.2022	TN11K1747	K.P.R. Mill Limited	Perundurai	35.3	ETP waste	20.68	LAT-75
367	01.07.2022	007857	01.07.2022	TN67BJ2452	K.P.R. Mill Limited	Perundurai	35.3	ETP waste	20.68	LAT-75
368	01.07.2022	007875	01.07.2022	TN67BJ6163	K.P.R. Mill Limited	Perundurai	35.3	ETP waste	21.49	LAT-75
369	01.07.2022	007668	01.07.2022	TN59CA4752	K.P.R. Mill Limited	Perundurai	35.3	ETP waste	17.54	LAT-75
370	01.07.2022	007709	01.07.2022	TN59CA5675	K.P.R. Mill Limited	Perundurai	35.3	ETP waste	18.53	LAT-75
371	01.07.2022	007868	01.07.2022	TN59CA5614	Needle Industries india Pvt. Ltd.	Nilgiris	35.3	Sludge Powder	15.32	LAT-105
372	01.07.2022	007833	01.07.2022	TN67BJ6024	Needle Industries india Pvt. Ltd.	Nilgiris	35.3	Sludge Powder	16.095	LAT-105
373	02.07.2022	007736	01.07.2022	TN23BL5836	Needle Industries india Pvt. Ltd.	Nilgiris	35.3	Sludge Powder	16.835	LAT-105
374	02.07.2022	000595	01.07.2022	TN38BW0249	Jayachandran Alloys Pvt Ltd	Perundurai	9.1	Waste Slag	18.62	LAT-147
375	02.07.2022	000594	01.07.2022	TN38BR9255	Jayachandran Alloys Pvt Ltd	Perundurai	9.1	Waste Slag	18.95	LAT-147
376	02.07.2022	007669	02.07.2022	TN59CA4752	K.P.R. Mill Limited	Perundurai	35.3	ETP waste	18.02	LAT-75
377	02.07.2022	007869	02.07.2022	TN59CA5614	K.P.R. Mill Limited	Perundurai	35.3	ETP waste	18.99	LAT-75
378	02.07.2022	007710	02.07.2022	TN59CA5675	K.P.R. Mill Limited	Perundurai	35.3	ETP waste	18.96	LAT-75
379	02.07.2022	007842	02.07.2022	TN59CA4795	K.P.R. Mill Limited	Perundurai	35.3	ETP waste	18.37	LAT-75
380	03.07.2022	007820	02.07.2022	TN67BJ6181	K.P.R. Mill Limited	Perundurai	35.3	ETP waste	21.06	LAT-75
381	03.07.2022	007876	02.07.2022	TN67BJ6163	K.P.R. Mill Limited	Perundurai	35.3	ETP waste	20.86	LAT-75
382	03.07.2022	007834	02.07.2022	TN67BJ6024	K.P.R. Mill Limited	Perundurai	35.3	ETP waste	21.61	LAT-75
383	03.07.2022	007858	02.07.2022	TN67BJ2452	K.P.R. Mill Limited	Perundurai	35.3	ETP waste	21.26	LAT-75
384	03.07.2022	007889	02.07.2022	TN11K1747	Encee Aromatics (P) Ltd	Coimbatore	35.3	Salt from ETP	17.275	LAT-75
385	04.07.2022	000596	03.07.2022	TN38BW0249	Jayachandran Alloys Pvt Ltd	Perundurai	9.1	Waste Slag	18.73	LAT-147
386	04.07.2022	000597	03.07.2022	TN38CE0694	Jayachandran Alloys Pvt Ltd	Perundurai	9.1	Waste Slag	18.32	LAT-147
387	04.07.2022	007737	04.07.2022	TN23BL5836	Sundram Fasteners Ltd	Virudhunagar	35.3	Chemical Sludge from WWT	19.59	LAT-9
388	04.07.2022	007843	04.07.2022	TN59CA4795	Sundram Fasteners Ltd	Virudhunagar	35.3	Salt(Collected from ATFD)	18.65	LAT-75
389	04.07.2022	007738	04.07.2022	TN23BL5836	Sundram Fasteners Ltd	Virudhunagar	35.3	Chemical Sludge from WWT	18.26	LAT-9
390	04.07.2022	007844	04.07.2022	TN59CA4795	Sundram Fasteners Ltd	Virudhunagar	35.3	Chemical Sludge from WWT	18	LAT-9
391	04.07.2022	007859	04.07.2022	TN67BJ2452	Jasmine Towels Pvt Ltd	Sivagangai	35.3	Mixed Salt	16.26	LAT-1
392	04.07.2022	007821	04.07.2022	TN67BJ6181	Jasmine Towels Pvt Ltd	Sivagangai	35.3	Mixed Salt	17.34	LAT-1
393	04.07.2022	007890	04.07.2022	TN11-K-1747	Zirconium complex	Tuticorin	Schedule-2, class-C	Washed & Dried Silt	16.06	LAT-93
394	04.07.2022	007870	04.07.2022	TN59CA5614	Zirconium complex	Tuticorin	37.1	Neutralised silt	17.01	LAT-75
395	05.07.2022	000598	04.07.2022	TN38BR9255	Jayachandran Alloys Pvt Ltd	Perundurai	9.1	Waste Slag	17.92	LAT-147
396	05.07.2022	007924	04.07.2022	TN59CB8706	Hindustan Unilever Limited	Dindugal	A6	Removed insulation material	0.76	DLF
397	05.07.2022	007923	04.07.2022	TN59CB8706	Hindustan Unilever Limited	Dindugal	35.3	ETP Sludge	4.85	LAT-155
398	06.07.2022	000599	05.07.2022	TN38BW0249	Jayachandran Alloys Pvt Ltd	Perundurai	9.1	Waste Slag	18.37	LAT-147
399	06.07.2022	007739	06.07.2022	TN23BL5836	TVS srachakra Limited	Madurai	35.3	ETP sludge waste	17.74	LAT-75
400	07.07.2022	000600	06.07.2022	TN38BR9255	Jayachandran Alloys Pvt Ltd	Perundurai	9.1	Waste Slag	18.68	LAT-147
401	07.07.2022	000601	06.07.2022	TN38CE0694	Jayachandran Alloys Pvt Ltd	Perundurai	9.1	Waste Slag	18.35	LAT-147
402	08.07.2022	007822	07.07.2022	TN67BJ6181	Chemplast sanmar Limited (Plant-3)	Salem	16.3	Brine sludge	17.2	DLF
403	08.07.2022	007740	07.07.2022	TN23BL5836	Chemplast sanmar Limited (Plant-3)	Salem	16.3	Brine sludge	17.66	DLF
404	08.07.2022	007864	07.07.2022	TN59CA5614	Chemplast sanmar Limited (Plant-3)	Salem	16.3	Brine sludge	18.41	DLF
405	08.07.2022	000602	07.07.2022	TN38BW0249	Jayachandran Alloys Pvt Ltd	Perundurai	9.1	Waste Slag	18.64	LAT-147
406	08.07.2022	007711	07.07.2022	TN59CA5675	K.P.R. Mill Limited	Perundurai	35.3	ETP waste	19.24	LAT-75
407	08.07.2022	007586	07.07.2022	TN67BJ6163	K.P.R. Mill Limited	Perundurai	35.3	ETP waste	21.62	LAT-75
408	08.07.2022	007836	08.07.2022	TN67BJ6024	K.P.R. Mill Limited	Perundurai	35.3	ETP waste	20.64	LAT-75
409	08.07.2022	007845	08.07.2022	TN59CA4795	K.P.R. Mill Limited	Perundurai	35.3	ETP waste	17.99	LAT-75
410	08.07.2022	007846	08.07.2022	TN59CA4752	K.P.R. Mill Limited	Perundurai	35.3	ETP waste	17.56	LAT-75
411	09.07.2022	000603	08.07.2022	TN38BR9255	Jayachandran Alloys Pvt Ltd	Perundurai	9.1	Waste Slag	17.8	LAT-147
412	09.07.2022	000604	08.07.2022	TN40P0275	Jayachandran Alloys Pvt Ltd	Perundurai	9.1	Waste Slag	18.03	LAT-147
413	09.07.2022	007741	09.07.2022	TN23BL5836	Sither metal industry	Tuticorin	9.1	Lead slag	17.36	DLF

414	09.07.2022	007847	09.07.2022	TN59CA4795	K.P.R. Mill Limited	Perundurai	35.3	ETP waste	18	LAT-75
415	09.07.2022	007861	09.07.2022	TN67BJ2452	K.P.R. Mill Limited	Perundurai	35.3	ETP waste	21.32	LAT-75
416	09.07.2022	007871	09.07.2022	TN59CA5614	K.P.R. Mill Limited	Perundurai	35.3	ETP waste	18.9	LAT-75
417	09.07.2022	007892	09.07.2022	TN11-K-1747	K.P.R. Mill Limited	Perundurai	35.3	ETP waste	21.13	LAT-75
418	09.07.2022	007877	09.07.2022	TN67BJ6163	K.P.R. Mill Limited	Perundurai	35.3	ETP waste	20.9	LAT-75
419	10.07.2022	000605	09.07.2022	TN38BW0249	Jayachandran Alloys Pvt Ltd	Perundurai	9.1	Waste Slag	18.53	LAT-147
420	10.07.2022	000019	09.07.2022	TN38CE0694	Jayachandran Industry Pvt. Ltd.	Coimbatore	35.3	ETP sludge	14.145	LAT-88
421	11.07.2022	000607	10.07.2022	TN38BR9255	Jayachandran Alloys Pvt Ltd	Perundurai	9.1	Waste Slag	18.1	LAT-147
422	11.07.2022	000606	10.07.2022	TN40P0275	Jayachandran Alloys Pvt Ltd	Perundurai	9.1	Waste Slag	18.16	LAT-147
423	12.07.2022	000608	11.07.2022	TN38BW0249	Jayachandran Alloys Pvt Ltd	Perundurai	9.1	Waste Slag	18.29	LAT-147
424	12.07.2022	007862	11.07.2022	TN67BJ2452	Chemplast sanmar Limited (Plant-3)	Salem	16.3	Brine sludge	17.51	DLF
425	12.07.2022	007823	11.07.2022	TN67BJ6181	Chemplast sanmar Limited (Plant-3)	Salem	16.3	Brine sludge	17.36	DLF
426	12.07.2022	007848	11.07.2022	TN59CA4795	Rane brake lining Ltd.	Trichy	35.1	Gas cleaning residue	14.81	LAT-1
427	12.07.2022	007712	11.07.2022	TN59CA5675	Rane brake lining Ltd.	Trichy	35.1	Gas cleaning residue	15.78	LAT-1
428	12.07.2022	007935	11.07.2022	TN59CA4752	Chemplast sanmar Limited (Plant-3)	Salem	16.3	Brine sludge	17.79	DLF
429	12.07.2022	007837	11.07.2022	TN67BJ6024	Chemplast sanmar Limited (Plant-3)	Salem	16.3	Brine sludge	17.24	DLF
430	12.07.2022	000609	11.07.2022	TN38CE0694	Jayachandran Alloys Pvt Ltd	Perundurai	9.1	Waste Slag	18.56	LAT-147
431	13.07.2022	000610	12.07.2022	TN40P0275	Jayachandran Alloys Pvt Ltd	Perundurai	9.1	Waste Slag	18.05	LAT-147
432	13.07.2022	000611	12.07.2022	TN38BR9255	Jayachandran Alloys Pvt Ltd	Perundurai	9.1	Waste Slag	18.39	LAT-147
433	14.07.2022	007878	13.07.2022	TN67BJ6163	Chemplast sanmar Limited (Plant-II) PVC division	Salem	35.3	Chemical Sludge from WWT	17.57	DLF
434	14.07.2022	007742	13.07.2022	TN23BL5836	Chemplast sanmar Limited (Plant-II) PVC division	Salem	35.3	Chemical Sludge from WWT	17.84	DLF
435	14.07.2022	007824	14.07.2022	TN67BJ6181	Meridean Textile Dyers	Erode	35.3	Sludge	16.34	LAT-37
436	15.07.2022	007925	14.07.2022	TN59CB8706	Chemplast sanmar Limited (Plant-II) PVC division	Salem	35.3	Chemical Sludge from WWT	17.45	DLF
437	15.07.2022	007894	14.07.2022	TN11-K-1747	Chemplast sanmar Limited (Plant-II) PVC division	Salem	35.3	Chemical Sludge from WWT	17.16	DLF
438	15.07.2022	007995	14.07.2022	TN67BJ2452	Premier textile dyers	Erode	35.3	Sludge	15.01	LAT-1
439	15.07.2022	000612	14.07.2022	TN38BW0249	Jayachandran Alloys Pvt Ltd	Perundurai	9.1	Waste Slag	18.05	LAT-147
440	15.07.2022	007838	14.07.2022	TN67BJ6024	Imperrial textile dyers	Erode	35.3	Sludge	18.48	LAT-10
441	15.07.2022	000613	14.07.2022	TN38CE0694	Jayachandran Alloys Pvt Ltd	Perundurai	9.1	Waste Slag	18.5	LAT-147
442	16.07.2022	007936	15.07.2022	TN59CA4752	Chemplast sanmar Limited (Plant-3)	Salem	16.3	Brine sludge	18.58	DLF
443	16.07.2022	007825	15.07.2022	TN67BJ6181	Chemplast sanmar Limited (Plant-3)	Salem	16.3	Brine sludge	17.25	DLF
444	16.07.2022	007947	15.07.2022	TN23BL5836	Chemplast sanmar Limited (Plant-II) PVC division	Salem	35.3	Chemical Sludge from WWT	17.84	DLF
445	16.07.2022	000614	15.07.2022	TN40P0275	Jayachandran Alloys Pvt Ltd	Perundurai	9.1	Waste Slag	17.82	LAT-147
446	16.07.2022	007873	15.07.2022	TN59CA5614	Chemplast sanmar Limited (Plant-3)	Salem	16.3	Brine sludge	18.31	DLF
447	16.07.2022	007879	15.07.2022	TN67BJ6163	Chemplast sanmar Limited (Plant-3)	Salem	16.3	Brine sludge	17.15	DLF
448	16.07.2022	007895	15.07.2022	TN11-K-1747	Rane Engine valve Ltd.,	Pudukkottai	35.3	Sludge	20.11	DLF
449	17.07.2022	000615	16.07.2022	TN38CE0694	Jayachandran Alloys Pvt Ltd	Perundurai	9.1	Waste Slag	18.47	LAT-147
450	17.07.2022	000616	16.07.2022	TN38BW0249	Jayachandran Alloys Pvt Ltd	Perundurai	9.1	Waste Slag	18.76	LAT-147
451	17.07.2022	007959	16.07.2022	TN67BJ6024	Aseptic Systems BMW Company	Tirunelveli	37.2	Sludge	15.88	LAT-1
452	17.07.2022	007996	16.07.2022	TN67BJ2452	Rajapalayam Mills Ltd	Virudhunagar	35.3	ATFD Salt	20.9	LAT-75
453	19.07.2022	000618	18.07.2022	TN38BW0249	Jayachandran Alloys Pvt Ltd	Perundurai	9.1	Waste Slag	18.52	LAT-147
454	19.07.2022	007826	18.07.2022	TN67BJ6181	Zirconium complex	Tuticorin	37.1	Neutralised silt	16.65	LAT-75
455	19.07.2022	007849	18.07.2022	TN59CA4795	Zirconium complex	Tuticorin	37.1	Neutralised silt	17.08	LAT-75
456	19.07.2022	007948	18.07.2022	TN23BL5836	Zirconium complex	Tuticorin	Schedule-2, class-C	Washed & Dried Silt	16.26	LAT-93
457	19.07.2022	007997	19.07.2022	TN67BJ2452	Sither metal industry	Tuticorin	9.1	Lead slag	24.34	DLF
458	19.07.2022	007874	19.07.2022	TN59CA5614	Zirconium complex	Tuticorin	Schedule-2, class-C	Washed & Dried Silt	16.96	LAT-93
459	19.07.2022	007880	19.07.2022	TN67BJ6163	Zirconium complex	Tuticorin	37.1	Neutralised silt	17.13	LAT-75
460	19.07.2022	007937	19.07.2022	TN59CA4752	Zirconium complex	Tuticorin	37.1	Neutralised silt	17.33	LAT-75
461	19.07.2022	007960	19.07.2022	TN67BJ6024	Zirconium complex	Tuticorin	37.1	Neutralised silt	17.33	LAT-75
462	19.07.2022	007896	19.07.2022	TN11K1747	E.I.D.parry (India)Ltd,Oonaiyur	Pudukkottai	35.3	Chemical Sludge	8.6	LAT-5
463	19.07.2022	007897	19.07.2022	TN11K1747	E.I.D.parry (India)Ltd,Saveriyarpuram	Pudukkottai	35.3	Chemical Sludge	7.91	LAT-5
464	20.07.2022	000617	18.07.2022	TN40P0275	Jayachandran Alloys Pvt Ltd	Perundurai	9.1	Waste Slag	18.44	LAT-147
465	20.07.2022	007881	20.07.2022	TN67BJ6163	Sundram Fasteners Ltd	Virudhunagar	35.3	Salt	17.11	LAT-75
466	20.07.2022	007961	20.07.2022	TN67BJ6024	Sundram Fasteners Ltd	Virudhunagar	35.3	Salt	21.12	LAT-75
467	20.07.2022	007882	20.07.2022	TN67BJ6163	Sundram Fasteners Ltd	Virudhunagar	35.3	Chemical Sludge from WWT	18.05	LAT-9
468	20.07.2022	007962	20.07.2022	TN67BJ6024	Sundram Fasteners Ltd	Virudhunagar	35.3	Chemical Sludge from WWT	16.75	LAT-9
469	20.07.2022	007622	20.07.2022	TN59CA5614	Chemplast sanmar Limited (Plant-3)	Salem	16.3	Brine sludge	18.47	DLF
470	20.07.2022	007713	20.07.2022	TN59CA5675	Zirconium complex	Tuticorin	Schedule-2, class-C	Washed & Dried Silt	16.65	LAT-93
471	20.07.2022	007949	20.07.2022	TN23BL5836	Zirconium complex	Tuticorin	Schedule-2, class-C	Washed & Dried Silt	16.88	LAT-93
472	20.07.2022	007971	20.07.2022	TN67BJ6181	Zirconium complex	Tuticorin	37.1	Neutralised silt	17.1	LAT-75
473	21.07.2022	007938	20.07.2022	TN59CA4752	Zirconium complex	Tuticorin	37.1	Neutralised silt	17.74	LAT-75

474	21.07.2022	007850	20.07.2022	TN59CA4795	Chemplast sanmar Limited (Plant-3)	Salem	16.3	Brine sludge	17.95	DLF
475	21.07.2022	007998	20.07.2022	TN67BJ2452	Chemplast sanmar Limited (Plant-3)	Salem	16.3	Brine sludge	17.37	DLF
476	21.07.2022	000619	20.07.2022	TN38CE0694	Jayachandran Alloys Pvt Ltd	Perundurai	9.1	Waste Slag	18.63	LAT-147
477	21.07.2022	007714	21.07.2022	TN59CA5675	Zirconium complex	Tuticorin	37.1	Neutralised silt	19.77	LAT-75
478	21.07.2022	007883	21.07.2022	TN67BJ6163	Zirconium complex	Tuticorin	Schedule-2, class-C	Washed & Dried Silt	16.98	LAT-93
479	22.07.2022	000621	21.07.2022	TN38BW0249	Jayachandran Alloys Pvt Ltd	Perundurai	9.1	Waste Slag	18.53	LAT-147
480	22.07.2022	000620	21.07.2022	TN40PO275	Jayachandran Alloys Pvt Ltd	Perundurai	9.1	Waste Slag	18.5	LAT-147
481	22.07.2022	007715	22.07.2022	TN59CA5675	TVS srichakra Limited	Madurai	35.3	ETP sludge waste	17.55	LAT-75
482	23.07.2022	007559	22.07.2022	TN66E9714	Rane brake lining Ltd.	Trichy	35.1	Gas cleaning residue	16.39	LAT-1
483	23.07.2022	007560	22.07.2022	TN67BJ6181	Rane brake lining Ltd.	Trichy	35.1	Gas cleaning residue	16.3	LAT-1
484	23.07.2022	000622	22.07.2022	TN38CE0694	Jayachandran Alloys Pvt Ltd	Perundurai	9.1	Waste Slag	18.21	LAT-147
485	23.07.2022	007898	21.07.2022	TN11K1747	Zirconium complex	Tuticorin	37.1	Neutralised silt	17.23	LAT-75
486	23.07.2022	007911	22.07.2022	TN59CA4795	Zirconium complex	Tuticorin	37.1	Neutralised silt	17.29	LAT-75
487	23.07.2022	008007	22.07.2022	TN59CA5614	Zirconium complex	Tuticorin	37.1	Neutralised silt	19.07	LAT-75
488	23.07.2022	007950	22.07.2022	TN23BL5836	Zirconium complex	Tuticorin	Schedule-2, class-C	Washed & Dried Silt	16.73	LAT-93
489	23.07.2022	007963	22.07.2022	TN67BJ6024	Zirconium complex	Tuticorin	Schedule-2, class-C	Washed & Dried Silt	17.14	LAT-93
490	23.07.2022	007939	23.07.2022	TN59CA4752	Zirconium complex	Tuticorin	37.1	Neutralised silt	17.27	LAT-75
491	23.07.2022	007926	23.07.2022	TN59CB8706	Zirconium complex	Tuticorin	37.1	Neutralised silt	18.27	LAT-75
492	23.07.2022	007999	23.07.2022	TN67BJ2452	Zirconium complex	Tuticorin	Schedule-2, class-C	Washed & Dried Silt	17.43	LAT-93
493	23.07.2022	007884	23.07.2022	TN67BJ6163	Zirconium complex	Tuticorin	Schedule-2, class-C	Washed & Dried Silt	20.16	LAT-93
494	25.07.2022	000623	24.07.2022	TN40PO275	Jayachandran Alloys Pvt Ltd	Perundurai	9.1	Waste Slag	18.57	LAT-147
495	25.07.2022	000624	24.07.2022	TN38BW0249	Jayachandran Alloys Pvt Ltd	Perundurai	9.1	Waste Slag	18.17	LAT-147
496	25.07.2022	007716	25.07.2022	TN59CA5675	Zirconium complex	Tuticorin	Schedule-2, class-C	Washed & Dried Silt	19.5	LAT-93
497	25.07.2022	007983	25.07.2022	TN11K1747	Zirconium complex	Tuticorin	Schedule-2, class-C	Washed & Dried Silt	18.51	LAT-93
498	25.07.2022	008008	25.07.2022	TN59CA5614	Zirconium complex	Tuticorin	37.1	Neutralised silt	18.94	LAT-75
499	25.07.2022	007912	25.07.2022	TN59CA4795	Zirconium complex	Tuticorin	37.1	Neutralised silt	17.16	LAT-75
500	25.07.2022	007964	25.07.2022	TN67BJ6024	Emaar lead company pvt ltd	Coimbatore	9.1	Slag	17.79	DLF
501	25.07.2022	007972	25.07.2022	TN67BJ6181	Emaar lead company pvt ltd	Coimbatore	9.1	Slag	17.75	DLF
502	26.07.2022	000625	25.07.2022	TN38CE0694	Jayachandran Alloys Pvt Ltd	Perundurai	9.1	Waste Slag	18.61	LAT-147
503	26.07.2022	007951	25.07.2022	TN23BL5836	Imperial textile dyers	Erode	35.3	Sludge	17.81	LAT-10
504	26.07.2022	007623	26.07.2022	TN67BJ2452	Zirconium complex	Tuticorin	Schedule-2, class-C	Washed & Dried Silt	17.87	LAT-93
505	26.07.2022	007611	26.07.2022	TN11K1747	Zirconium complex	Tuticorin	37.1	Neutralised silt	16.68	LAT-75
506	26.07.2022	007612	26.07.2022	TN59CA4752	Zirconium complex	Tuticorin	37.1	Neutralised silt	17.41	LAT-75
507	26.07.2022	007613	26.07.2022	TN59CA5614	Zirconium complex	Tuticorin	37.1	Neutralised silt	18.16	LAT-75
508	28.07.2022	000626	27.07.2022	TN38BW0249	Jayachandran Alloys Pvt Ltd	Perundurai	9.1	Waste Slag	18.7	LAT-147
509	28.07.2022	007965	27.07.2022	TN67BJ6024	Chemplast sanmar Limited (Plant-3)	Salem	16.3	Brine sludge	17.33	DLF
510	28.07.2022	007973	27.07.2022	TN67BJ6181	Chemplast sanmar Limited (Plant-3)	Salem	16.3	Brine sludge	17.25	DLF
511	28.07.2022	007984	27.07.2022	TN11K1747	Chemplast sanmar Limited (Plant-3)	Salem	16.3	Brine sludge	16.54	DLF
512	28.07.2022	007908	27.07.2022	TN59CB8706	Sri srinivasa dyeing	Namakkal	35.3	ETP Sludge	1.28	DLF
513	28.07.2022	007909	27.07.2022	TN59CB8706	Ravi Dyeing Works	Namakkal	35.3	Dyeing sludge	1.05	DLF
514	28.07.2022	007910	27.07.2022	TN59CB8706	Kamadhenu dyeings	Namakkal	35.3	Sludge	2.5	DLF
515	28.07.2022	007927	27.07.2022	TN59CB8706	Sri durga dyeing	Salem	35.3	Sludge	0.77	LAT-3
516	28.07.2022	007624	28.07.2022	TN67BJ6163	Zirconium complex	Tuticorin	37.1	Neutralised silt	19.51	LAT-75
517	28.07.2022	007940	28.07.2022	TN59CA4752	Zirconium complex	Tuticorin	37.1	Neutralised silt	18.41	LAT-75
518	28.07.2022	007717	28.07.2022	TN59CA5675	Zirconium complex	Tuticorin	Schedule-2, class-C	Washed & Dried Silt	18.18	LAT-93
519	28.07.2022	007952	28.07.2022	TN23BL5836	Zirconium complex	Tuticorin	Schedule-2, class-C	Washed & Dried Silt	16.62	LAT-93
520	29.07.2022	008001	28.07.2022	TN59CA4795	Chemplast sanmar Limited (Plant-3)	Salem	16.3	Brine sludge	18.04	DLF
521	29.07.2022	008009	28.07.2022	TN59CA5614	Chemplast sanmar Limited (Plant-3)	Salem	16.3	Brine sludge	18.38	DLF
522	29.07.2022	008000	28.07.2022	TN67BJ2452	Chemplast sanmar Limited (Plant-3)	Salem	16.3	Brine sludge	17.5	DLF
523	29.07.2022	007626	29.07.2022	TN23BL5836	Zirconium complex	Tuticorin	37.1	Neutralised silt	17.66	LAT-75
524	29.07.2022	007625	29.07.2022	TN59CA5675	Zirconium complex	Tuticorin	37.1	Neutralised silt	17.79	LAT-75
525	29.07.2022	007966	29.07.2022	TN67BJ6024	Zirconium complex	Tuticorin	Schedule-2, class-C	Washed & Dried Silt	17.92	LAT-93
526	29.07.2022	007985	29.07.2022	TN11K1747	Zirconium complex	Tuticorin	Schedule-2, class-C	Washed & Dried Silt	18.04	LAT-93
527	30.07.2022	000627	29.07.2022	TN38CE0694	Jayachandran Alloys Pvt Ltd	Perundurai	9.1	Waste Slag	18.47	LAT-147
528	30.07.2022	007913	30.07.2022	TN59CA4795	Jayam shree rotary	Tirupur	35.3	ETP Sludge	18.24	DLF
529	30.07.2022	008002	30.07.2022	TN67BJ2452	Jayam shree rotary	Tirupur	35.3	ETP Sludge	18.64	DLF
530	30.07.2022	008046	30.07.2022	TN11-K-1747	Zirconium complex	Tuticorin	37.1	Neutralised silt	16.69	LAT-75
531	30.07.2022	008045	30.07.2022	TN59CA5614	Zirconium complex	Tuticorin	37.1	Neutralised silt	18.71	LAT-75
532	30.07.2022	008044	30.07.2022	TN67BJ6163	Zirconium complex	Tuticorin	37.1	Neutralised silt	17.78	LAT-75
533	30.07.2022	008043	30.07.2022	TN67BJ6181	Zirconium complex	Tuticorin	Schedule-2, class-C	Washed & Dried Silt	17.63	LAT-93

534	01.08.2022	000628	31.07.2022	TN38BW0249	Jayachandran alloys pvt ltd	Perundurai	9.1	Waste slag	18.61	LAT-147
535	01.08.2022	000629	31.07.2022	TN38CE0694	Jayachandran alloys pvt ltd	Perundurai	9.1	Waste slag	18.73	LAT-147
536	02.08.2022	000630	01.08.2022	TN40P0275	Jayachandran alloys pvt ltd	Perundurai	9.1	Waste slag	18.31	LAT-147
537	03.08.2022	000631	02.08.2022	TN38BW0249	Jayachandran alloys pvt ltd	Perundurai	9.1	Waste slag	19.1	LAT-147
538	03.08.2022	007967	02.08.2022	TN67BJ6024	Imperiall textile dyers	Erode	35.3	Sludge	18.11	LAT-10
539	03.08.2022	007561	03.08.2022	TN66E9714	Rane Brake Lining Ltd	Trichy	35.1	Gas cleaning residue	16.79	LAT-1
540	03.08.2022	007914	03.08.2022	TN59CA4795	TVS Srichakra Ltd	Madurai	35.3	ETP sludge	17.96	LAT-75
541	04.08.2022	007931	03.08.2022	TN59CB8706	Anugraha valve castings limited(unit-I)	Coimbatore	35.3	ETP sludge	0.031	DLF
542	04.08.2022	007928	03.08.2022	TN59CB8706	Anugraha valve castings limited(unit-II)	Coimbatore	35.3	Phosphate sludge	0.857	DLF
543	04.08.2022	007930	03.08.2022	TN59CB8706	Anugraha valve castings limited(unit-II)	Coimbatore	35.3	ETP sludge	2.72	DLF
544	04.08.2022	007932	03.08.2022	TN59CB8706	Anugraha valve castings limited(unit-V)	Coimbatore	35.3	ETP sludge	0.059	LAT-103
545	04.08.2022	007933	03.08.2022	TN59CB8706	Anugraha valve castings limited(unit-VI)	Coimbatore	35.3	ETP sludge	0.065	DLF
546	04.08.2022	007929	03.08.2022	TN59CB8706	Tekno therm industries	Coimbatore	37.2	Incineration ash	5.55	DLF
547	04.08.2022	007934	03.08.2022	TN59CB8706	Tekno therm industries	Coimbatore	35.3	ETP sludge	2.17	LAT-11
548	04.08.2022	000632	03.08.2022	TN40P0275	Jayachandran alloys pvt ltd	Perundurai	9.1	Waste slag	18.29	LAT-147
549	04.08.2022	007699	04.08.2022	TN66E9184	J.K.Fenner (India) Ltd	Madurai	35.3	ETP chemical sludge	0.815	LAT-9
550	04.08.2022	007700	04.08.2022	TN66E9184	Sirius zip fasteners pvt ltd	Sivagangai	6.2	Zinc dust	0.07457	LAT-103
551	05.08.2022	007987	04.08.2022	TN11K1747	AGPL rotary printing	Tirupur	35.3	ETP chemical sludge	16.81	LAT-134
552	05.08.2022	000633	03.08.2022	TN38BW0249	Jayachandran alloys pvt ltd	Perundurai	9.1	Waste slag	19	LAT-147
553	05.08.2022	008067	05.08.2022	TN59CB8706	K.P.R.Mill Limited	Perundurai	35.3	ETP Waste	17.95	LAT-75
554	05.08.2022	008003	05.08.2022	TN67BJ2452	K.P.R.Mill Limited	Perundurai	35.3	ETP Waste	20.65	LAT-75
555	05.08.2022	007974	05.08.2022	TN67BJ6181	K.P.R.Mill Limited	Perundurai	35.3	ETP Waste	21.38	LAT-75
556	05.08.2022	007968	05.08.2022	TN67BJ6024	K.P.R.Mill Limited	Perundurai	35.3	ETP Waste	21.62	LAT-75
557	05.08.2022	007942	05.08.2022	TN59CA4752	K.P.R.Mill Limited	Perundurai	35.3	ETP Waste	17.81	LAT-75
558	06.08.2022	008004	06.08.2022	TN67BJ2452	K.P.R.Mill Limited	Perundurai	35.3	ETP Waste	21.98	LAT-75
559	06.08.2022	007953	06.08.2022	TN23BL5836	K.P.R.Mill Limited	Perundurai	35.3	ETP Waste	17.15	LAT-75
560	06.08.2022	007885	06.08.2022	TN67BJ6163	K.P.R.Mill Limited	Perundurai	35.3	ETP Waste	20.38	LAT-75
561	06.08.2022	008068	06.08.2022	TN59CB8706	K.P.R.Mill Limited	Perundurai	35.3	ETP Waste	18.44	LAT-75
562	06.08.2022	007943	06.08.2022	TN59CA4752	K.P.R.Mill Limited	Perundurai	35.3	ETP Waste	17.86	LAT-75
563	06.08.2022	007975	06.08.2022	TN67BJ6181	K.P.R.Mill Limited	Perundurai	35.3	ETP Waste	21.4	LAT-75
564	06.08.2022	007969	06.08.2022	TN67BJ6024	K.P.R.Mill Limited	Perundurai	35.3	ETP Waste	20.42	LAT-75
565	06.08.2022	007988	06.08.2022	TN11K1747	K.P.R.Mill Limited	Perundurai	35.3	ETP Waste	23.51	LAT-75
566	08.08.2022	007954	08.08.2022	TN23BL5836	Sundram Fasteners Ltd	Virudhunagar	35.3	Chemical sludge from WWT	18.1	LAT-9
567	08.08.2022	007955	08.08.2022	TN23BL5836	Sundram Fasteners Ltd	Virudhunagar	35.3	Chemical sludge from WWT	18.81	LAT-9
568	08.08.2022	007886	08.08.2022	TN67BJ6163	K.P.R.Mill Limited	Perundurai	35.3	ETP Waste	21.76	LAT-75
569	08.08.2022	007976	08.08.2022	TN67BJ6181	K.P.R.Mill Limited	Perundurai	35.3	ETP Waste	23.33	LAT-75
570	08.08.2022	007944	08.08.2022	TN59CA4752	K.P.R.Mill Limited	Perundurai	35.3	ETP Waste	18.09	LAT-75
571	08.08.2022	007989	08.08.2022	TN11K1747	K.P.R.Mill Limited	Perundurai	35.3	ETP Waste	17	LAT-75
572	08.08.2022	007970	08.08.2022	TN67BJ6024	K.P.R.Mill Limited	Perundurai	35.3	ETP Waste	20.1	LAT-75
573	10.08.2022	007990	10.08.2022	TN11K1747	Medicare Enviro Systems	Thanjavur	37.2	Incineration ash	15.76	DLF
574	10.08.2022	007718	10.08.2022	TN59CA5675	Medicare Enviro Systems	Thanjavur	37.2	Incineration ash	14.12	DLF
575	12.08.2022	007977	11.08.2022	TN67BJ6181	Golden Textile Dyers	Erode	35.3	Sludge	17.2	LAT-49
576	12.08.2022	007991	12.08.2022	TN11K1747	Zirconium Complex	Tuticorin	37.1	Neutralised silt	16.43	LAT-75
577	12.08.2022	008079	12.08.2022	TN66E9714	Zirconium Complex	Tuticorin	37.1	Neutralised silt	18.14	LAT-75
578	12.08.2022	008103	12.08.2022	TN67BJ6163	Zirconium Complex	Tuticorin	Schedule-2, class-C	Washed & Dried Silt	16.88	LAT-93
579	12.08.2022	008104	12.08.2022	TN59CA4752	Zirconium Complex	Tuticorin	Schedule-2, class-C	Washed & Dried Silt	17.62	LAT-93
580	12.08.2022	008006	12.08.2022	TN67BJ2452	Chemplast sanmar Limited (Plant-3)	Salem	16.3	Brine sludge	17.32	DLF
581	12.08.2022	008055	12.08.2022	TN59CA5675	Chemplast sanmar Limited (Plant-3)	Salem	16.3	Brine sludge	18.4	DLF
582	12.08.2022	008070	12.08.2022	TN59CB8706	Chemplast sanmar Limited (Plant-3)	Salem	16.3	Brine sludge	17.8	DLF
583	12.08.2022	008091	12.08.2022	TN67BJ6024	Chemplast sanmar Limited (Plant-3)	Salem	16.3	Brine sludge	17.47	DLF
584	13.08.2022	000634	11.08.2022	TN38CE0694	Jayachandran alloys pvt ltd	Perundurai	9.1	Waste slag	18.46	LAT-147
585	13.08.2022	007958	12.08.2022	TN23BL5836	Unitedcarbon solutions pvt ltd	Tirupur	35.3	Chemical sludge from WWT	5.5	LAT-5
586	13.08.2022	007956	12.08.2022	TN23BL5836	Rajavinayagar printing factory	Tirupur	35.3	Chemical sludge from WWT	4.58	LAT-134
587	13.08.2022	007957	12.08.2022	TN23BL5836	Rajavinayagar printing company	Tirupur	35.3	Chemical sludge from WWT	3.77	Lat-134
588	13.08.2022	008115	12.08.2022	TN23BL5836	Viskar fashions	Tirupur	35.3	Chemical sludge from WWT	0.12	LAT-142
589	13.08.2022	007701	13.08.2022	TN66E9184	Rajapalayam mills limited	Virudhunagar	35.3	ATFD Salt	17.75	LAT-75
590	13.08.2022	007992	13.08.2022	TN11K1747	Zirconium Complex	Tuticorin	37.1	Neutralised silt	16.99	LAT-75
591	13.08.2022	008056	13.08.2022	TN59CA5675	Zirconium Complex	Tuticorin	37.1	Neutralised silt	17.53	LAT-75
592	13.08.2022	007978	13.08.2022	TN67BJ6181	Zirconium Complex	Tuticorin	Schedule-2, class-C	Washed & Dried Silt	17.87	LAT-93
593	13.08.2022	007945	13.08.2022	TN59CA4752	Zirconium Complex	Tuticorin	Schedule-2, class-C	Washed & Dried Silt	17.79	LAT-93

594	16.08.2022	000635	15.08.2022	TN40P0275	Jayachandran alloys pvt ltd	Perundurai	9.1	Waste slag	18.19	LAT-147
595	16.08.2022	000636	15.08.2022	TN38BW0249	Jayachandran alloys pvt ltd	Perundurai	9.1	Waste slag	18.52	LAT-147
596	16.08.2022	008057	16.08.2022	TN59CA5675	Zirconium Complex	Tuticorin	37.1	Neutralised silt	18.27	LAT-75
597	16.08.2022	007993	16.08.2022	TN11K1747	Zirconium Complex	Tuticorin	37.1	Neutralised silt	16.8	LAT-75
598	16.08.2022	008092	16.08.2022	TN67BJ6024	Zirconium Complex	Tuticorin	Schedule-2, class-C	Washed & Dried Silt	18.41	LAT-93
599	16.08.2022	007946	16.08.2022	TN59CA4752	Zirconium Complex	Tuticorin	Schedule-2, class-C	Washed & Dried Silt	17.87	LAT-93
600	17.08.2022	008058	17.08.2022	TN59CA5675	Zirconium Complex	Tuticorin	37.1	Neutralised silt	18.76	LAT-75
601	17.08.2022	007994	17.08.2022	TN11K1747	Zirconium Complex	Tuticorin	37.1	Neutralised silt	16.84	LAT-75
602	17.08.2022	008071	17.08.2022	TN59CB8706	Zirconium Complex	Tuticorin	37.1	Neutralised silt	17.93	LAT-75
603	17.08.2022	008127	17.08.2022	TN67BJ2452	Zirconium Complex	Tuticorin	Schedule-2, class-C	Washed & Dried Silt	17.67	LAT-93
604	18.08.2022	000637	17.08.2022	TN40P0275	Jayachandran alloys pvt ltd	Perundurai	9.1	Waste slag	18.32	LAT-147
605	18.08.2022	000638	17.08.2022	TN38CE0694	Jayachandran alloys pvt ltd	Perundurai	9.1	Waste slag	18.14	LAT-147
606	18.08.2022	008105	17.08.2022	TN67BJ6163	Imperial textile dyers	Erode	35.3	Sludge	17.95	LAT-10
607	18.08.2022	007915	18.08.2022	TN59CA4795	Chemplast sanmar Limited (Plant-3)	Salem	16.3	Brine sludge	18.12	DLF
608	18.08.2022	007979	18.08.2022	TN67BJ6181	Chemplast sanmar Limited (Plant-3)	Salem	16.3	Brine sludge	17.28	DLF
609	18.08.2022	008059	18.08.2022	TN59CA5675	Chemplast sanmar Limited (Plant-3)	Salem	16.3	Brine sludge	18.23	DLF
610	18.08.2022	008072	18.08.2022	TN59CB8706	Zirconium Complex	Tuticorin	Schedule-2, class-C	Washed & Dried Silt	18.02	LAT-93
611	18.08.2022	008128	18.08.2022	TN67BJ2452	Zirconium Complex	Tuticorin	Schedule-2, class-C	Washed & Dried Silt	17.74	LAT-93
612	18.08.2022	008093	18.08.2022	TN67BJ6024	Zirconium Complex	Tuticorin	37.1	Neutralised silt	17.4	LAT-75
613	18.08.2022	008139	18.08.2022	TN11K1747	Zirconium Complex	Tuticorin	37.1	Neutralised silt	17.08	LAT-75
614	19.08.2022	007916	19.08.2022	TN59CA4795	TVS Srichakra Ltd	Madurai	35.3	ETP Sludge	18.2	LAT-75
615	19.08.2022	007980	19.08.2022	TN67BJ6181	Zirconium Complex	Tuticorin	37.1	Neutralised silt	17.74	LAT-75
616	19.08.2022	008073	19.08.2022	TN59CB8706	Zirconium Complex	Tuticorin	37.1	Neutralised silt	17.8	LAT-75
617	19.08.2022	008080	19.08.2022	TN66E9714	Zirconium Complex	Tuticorin	Schedule-2, class-C	Washed & Dried Silt	16.7	LAT-93
618	19.08.2022	008060	19.08.2022	TN59CA5675	Zirconium Complex	Tuticorin	Schedule-2, class-C	Washed & Dried Silt	18.24	LAT-93
619	20.08.2022	000639	19.08.2022	TN38BW0249	Jayachandran alloys pvt ltd	Perundurai	9.1	Waste slag	18.42	LAT-147
620	20.08.2022	000640	19.08.2022	TN38CE0694	Jayachandran alloys pvt ltd	Perundurai	9.1	Waste slag	18.8	LAT-147
621	20.08.2022	008106	19.08.2022	TN67BJ6163	Chemplast sanmar Limited (Plant-3)	Salem	16.3	Brine sludge	17.02	DLF
622	20.08.2022	008140	19.08.2022	TN11K1747	Chemplast sanmar Limited (Plant-3)	Salem	16.3	Brine sludge	16.73	DLF
623	20.08.2022	008094	19.08.2022	TN67BJ6024	Chemplast sanmar Limited (Plant-3)	Salem	16.3	Brine sludge	17.33	DLF
624	20.08.2022	008061	20.08.2022	TN59CA5675	Rane Brake Lining Ltd	Trichy	35.1	Gas cleaning residue	15.24	LAT-1
625	21.08.2022	007917	20.08.2022	TN59CA4795	Rane Brake Lining Ltd.	Trichy	35.1	Gas cleaning residue	14.72	LAT-1
626	21.08.2022	008116	20.08.2022	TN23BL5836	Cabot Sanmar Ltd.	Salem	17.1	Acidic Residue Filter cake	17.1	DLF
627	22.08.2022	000641	21.08.2022	TN40P0275	Jayachandran alloys pvt ltd	Perundurai	9.1	Waste slag	18.42	LAT-147
628	22.08.2022	000642	21.08.2022	TN38BW0249	Jayachandran alloys pvt ltd	Perundurai	9.1	Waste slag	18.04	LAT-147
629	22.08.2022	008141	22.08.2022	TN11K1747	Sundram Fasteners Ltd	Virudhunagar	35.3	Collected from ATFD	20.64	LAT-75
630	22.08.2022	008117	22.08.2022	TN23BL5836	Sundram Fasteners Ltd	Virudhunagar	35.3	Chemical sludge from WWT	16.43	LAT-9
631	22.08.2022	008142	22.08.2022	TN11K1747	Sundram Fasteners Ltd	Virudhunagar	35.3	Chemical sludge from WWT	16.29	LAT-9
632	22.08.2022	008119	22.08.2022	TN23BL5836	Sundram Fasteners Ltd	Virudhunagar	35.3	Chemical sludge from WWT	17.29	LAT-9
633	23.08.2022	008081	23.08.2022	TN66E9714	Navarang Dye Works	Karur	35.3	Salt from SEP	17.515	LAT-75
634	23.08.2022	007918	23.08.2022	TN59CA4795	Navarang Dye Works	Karur	35.3	Salt from SEP	18.09	LAT-75
635	23.08.2022	008143	23.08.2022	TN11K1747	TVS Srichakra Ltd	Madurai	35.3	ETP sludge	16.32	LAT-49
636	24.08.2022	000643	23.08.2022	TN38CE0694	Jayachandran alloys pvt ltd	Perundurai	9.1	Waste slag	18.25	LAT-147
637	25.08.2022	000644	24.08.2022	TN40P0275	Jayachandran alloys pvt ltd	Perundurai	9.1	Waste slag	18.21	LAT-147
638	25.08.2022	007982	24.08.2022	TN67BJ6181	Tekno therm industries	Coimbatore	37.2	Incineration ash	9.14	DLF
639	25.08.2022	007981	24.08.2022	TN67BJ6181	Tekno therm industries	Coimbatore	35.3	ETP Sludge	3.77	LAT-11
640	25.08.2022	008062	24.08.2022	TN59CA5675	Sincere Process Mills	Erode	35.3	Chemical sludge from WWT	3.95	LAT-10
641	25.08.2022	008063	24.08.2022	TN59CA5675	Sree Omsakthi Dyeings	Erode	35.3	Chemical sludge	1.27	DLF
642	25.08.2022	008064	24.08.2022	TN59CA5675	Sun Yarn Processors	Namakkal	35.3	Chemical sludge from WWT	8.39	DLF
643	25.08.2022	008107	25.08.2022	TN67BJ6163	Sither metal industry	Tuticorin	9.1	Lead slag	20.99	DLF
644	26.08.2022	008144	25.08.2022	TN11K1747	Kovai Bio Waste Management Pvt Ltd	Coimbatore	35.3	ETP Sludge	4.19	LAT-5
645	26.08.2022	008145	25.08.2022	TN11K1747	Kovai Bio Waste Management Pvt Ltd	Coimbatore	37.2	Incineration ash	9.24	DLF
646	26.08.2022	008065	26.08.2022	TN59CA5675	Navarang Dye Works	Karur	35.3	Salt from SEP	19.13	LAT-75
647	26.08.2022	007919	26.08.2022	TN59CA4795	Navarang Dye Works	Karur	35.3	Salt from SEP	18.175	LAT-75
648	29.08.2022	008146	29.08.2022	TN11K1747	Sundram Fasteners Ltd	Virudhunagar	35.3	Salt(Collected from ATFD)	21.58	LAT-75
649	29.08.2022	007920	29.08.2022	TN59CA4795	Sundram Fasteners Ltd	Virudhunagar	35.3	Chemical sludge from WWT	19.11	LAT-9
650	29.08.2022	007921	29.08.2022	TN59CA4795	Sundram Fasteners Ltd	Virudhunagar	35.3	Chemical sludge from WWT	17.07	LAT-9
651	29.08.2022	008147	29.08.2022	TN11K1747	Sundram Fasteners Ltd	Virudhunagar	35.3	Chemical sludge from WWT	19.48	LAT-9
652	30.08.2022	008187	29.08.2022	TN59CA5675	Algavista Greentech Pvt.Ltd.	Pudukkottai	35.3	Chemical sludge from WWT	15.49	LAT-1
653	31.08.2022	008151	30.08.2022	TN59CA4752	Algavista Greentech Pvt.Ltd.	Pudukkottai	35.3	Chemical sludge from WWT	14.56	LAT-1

654	01.09.2022	008188	01.09.2022	TN59CA5675	Zirconium complex	Tuticorin	Schedule-2, class-C	Washed and dried slit	16.86	LAT-93
655	01.09.2022	007922	01.09.2022	TN59CA4795	Zirconium complex	Tuticorin	Schedule-2, class-C	Washed and dried slit	18.43	LAT-93
656	01.09.2022	008176	01.09.2022	TN67BJ6181	Zirconium complex	Tuticorin	37.1	Neutralized silt	17.55	LAT-75
657	01.09.2022	008149	01.09.2022	TN11K1747	Zirconium complex	Tuticorin	37.1	Neutralized silt	17.24	LAT-75
658	02.09.2022	000645	01.09.2022	TN38BW0249	Jayachandran Alloys Pvt. Ltd	Perundurai	9.1	Waste slag	18.73	LAT-147
659	02.09.2022	007627	02.09.2022	TN59CA4752	Zirconium complex	Tuticorin	37.1	Neutralized silt	18.86	LAT-75
660	02.09.2022	008189	02.09.2022	TN59CA5675	Zirconium complex	Tuticorin	Schedule-2, class-C	Washed and dried slit	18.18	LAT-93
661	02.09.2022	008150	02.09.2022	TN11K1747	Zirconium complex	Tuticorin	37.1	Neutralized silt	17.56	LAT-75
662	02.09.2022	008096	02.09.2022	TN67BJ6024	Zirconium complex	Tuticorin	37.1	Neutralized silt	20.56	LAT-75
663	09.09.2022	008108	08.09.2022	TN67BJ6163	Emaar Lead Company Private Limited	Coimbatore	9.1	Lead slag	18.46	DLF
664	09.09.2022	008031	08.09.2022	TN59CA4795	Emaar Lead Company Private Limited	Coimbatore	9.1	Lead slag	19.58	DLF
665	09.09.2022	008152	09.09.2022	TN59CA4752	S.Magesh babu	Virudhunagar	35.3	ETP Sludge	20.44	LAT-1
666	09.09.2022	008190	09.09.2022	TN59CA5675	S.Magesh babu	Virudhunagar	35.3	ETP Sludge	20.86	LAT-1
667	10.09.2022	008191	10.09.2022	TN59CA5675	Rajapalayam Mills Ltd.	Virudhunagar	35.3	ATFD Salt	17.09	LAT-75
668	11.09.2022	008097	10.09.2022	TN67BJ6024	K.P.R. MILL Ltd.	Perundurai	35.3	ETP waste	19.61	LAT-75
669	11.09.2022	008120	10.09.2022	TN23BL5836	K.P.R. MILL Ltd.	Perundurai	35.3	ETP waste	17.51	LAT-75
670	11.09.2022	008109	10.09.2022	TN67BJ6163	K.P.R. MILL Ltd.	Perundurai	35.3	ETP waste	19.62	LAT-75
671	11.09.2022	008032	10.09.2022	TN59CA4795	K.P.R. MILL Ltd.	Perundurai	35.3	ETP waste	18.1	LAT-75
672	11.09.2022	008153	10.09.2022	TN59CA4752	K.P.R. MILL Ltd.	Perundurai	35.3	ETP waste	18.03	LAT-75
673	11.09.2022	008212	10.09.2022	TN11-K-1747	K.P.R. MILL Ltd.	Perundurai	35.3	ETP waste	20.03	LAT-75
674	11.09.2022	008177	11.09.2022	TN67BJ6181	Medicare Enviro Systems	Thanjavur	37.2	Incineration ash	3.86	DLF
675	11.09.2022	008178	11.09.2022	TN67BJ6181	Medicare Enviro Systems	Thanjavur	35.3	ETP Sludge	9.5	LAT-1
676	12.09.2022	008213	12.09.2022	TN11K1747	K.P.R. MILL Ltd.	Perundurai	35.3	ETP waste	18.72	LAT-75
677	12.09.2022	008179	12.09.2022	TN67BJ6181	K.P.R. MILL Ltd.	Perundurai	35.3	ETP waste	21.56	LAT-75
678	12.09.2022	008131	12.09.2022	TN67BJ2452	K.P.R. MILL Ltd.	Perundurai	35.3	ETP waste	21.27	LAT-75
679	12.09.2022	008033	12.09.2022	TN59CA4795	K.P.R. MILL Ltd.	Perundurai	35.3	ETP waste	18.01	LAT-75
680	13.09.2022	008034	13.09.2022	TN59CA4795	S.Magesh babu	Virudhunagar	35.3	ETP Sludge	19.82	LAT-1
681	13.09.2022	007628	13.09.2022	TN11-K-1747	Zirconium complex	Tuticorin	37.1	Neutralized silt	16.68	LAT-75
682	13.09.2022	007629	13.09.2022	TN23BL5836	Zirconium complex	Tuticorin	37.1	Neutralized silt	19.32	LAT-75
683	13.09.2022	007630	13.09.2022	TN59CA4752	Zirconium complex	Tuticorin	Schedule-2, class-C	Washed and dried slit	17.97	LAT-93
684	13.09.2022	007631	13.09.2022	TN67BJ6181	Zirconium complex	Tuticorin	Schedule-2, class-C	Washed and dried slit	17.66	LAT-93
685	13.09.2022	008098	13.09.2022	TN67BJ6024	Rane Brake Lining Ltd	Trichy	35.1	Gas Cleaning Residue	14.36	LAT-1
686	14.09.2022	008082	13.09.2022	TN66E9714	Rane Brake Lining Ltd	Trichy	35.1	Gas Cleaning Residue	13.98	LAT-1
687	14.09.2022	008099	14.09.2022	TN67BJ6024	K.P.R. MILL Ltd.	Perundurai	35.3	ETP waste	20.82	LAT-75
688	14.09.2022	008133	14.09.2022	TN67BJ2452	K.P.R. MILL Ltd.	Perundurai	35.3	ETP waste	21.32	LAT-75
689	14.09.2022	008035	14.09.2022	TN59CA4795	K.P.R. MILL Ltd.	Perundurai	35.3	ETP waste	17.78	LAT-75
690	14.09.2022	008180	14.09.2022	TN67BJ6181	K.P.R. MILL Ltd.	Perundurai	35.3	ETP waste	21.75	LAT-75
691	14.09.2022	007633	14.09.2022	TN23BL5836	Zirconium complex	Tuticorin	37.1	Neutralized silt	17.53	LAT-75
692	14.09.2022	007634	14.09.2022	TN11K1747	Zirconium complex	Tuticorin	37.1	Neutralized silt	18.19	LAT-75
693	14.09.2022	007632	14.09.2022	TN59CA4752	Zirconium complex	Tuticorin	Schedule-2, class-C	Washed and dried slit	17.92	LAT-93
694	14.09.2022	008047	14.09.2022	TN67BJ6163	Zirconium complex	Tuticorin	Schedule-2, class-C	Washed and dried slit	17.4	LAT-93
695	15.09.2022	008049	15.09.2022	TN67BJ6181	Zirconium complex	Tuticorin	Schedule-2, class-C	Washed and dried slit	17.64	LAT-93
696	15.09.2022	008134	15.09.2022	TN67BJ2452	K.P.R. MILL Ltd.	Perundurai	35.3	ETP Waste	21.96	LAT-75
697	15.09.2022	008036	15.09.2022	TN59CA4795	K.P.R. MILL Ltd.	Perundurai	35.3	ETP waste	18.43	LAT-75
698	15.09.2022	008214	15.09.2022	TN11K1747	K.P.R. MILL Ltd.	Perundurai	35.3	ETP waste	20.5	LAT-75
699	15.09.2022	008111	15.09.2022	TN67BJ6163	K.P.R. MILL Ltd.	Perundurai	35.3	ETP waste	21.19	LAT-75
700	15.09.2022	008048	15.09.2022	TN67BJ6024	Zirconium complex	Tuticorin	Schedule-2, class-C	Washed and dried slit	16.66	LAT-93
701	15.09.2022	008050	15.09.2022	TN23BL5836	Zirconium complex	Tuticorin	37.1	Neutralized silt	17.65	LAT-75
702	15.09.2022	008051	15.09.2022	TN66E9714	Zirconium complex	Tuticorin	37.1	Neutralized silt	17.33	LAT-75
703	15.09.2022	008052	15.09.2022	TN59CA4752	Zirconium complex	Tuticorin	37.1	Neutralized silt	19.07	LAT-75
704	16.09.2022	008100	16.09.2022	TN67BJ6024	K.P.R. MILL Ltd.	Perundurai	35.3	ETP waste	21.97	LAT-75
705	16.09.2022	008112	16.09.2022	TN67BJ6163	K.P.R. MILL Ltd.	Perundurai	35.3	ETP waste	20.42	LAT-75
706	16.09.2022	008215	16.09.2022	TN11K1747	K.P.R. MILL Ltd.	Perundurai	35.3	ETP waste	20.89	LAT-75
707	16.09.2022	008075	16.09.2022	TN59CB8706	K.P.R. MILL Ltd.	Perundurai	35.3	ETP waste	18.6	LAT-75
708	16.09.2022	008154	16.09.2022	TN59CA4752	K.P.R. MILL Ltd.	Perundurai	35.3	ETP waste	18.09	LAT-75
709	16.09.2022	008121	16.09.2022	TN23BL5836	K.P.R. MILL Ltd.	Perundurai	35.3	ETP waste	20.3	LAT-75
710	17.09.2022	008216	17.09.2022	TN11K1747	K.P.R. MILL Ltd.	Perundurai	35.3	ETP waste	22.1	LAT-75
711	17.09.2022	008037	17.09.2022	TN59CA4795	K.P.R. MILL Ltd.	Perundurai	35.3	ETP waste	17.85	LAT-75
712	17.09.2022	008181	17.09.2022	TN67BJ6181	K.P.R. MILL Ltd.	Perundurai	35.3	ETP waste	20.71	LAT-75
713	17.09.2022	008135	17.09.2022	TN67BJ2452	K.P.R. MILL Ltd.	Perundurai	35.3	ETP waste	19.9	LAT-75

714	17.09.2022	008101	17.09.2022	TN67BJ6024	K.P.R. MILL Ltd.	Perundurai	35.3	ETP waste	22.25	LAT-75
715	17.09.2022	008155	17.09.2022	TN59CA4752	K.P.R. MILL Ltd.	Perundurai	35.3	ETP waste	17.99	LAT-75
716	19.09.2022	008136	19.09.2022	TN67BJ2452	K.P.R. MILL Ltd.	Perundurai	35.3	ETP waste	21.65	LAT-75
717	19.09.2022	008182	19.09.2022	TN67BJ6181	K.P.R. MILL Ltd.	Perundurai	35.3	ETP waste	22.58	LAT-75
718	19.09.2022	008038	19.09.2022	TN59CA4795	K.P.R. MILL Ltd.	Perundurai	35.3	ETP waste	17.83	LAT-75
719	19.09.2022	008156	19.09.2022	TN59CA4752	K.P.R. MILL Ltd.	Perundurai	35.3	ETP waste	17.61	LAT-75
720	19.09.2022	008217	19.09.2022	TN11K1747	K.P.R. MILL Ltd.	Perundurai	35.3	ETP waste	23.77	LAT-75
721	19.09.2022	008102	19.09.2022	TN67BJ6024	K.P.R. MILL Ltd.	Perundurai	35.3	ETP waste	20.39	LAT-75
722	20.09.2022	008113	20.09.2022	TN67BJ6163	K.P.R. MILL Ltd.	Perundurai	35.3	ETP waste	20.16	LAT-75
723	20.09.2022	008137	20.09.2022	TN67BJ2452	K.P.R. MILL Ltd.	Perundurai	35.3	ETP waste	21.23	LAT-75
724	20.09.2022	008183	20.09.2022	TN67BJ6181	K.P.R. MILL Ltd.	Perundurai	35.3	ETP waste	22.2	LAT-75
725	20.09.2022	008218	20.09.2022	TN11K1747	K.P.R. MILL Ltd.	Perundurai	35.3	ETP waste	21.96	LAT-75
726	20.09.2022	008157	20.09.2022	TN59CA4752	TVS Sri Chakra Limited	Madurai	35.3	ETP Sludge Waste	17.46	LAT-75
727	21.09.2022	008076	20.09.2022	TN59CB8706	Prime Tech Knit Print	Tiruppur	35.3	Chemical sludge from WWT	1.89	DLF
728	21.09.2022	008226	20.09.2022	TN59CB8706	B L International Clothing (P) Ltd	Tiruppur	35.3	Chemical sludge from WWT	0.45	LAT-88
729	21.09.2022	008228	20.09.2022	TN59CB8706	Maps Tek	Coimbatore	35.3	Chemical sludge from WWT	0.42	LAT-89
730	21.09.2022	008227	20.09.2022	TN59CB8706	Sri Royal Design	Tiruppur	35.3	ETP Sludge	0.07	LAT-5
731	21.09.2022	008077	20.09.2022	TN59CB8706	Sri Siva Prints	Tiruppur	35.3	Chemical sludge from WWT	0.06	LAT-134
732	21.09.2022	008078	20.09.2022	TN59CB8706	Knit Line (Unit-I)	Tiruppur	35.3	Chemical sludge from WWT	0.11	LAT-1
733	21.09.2022	008223	20.09.2022	TN59CB8706	Knit Line	Tiruppur	35.3	Chemical sludge from WWT	0.06	LAT-1
734	21.09.2022	008225	20.09.2022	TN59CB8706	Adams Screen Printers	Tiruppur	35.3	Chemical sludge from WWT	0.96	LAT-124
735	21.09.2022	008224	20.09.2022	TN59CB8706	Sri Vijayalakshmi Printing	Tiruppur	35.3	Chemical sludge from WWT	0.48	LAT-105
736	21.09.2022	008229	20.09.2022	TN59CB8706	GTN Exports Ltd (Unit-II)	Tiruppur	35.3	Chemical sludge from WWT-I	4.18	LAT-103
737	21.09.2022	008122	21.09.2022	TN23BL5836	TVS Sri Chakra Limited	Madurai	35.3	ETP Sludge Waste	16.0	LAT-75
738	21.09.2022	008039	21.09.2022	TN59CA4795	K.P.R. MILL Ltd.	Perundurai	35.3	ETP waste	18.84	LAT-75
739	21.09.2022	008219	21.09.2022	TN11K1747	K.P.R. MILL Ltd.	Perundurai	35.3	ETP waste	24.05	LAT-75
740	22.09.2022	008220	22.09.2022	TN11K1747	TVS Sri Chakra Limited	Madurai	35.3	ETP Sludge Waste	18.66	LAT-75
741	22.09.2022	008259	21.09.2022	TN67BJ6024	Tekno Therm Industries	Coimbatore	37.2	Incineration ash	12.17	DLF
742	22.09.2022	008260	21.09.2022	TN67BJ6024	Tekno Therm Industries	Coimbatore	35.3	ETP Sludge	1.47	LAT-11
743	22.09.2022	008114	22.09.2022	TN67BJ6163	K.P.R. MILL Ltd.	Perundurai	35.3	ETP waste	22.64	LAT-75
744	23.09.2022	008184	23.09.2022	TN67BJ6181	TVS Sri Chakra Limited	Madurai	35.3	ETP Sludge Waste	16.76	LAT-49
745	24.09.2022	008138	23.09.2022	TN67BJ2452	Imperrial Textile Dyers	Erode	35.3	Chemical sludge	16.68	LAT-10
746	24.09.2022	008221	23.09.2022	TN11K1747	Imperrial Textile Dyers	Erode	35.3	Chemical sludge	19	LAT-10
747	24.09.2022	008235	24.09.2022	TN67BJ6163	Rane Brake Lining Ltd	Trichy	35.1	Gas Cleaning Residue	15.03	LAT-1
748	24.09.2022	008261	24.09.2022	TN67BJ6024	Rane Brake Lining Ltd	Trichy	35.1	Gas Cleaning Residue	15.54	LAT-1
749	26.09.2022	008158	24.09.2022	TN59CA4752	Rane Brake Lining Ltd	Trichy	35.1	Gas Cleaning Residue	13.27	LAT-1
750	26.09.2022	008273	24.09.2022	TN59CB8706	Anderson Greenwood Crosby Sanmar Ltd	Pudukkottai	5.2	Lapping Sludge	0.5	DLF
751	26.09.2022	008272	24.09.2022	TN59CB8706	Anderson Greenwood Crosby Sanmar Ltd	Pudukkottai	35.3	Chemical Sludge	1	DLF
752	26.09.2022	008274	24.09.2022	TN59CB8706	Sanmar Matrix Metals Ltd(M/S-1)	Pudukkottai	35.3	Chemical Sludge	2	LAT-171
753	26.09.2022	008276	24.09.2022	TN59CB8706	Xomox Sanmar Ltd	Pudukkottai	35.3	Chemical Sludge	0.7	LAT-10
754	26.09.2022	008275	24.09.2022	TN59CB8706	Sanmar Matrix Metals Ltd(M/S-2)	Pudukkottai	35.3	Chemical Sludge	0.3	DLF
755	26.09.2022	008271	24.09.2022	TN59CB8706	Sanmar Matrix Metals Ltd(Foundry)	Pudukkottai	7.5	Sludge From Scrubber	0.6	LAT-9
756	26.09.2022	008277	24.09.2022	TN59CB8706	Sanmar Matrix Metals Ltd(Foundry)	Pudukkottai	35.3	Chemical Sludge	2.2	LAT-9
757	29.09.2022	008192	28.09.2022	TN59CA5675	Shri Kara Engineering Private Limited	Coimbatore	35.3	Chemical sludge from WWT	21.6	LAT-103
758	29.09.2022	008185	29.09.2022	TN67BJ6181	Sither Metal industry	Tuticorin	9.1	Lead slag	25	DLF
759	29.09.2022	008222	29.09.2022	TN11K1747	Sundram Fasteners Ltd	Virudhunagar	35.3	Chemical sludge from WWT	18.54	LAT-9
760	30.09.2022	008283	29.09.2022	TN11K1747	Sundram Fasteners Ltd	Virudhunagar	35.3	Salt	20.34	LAT-75
761	30.09.2022	008193	30.09.2022	TN59CA5675	Hindustan Unilever Limited	Kodaikanal	35.3	ETP Sludge	8.36	LAT-155
762	01.10.2022	008123	01.10.2022	TN23BL5836	Chemplast Sanmar Limited (Plant-III)	Salem	16.3	Brine Sludge	17.67	DLF
763	01.10.2022	008236	01.10.2022	TN67BJ6163	Chemplast Sanmar Limited (Plant-III)	Salem	16.3	Brine Sludge	17.3	DLF
764	01.10.2022	008247	01.10.2022	TN67BJ2452	Chemplast Sanmar Limited (Plant-III)	Salem	16.3	Brine Sludge	17.52	DLF
765	01.10.2022	008262	01.10.2022	TN67BJ6024	Chemplast Sanmar Limited (Plant-III)	Salem	16.3	Brine Sludge	17.44	DLF
766	01.10.2022	008284	01.10.2022	TN11K1747	Chemplast Sanmar Limited (Plant-III)	Salem	16.3	Brine Sludge	16.6	DLF
767	01.10.2022	008194	01.10.2022	TN59CA5675	Premier Textiles Dyers	Erode	35.3	ETP Sludge	15.09	LAT-1
768	07.10.2022	008186	06.10.2022	TN67BJ6181	Chemplast Sanmar Limited (Plant-III)	Salem	16.3	Brine Sludge	17.41	DLF
769	07.10.2022	008195	06.10.2022	TN59CA5675	Chemplast Sanmar Limited (Plant-III)	Salem	16.3	Brine Sludge	17.71	DLF
770	07.10.2022	008285	06.10.2022	TN11K1747	Chemplast Sanmar Limited (Plant-III)	Salem	16.3	Brine Sludge	16.63	DLF
771	07.10.2022	008159	06.10.2022	TN59CA4752	Chemplast Sanmar Limited (Plant-III)	Salem	16.3	Brine Sludge	17.49	DLF
772	10.10.2022	008196	08.10.2022	TN59CA5675	Enceee Aromatics Limited	Coimbatore	35.3	Salt	18.76	LAT-75
773	11.10.2022	000020	10.10.2022	TN38BW0249	Jayachandran Industries Private Limited	Coimbatore	35.3	ETP Sludge	13.61	LAT-88

774	11.10.2022	008279	11.10.2022	TN59CB8706	Atc Tires Pvt Ltd	Tirunelveli	35.3	Chemical sludge from WTP	3.24	LAT-10
775	11.10.2022	008278	11.10.2022	TN59CB8706	Atc Tires Pvt Ltd	Tirunelveli	6.2	Zinc fines	3.24	LAT-103
776	13.10.2022	008263	12.10.2022	TN67BJ6024	Trichy Metals and Alloys	Trichy	9.1	Lead slag	17.87	LAT-9
777	13.10.2022	008280	13.10.2022	TN59CB8706	Sither Metal Industry	Tuticorin	9.1	Lead slag	18.35	DLF
778	13.10.2022	008248	12.10.2022	TN67BJ2452	Golden Textile Dyers	Erode	35.3	ETP Sludge	17.455	LAT-49
779	13.10.2022	008040	13.10.2022	TN59CA4795	Rane Brake Lining Ltd	Trichy	12.5	Phosphate Sludge	3	DLF
780	13.10.2022	008041	13.10.2022	TN59CA4795	Rane Brake Lining Ltd	Trichy	35.1	Gas Cleaning Residue	11.31	LAT-1
781	13.10.2022	008287	13.10.2022	TN11K1747	Rane Brake Lining Ltd	Trichy	35.1	Gas Cleaning Residue	13.5	LAT-1
782	14.10.2022	008085	13.10.2022	TN66E9714	Rane Brake Lining Ltd	Trichy	35.1	Gas Cleaning Residue	14.61	LAT-1
783	14.10.2022	008307	13.10.2022	TN67BJ6181	Lakshmi Machine Works Ltd Unit-1	Coimbatore	12.5	Phosphate Sludge	1.01	LAT-11
784	14.10.2022	008308	13.10.2022	TN67BJ6181	Lakshmi Machine Works Ltd Unit-1	Coimbatore	35.3	ETP Sludge	4.54	LAT-124
785	14.10.2022	008160	13.10.2022	TN59CA4752	Chemplast Sanmar Limited (Plant-III)	Salem	16.3	Brine Sludge	17.89	DLF
786	14.10.2022	008197	13.10.2022	TN59CA5675	Chemplast Sanmar Limited (Plant-III)	Salem	16.3	Brine Sludge	18.01	DLF
787	14.10.2022	008237	13.10.2022	TN67BJ6163	Chemplast Sanmar Limited (Plant-III)	Salem	16.3	Brine Sludge	17.19	DLF
788	14.10.2022	008042	14.10.2022	TN59CA4795	Sundram Fasteners Ltd	Virudhunagar	35.3	Salt	19.99	LAT-75
789	14.10.2022	008288	14.10.2022	TN11K1747	Sundram Fasteners Ltd	Virudhunagar	35.3	ETP Sludge	19.12	LAT-9
790	14.10.2022	008264	14.10.2022	TN67BJ6024	Rane Engine valve Ltd Plant-5	Pudukkottai	5.2	Waste Containg Sludge	21.25	DLF
791	14.10.2022	008289	14.10.2022	TN11K1747	Sundram Fasteners Ltd	Virudhunagar	35.3	ETP Sludge	18.12	LAT-9
792	14.10.2022	008230	14.10.2022	TN59CA4795	Sundram Fasteners Ltd	Virudhunagar	35.3	Salt	18.91	LAT-75
793	15.10.2022	000646	14.10.2022	TN38BW0249	Jayachandran alloys pvt ltd	Perundurai	9.1	Waste slag	18.59	LAT-147
794	17.10.2022	000647	16.10.2022	TN40PO275	Jayachandran alloys pvt ltd	Perundurai	9.1	Waste slag	18.34	LAT-147
795	17.10.2022	008311	17.10.2022	TN67BJ6181	Sither Metal Industry	Tuticorin	9.1	Lead slag	24.88	DLF
796	18.10.2022	000648	17.10.2022	TN40PO275	Jayachandran alloys pvt ltd	Perundurai	9.1	Waste slag	18.08	LAT-147
797	19.10.2022	000649	19.10.2022	TN38BW0249	Jayachandran alloys pvt ltd	Perundurai	9.1	Waste slag	18.12	LAT-147
798	19.10.2022	008198	19.10.2022	TN59CA5675	Rane Brake Lining Ltd	Trichy	35.1	Gas Cleaning Residue	12.76	LAT-1
799	20.10.2022	000650	19.10.2022	TN40PO275	Jayachandran alloys pvt ltd	Perundurai	9.1	Waste slag	18.64	LAT-147
800	20.10.2022	008231	19.10.2022	TN59CA4795	Rane Brake Lining Ltd	Trichy	35.1	Gas Cleaning Residue	14.15	LAT-1
801	20.10.2022	008291	20.10.2022	TN11K1747	K.P.R. Mills Limited	Perundurai	35.3	ETP Waste	23.16	LAT-75
802	20.10.2022	008265	20.10.2022	TN67BJ6024	K.P.R. Mills Limited	Perundurai	35.3	ETP Waste	19.96	LAT-75
803	20.10.2022	008319	20.10.2022	TN59CA5675	K.P.R. Mills Limited	Perundurai	35.3	ETP Waste	17.64	LAT-75
804	20.10.2022	008355	20.10.2022	TN94 8940	Jothi Dyeing Factory	Ramanathapuram	35.3	ETP Sludge	0.028	DLF
805	20.10.2022	008356	20.10.2022	TN94 8940	S.R.Balaswamy iyer dyeing factory	Ramanathapuram	35.3	ETP Sludge	0.028	DLF
806	20.10.2022	008250	20.10.2022	TN67BJ2452	K.P.R. Mills Limited	Perundurai	35.3	ETP Waste	23.24	LAT-75
807	21.10.2022	008313	21.10.2022	TN67BJ6181	K.P.R. Mills Limited	Perundurai	35.3	ETP Waste	19.76	LAT-75
808	21.10.2022	008320	21.10.2022	TN59CA5675	K.P.R. Mills Limited	Perundurai	35.3	ETP Waste	18.67	LAT-75
809	21.10.2022	008232	21.10.2022	TN59CA4795	K.P.R. Mills Limited	Perundurai	35.3	ETP Waste	18.07	LAT-75
810	21.10.2022	008251	21.10.2022	TN67BJ2452	K.P.R. Mills Limited	Perundurai	35.3	ETP Waste	19.66	LAT-75
811	22.10.2022	000651	21.10.2022	TN38BW0249	Jayachandran alloys pvt ltd	Perundurai	9.1	Waste slag	17.96	LAT-147
812	22.10.2022	008293	21.10.2022	TN11K1747	Lakshmi Machine Works Ltd Unit-2	Coimbatore	35.3	Chemical sludge from WWT	2.3	LAT-1
813	22.10.2022	008292	21.10.2022	TN11K1747	Lakshmi Machine Works Ltd Unit-2	Coimbatore	12.5	Phosphate Sludge	0.96	LAT-9
814	28.10.2022	008294	28.10.2022	TN11K1747	Sundram Fasteners Ltd	Virudhunagar	35.3	Chemical Sludge from WWT	18.13	LAT-9
815	28.10.2022	008367	28.10.2022	TN11K1747	Sundram Fasteners Ltd	Virudhunagar	35.3	Chemical Sludge from WWT	18.05	LAT-9
816	28.10.2022	008282	28.10.2022	TN59CB8706	Sundram Fasteners Ltd	Virudhunagar	35.3	Chemical Sludge from WWT	16.68	LAT-9
817	28.10.2022	008252	27.10.2022	TN67BJ2452	Chemplast Sanmar Limited (Plant-III)	Salem	16.3	Brine Sludge	17.65	DLF
818	28.10.2022	008321	27.10.2022	TN59CA5675	Chemplast Sanmar Limited (Plant-III)	Salem	16.3	Brine Sludge	18.08	DLF
819	28.10.2022	008314	27.10.2022	TN67BJ6181	Chemplast Sanmar Limited (Plant-III)	Salem	16.3	Brine Sludge	17.32	DLF
820	28.10.2022	008295	28.10.2022	TN59CB8706	Sundram Fasteners Ltd	Virudhunagar	35.3	Chemical Sludge from WWT	16.88	LAT-9
821	29.10.2022	000652	28.10.2022	TN40PO275	Jayachandran alloys pvt ltd	Perundurai	9.1	Waste slag	18.98	LAT-147
822	29.10.2022	008253	29.10.2022	TN67BJ2452	K.P.R. Mills Limited	Perundurai	35.3	ETP Waste	19.76	LAT-75
823	29.10.2022	008368	29.10.2022	TN11K1747	K.P.R. Mills Limited	Perundurai	35.3	ETP Waste	23.17	LAT-75
824	29.10.2022	008315	29.10.2022	TN67BJ6181	K.P.R. Mills Limited	Perundurai	35.3	ETP Waste	21.73	LAT-75
825	29.10.2022	008233	29.10.2022	TN59CA4795	K.P.R. Mills Limited	Perundurai	35.3	ETP Waste	18.18	LAT-75
826	29.10.2022	008322	29.10.2022	TN59CA5675	K.P.R. Mills Limited	Perundurai	35.3	ETP Waste	19.43	LAT-75
827	29.10.2022	008343	29.10.2022	TN59CA4752	K.P.R. Mills Limited	Perundurai	35.3	ETP Waste	18.42	LAT-75
828	30.10.2022	008268	29.10.2022	TN67BJ6024	Chemplast Sanmar Limited (Plant-III)	Salem	16.3	Brine Sludge	17.26	DLF
829	30.10.2022	008296	29.10.2022	TN59CB8706	Chemplast Sanmar Limited (Plant-III)	Salem	16.3	Brine Sludge	17.85	DLF
830	30.10.2022	008126	29.10.2022	TN23BL5836	Chemplast Sanmar Limited (Plant-III)	Salem	16.3	Chemical Sludge	17.59	DLF
831	31.10.2022	000653	30.10.2022	TN38BW0249	Jayachandran alloys pvt ltd	Perundurai	9.1	Waste slag	18.45	LAT-147
832	31.10.2022	008316	30.10.2022	TN67BJ6181	Chemplast Sanmar Ltd(Plant-II)	Salem	35.3	Chemical sludge from WWT	17.56	DLF
833	31.10.2022	008369	30.10.2022	TN11K1747	Chemplast Sanmar Ltd(Plant-II)	Salem	35.3	Chemical sludge from WWT	16.68	DLF

834	31.10.2022	008357	31.10.2022	TN23BL5836	Sither Metal Industry	Tuticorin	9.1	Lead slag	18.08	DLF
835	31.10.2022	008234	31.10.2022	TN59CA4795	Sundram Fasteners Ltd	Virudhunagar	35.3	Salt	21.44	LAT-75
836	31.10.2022	008344	31.10.2022	TN59CA4752	Trichy Metals and Alloys	Trichy	9.1	Lead slag	17.64	LAT-9
837	31.10.2022	008323	31.10.2022	TN59CA5675	Chemplast Sanmar Limited (Plant-III)	Salem	16.3	Brine Sludge	17.92	DLF
838	31.10.2022	008239	31.10.2022	TN67BJ6163	Chemplast Sanmar Limited (Plant-III)	Salem	16.3	Brine Sludge	17.34	DLF
839	31.10.2022	008269	31.10.2022	TN67BJ6024	J.K.Fenner(India)Ltd	Madurai	35.3	ETP Chemical sludge	1.495	LAT-9
840	31.10.2022	008270	31.10.2022	TN67BJ6024	Sirius Zip Fasteners Pvt Ltd	Sivagangai	6.2	Zinc dust	0.095	LAT-103
841	31.10.2022	008331	31.10.2022	TN59CA4795	Sundram Fasteners Ltd	Virudhunagar	35.3	Chemical sludge from WWT	18.61	LAT-9
842	02.11.2022	000654	01.11.2022	TN40P0275	Jayachandran alloys pvt ltd	Perundurai	9.1	Waste slag	18.47	LAT-147
843	03.11.2022	000655	02.11.2022	TN38BW0249	Jayachandran alloys pvt ltd	Perundurai	9.1	Waste slag	18.62	LAT-147
844	03.11.2022	008317	02.11.2022	TN67BJ6181	Tamilnadu Newsprint and Papers Limited	Trichy	Schedule-2, Class-2-5	Used Glass wool	3.79	DLF
845	05.11.2022	008370	05.11.2022	TN11K1747	Sither Metal Industry	Tuticorin	9.1	Lead slag	22.88	DLF
846	05.11.2022	008240	05.11.2022	TN67BJ6163	Ramesh Flowers Pvt Ltd	Tuticorin	35.3	ETP chemical sludge	12.58	LAT-24
847	05.11.2022	008332	05.11.2022	TN59CA4795	Ramesh Flowers Pvt Ltd	Tuticorin	35.3	ETP chemical sludge	12.94	LAT-24
848	05.11.2022	008324	05.11.2022	TN59CA5675	Hindustan Unilever Ltd	Kodaikanal	35.3	ETP sludge	8.54	LAT-155
849	07.11.2022	000656	06.11.2022	TN40P0275	Jayachandran alloys pvt ltd	Perundurai	9.1	Waste slag	18.31	LAT-147
850	07.11.2022	008318	07.11.2022	TN67BJ6181	Sither Metal Industry	Tuticorin	9.1	Lead slag	23	DLF
851	07.11.2022	008371	07.11.2022	TN11K1747	Tamilnadu Newsprint and Papers Limited	Trichy	Schedule-2, Class-2-5	Used Glass wool	6.64	DLF
852	07.11.2022	008345	07.11.2022	TN59CA4752	Ramesh Flowers Pvt Ltd	Tuticorin	35.3	ETP chemical sludge	12.86	LAT-24
853	08.11.2022	000657	07.11.2022	TN38BW0249	Jayachandran alloys pvt ltd	Perundurai	9.1	Waste slag	18.12	LAT-147
854	08.11.2022	008379	07.11.2022	TN67BJ6024	Tekno Therm Industries	Coimbatore	35.3	ETP sludge	2.81	LAT-11
855	08.11.2022	008380	07.11.2022	TN67BJ6024	Tekno Therm Industries	Coimbatore	37.2	Incineration ash	11.73	DLF
856	08.11.2022	008325	07.11.2022	TN59CA5675	Ramesh Flowers Pvt Ltd	Tuticorin	35.3	ETP chemical sludge	14.6	LAT-24
857	09.11.2022	000658	08.11.2022	TN40P0275	Jayachandran alloys pvt ltd	Perundurai	9.1	Waste slag	18.5	LAT-147
858	09.11.2022	008241	08.11.2022	TN67BJ6163	Tamilnadu Newsprint and Papers Limited	Trichy	Schedule-2, Class-2-5	Used Glass wool	5.87	DLF
859	09.11.2022	008334	08.11.2022	TN59CA4795	AGPL Rotary Printing	Tirupur	35.3	ETP chemical sludge	16.76	LAT-134
860	09.11.2022	008333	08.11.2022	TN59CA4795	R.V.Screen Printers	Tirupur	35.3	Chemical sludge from WWT	0.25	LAT-124
861	09.11.2022	008372	09.11.2022	TN11K1747	Trichy Metals and Alloys	Trichy	9.1	Lead slag	17.93	LAT-9
862	09.11.2022	008346	09.11.2022	TN59CA4752	Sicgilsol Gases Private Limited	Thanjavur	35.3	Chemical sludge from WWT	0.7	LAT-192
863	09.11.2022	008391	09.11.2022	TN67BJ6181	Metstar Industries Pvt Ltd	Perundurai	9.1	Lead bearing residues	17.59	LAT-147
864	11.11.2022	008242	10.11.2022	TN67BJ6163	Cabot Sanmar Limited (Plant-V)	Salem	17.1	Process acidic residue-Filter cake	16.21	DLF
865	11.11.2022	008327	10.11.2022	TN59CA5675	Cabot Sanmar Limited (Plant-V)	Salem	17.1	Process acidic residue-Filter cake	16.01	DLF
866	12.11.2022	008335	11.11.2022	TN59CA4795	Chemplast Sanmar Limited (Plant-III)	Salem	16.3	Brine Sludge	18.05	DLF
867	12.11.2022	008373	11.11.2022	TN11K1747	Chemplast Sanmar Limited (Plant-III)	Salem	16.3	Brine Sludge	16.57	DLF
868	12.11.2022	008392	11.11.2022	TN67BJ6181	Chemplast Sanmar Limited (Plant-III)	Salem	16.3	Brine Sludge	17.22	DLF
869	12.11.2022	008381	11.11.2022	TN67BJ6024	Sun Yarn Processors	Namakkal	35.3	Chemical sludge from WWT	11.71	DLF
870	12.11.2022	008382	11.11.2022	TN67BJ6024	Visak Texx Mills	Erode	35.3	ETP sludge	3.43	DLF
871	12.11.2022	008083	12.11.2022	TN66E9714	Rane Brake Lining Ltd	Trichy	35.1	Gas cleaning residue	15.66	LAT-1
872	14.11.2022	008328	12.11.2022	TN59CA5675	Rane Brake Lining Ltd	Trichy	35.1	Gas cleaning residue	15.05	LAT-1
873	14.11.2022	008374	14.11.2022	TN11K1747	Ramesh Flowers Pvt Ltd	Tuticorin	35.3	ETP chemical sludge	13.22	DLF
874	16.11.2022	000659	16.11.2022	TN40P0275	Jayachandran alloys pvt ltd	Perundurai	9.1	Waste slag	18.48	LAT-147
875	18.11.2022	008254	18.11.2022	TN67BJ2452	Chemplast Sanmar Limited (Plant-III)	Salem	16.3	Brine Sludge	17.48	DLF
876	18.11.2022	008375	18.11.2022	TN11K1747	Chemplast Sanmar Limited (Plant-III)	Salem	16.3	Brine Sludge	16.51	DLF
877	18.11.2022	008393	18.11.2022	TN67BJ6181	Chemplast Sanmar Limited (Plant-III)	Salem	16.3	Brine Sludge	17.48	DLF
878	19.11.2022	008297	19.11.2022	TN59CB8706	K.P.R. Mills Limited	Perundurai	35.3	ETP Waste	18.11	LAT-75
879	19.11.2022	008330	19.11.2022	TN59CA5675	K.P.R. Mills Limited	Perundurai	35.3	ETP Waste	18.27	LAT-75
880	19.11.2022	008349	19.11.2022	TN59CA4752	K.P.R. Mills Limited	Perundurai	35.3	ETP Waste	18.01	LAT-75
881	19.11.2022	008376	19.11.2022	TN11K1747	K.P.R. Mills Limited	Perundurai	35.3	ETP Waste	24.05	LAT-75
882	19.11.2022	008384	19.11.2022	TN67BJ6024	K.P.R. Mills Limited	Perundurai	35.3	ETP Waste	23.24	LAT-75
883	19.11.2022	008394	19.11.2022	TN67BJ6181	K.P.R. Mills Limited	Perundurai	35.3	ETP Waste	24.02	LAT-75
884	19.11.2022	008255	19.11.2022	TN67BJ2452	Rajapalayam Mills Limited	Virudhunagar	35.3	Salt	18.55	LAT-75
885	20.11.2022	008298	20.11.2022	TN59CB8706	K.P.R. Mills Limited	Perundurai	35.3	ETP Waste	18.08	LAT-75
886	20.11.2022	008403	20.11.2022	TN59CA5675	K.P.R. Mills Limited	Perundurai	35.3	ETP Waste	18.45	LAT-75
887	20.11.2022	008385	20.11.2022	TN67BJ6024	K.P.R. Mills Limited	Perundurai	35.3	ETP Waste	21.89	LAT-75
888	20.11.2022	008395	20.11.2022	TN67BJ6181	K.P.R. Mills Limited	Perundurai	35.3	ETP Waste	23.78	LAT-75
889	20.11.2022	008243	20.11.2022	TN67BJ6163	K.P.R. Mills Limited	Perundurai	35.3	ETP Waste	22.76	LAT-75
890	21.11.2022	008350	21.11.2022	TN59CA4752	Sundram Fasteners Ltd	Virudhunagar	35.3	Salt from ATFD	19.01	LAT-75
891	21.11.2022	008386	21.11.2022	TN67BJ6024	Sither Metal Industry	Tuticorin	9.1	Lead slag	22.39	DLF
892	21.11.2022	008351	21.11.2022	TN59CA4752	Sundram Fasteners Ltd	Virudhunagar	35.3	Chemical sludge from WWT	17.86	LAT-9
893	23.11.2022	008387	23.11.2022	TN67BJ6024	Chemplast Sanmar Limited (Plant-III)	Salem	16.3	Brine Sludge	17.24	DLF

894	23.11.2022	008244	23.11.2022	TN67BJ6163	Chemplast Sanmar Limited (Plant-III)	Salem	16.3	Brine Sludge	17.34	DLF
895	23.11.2022	008404	23.11.2022	TN59CA5675	Chemplast Sanmar Limited (Plant-III)	Salem	16.3	Brine Sludge	17.51	DLF
896	23.11.2022	008377	23.11.2022	TN11K1747	Chemplast Sanmar Limited (Plant-III)	Salem	16.3	Brine Sludge	16.32	DLF
897	24.11.2022	008388	24.11.2022	TN67BJ6024	Sither Metal Industry	Tuticorin	9.1	Lead slag	22.5	DLF
898	24.11.2022	008300	24.11.2022	TN59CB8706	Sibaflor Natural Decorations Pvt Ltd	Tuticorin	35.3	Chemical sludge from WWT	13.94	LAT-10
899	25.11.2022	008407	25.11.2022	TN59CA5675	Sundram Fasteners Ltd	Virudhunagar	35.3	Chemical sludge from WWT	17.81	LAT-9
900	25.11.2022	008406	25.11.2022	TN59CA5675	Sundram Fasteners Ltd	Virudhunagar	35.3	Chemical sludge from WWT	18.71	LAT-9
901	25.11.2022	008302	25.11.2022	TN59CB8706	Imperiall Textile Dyers	Erode	35.3	Sludge	17.34	LAT-10
902	25.11.2022	008427	25.11.2022	TN45AS9097	Hi-Tech Arai Pvt Ltd(Kappalur)	Madurai	35.3	Chemical sludge from WWT	3	LAT-10
903	25.11.2022	008428	25.11.2022	TN45AS9097	Hi-Tech Arai Pvt Ltd(Kappalur)	Madurai	12.5	Phosphate sludge	2.27	LAT-157
904	25.11.2022	008429	25.11.2022	TN45AS9097	Hi-Tech Arai Pvt Ltd(Pudur)	Madurai	35.3	Chemical sludge from WWT	3.336	LAT-161
905	25.11.2022	008301	25.11.2022	TN45AS9097	Hi-Tech Arai Pvt Ltd(Pudur)	Madurai	12.5	Phosphate sludge	1.094	LAT-161
906	26.11.2022	008399	26.11.2022	TN67BJ6181	Emaar Lead Company	Coimbatore	9.1	Waste slag	17.78	DLF
907	26.11.2022	008303	26.11.2022	TN59CB8706	Emaar Lead Company	Coimbatore	9.1	Waste slag	18.1	DLF
908	28.11.2022	000660	27.11.2022	TN40PO275	Jayachandran alloys pvt ltd	Perundurai	9.1	Waste slag	18.61	LAT-147
909	28.11.2022	008304	28.11.2022	TN59CB8706	Laurel Apparels (Embroidery & Printing Division)	Tirupur	35.3	ETP Sludge	7.85	LAT-124
910	30.11.2022	000661	29.11.2022	TN40PO275	Jayachandran alloys pvt ltd	Perundurai	9.1	Waste slag	18.7	LAT-147
911	30.11.2022	008452	29.11.2022	TN45AS9097	Knit Care	Tirupur	35.3	Chemical sludge from WWT	0.87	LAT-1
912	30.11.2022	008453	29.11.2022	TN45AS9097	Kandhan Prints	Tirupur	35.3	Chemical sludge from WWT	0.2	LAT-11
913	30.11.2022	008454	29.11.2022	TN45AS9097	Akruthi Apparel	Tirupur	35.3	Chemical sludge from WWT	0.76	LAT-10
914	30.11.2022	008455	29.11.2022	TN45AS9097	Greenway Clothings INDIA Pvt Ltd (Unit-I)	Tirupur	35.3	Chemical sludge from WWT	1.07	LAT-124
915	30.11.2022	008456	29.11.2022	TN45AS9097	Saran Print Paark	Tirupur	35.3	Chemical sludge from WWT	0.89	DLF
916	30.11.2022	008457	29.11.2022	TN45AS9097	Shree VPA Printing	Tirupur	35.3	Chemical sludge from WWT	0.52	LAT-1
917	30.11.2022	008458	29.11.2022	TN45AS9097	Spectra Desizns	Tirupur	35.3	Chemical sludge from WWT	0.48	LAT-200
918	30.11.2022	008459	29.11.2022	TN45AS9097	Afsar Screen Printing	Tirupur	35.3	Chemical sludge from WWT	0.63	DLF
919	30.11.2022	008460	29.11.2022	TN45AS9097	Kongu Printers	Tirupur	35.3	Chemical sludge from WWT	0.41	LAT-134
920	30.11.2022	008461	29.11.2022	TN45AS9097	Jayakumaran Exports Unit-I	Tirupur	35.3	Chemical sludge from WWT	0.11	LAT-1
921	30.11.2022	008462	29.11.2022	TN45AS9097	Power Win Yaarn Dyeing	Tirupur	35.3	Chemical sludge from WWT	2.065	DLF
922	30.11.2022	008511	30.11.2022	TN59BR1569	Quantum Drugs & Chemicals	Madurai	35.3	ETP Sludge	0.638	DLF
923	30.11.2022	008401	30.11.2022	TN67BJ6181	Tamilnadu Newsprint and Papers Limited	Karur	Schedule-2, Class-2-53	Used Glass wool	6.39	DLF
924	01.12.2022	008402	01.12.2022	TN67BJ6181	Sither Metal Industry	Tuticorin	9.1	Lead slag	24.1	DLF
925	01.12.2022	008257	01.12.2022	TN67BJ2452	Sither Metal Industry	Tuticorin	9.1	Lead slag	24.26	DLF
926	03.12.2022	000021	02.12.2022	TN38BW0249	Jayachandran Industries Private Limited	Coimbatore	35.3	ETP Sludge	15.07	LAT-88
927	03.12.2022	000662	02.12.2022	TN40PO275	Jayachandran Alloys Pvt Ltd	Perundurai	9.1	Waste Slag	18.55	LAT-147
928	03.12.2022	008412	02.12.2022	TN59CA5675	Chemplast Sanmar Limited (Plant-III)	Salem	16.3	Brine Sludge	18.24	DLF
929	03.12.2022	008306	02.12.2022	TN59CB8706	Chemplast Sanmar Limited (Plant-III)	Salem	16.3	Brine Sludge	18.03	DLF
930	05.12.2022	000663	04.12.2022	TN38BW0249	Jayachandran Alloys Pvt Ltd	Perundurai	9.1	Waste Slag	18.78	LAT-147
931	06.12.2022	000664	05.12.2022	TN40PO275	Jayachandran Alloys Pvt Ltd	Perundurai	9.1	Waste Slag	18.62	LAT-147
932	07.12.2022	008420	07.12.2022	TN11K1747	Varun Beverages Ltd	Tieunelveli	35.3	Chemical Sludge	13.4	DLF
933	08.12.2022	000665	06.12.2022	TN38BW0249	Jayachandran Alloys Pvt Ltd	Perundurai	9.1	Waste Slag	18.63	LAT-147
934	08.12.2022	008499	08.12.2022	TN59CB8706	Sither Metal Industry	Tuticorin	9.1	Lead slag	17.81	DLF
935	08.12.2022	008089	08.12.2022	TN66E9714	Rane Brake Lining Ltd	Trichy	35.1	Gas cleaning residue	14.45	LAT-1
936	08.12.2022	008440	08.12.2022	TN67BJ6024	Rane Brake Lining Ltd	Trichy	35.1	Gas cleaning residue	15.63	LAT-1
937	09.12.2022	008413	08.12.2022	TN59CA5675	Rane Brake Lining Ltd	Trichy	35.1	Gas cleaning residue	12.74	LAT-1
938	09.12.2022	008414	08.12.2022	TN59CA5675	Rane Brake Lining Ltd	Trichy	12.5	Phosphate sludge	2	DLF
939	10.12.2022	000666	09.12.2022	TN40PO275	Jayachandran Alloys Pvt Ltd	Perundurai	9.1	Waste Slag	18.53	LAT-147
940	13.12.2022	008547	13.12.2022	TN59CA5675	Sundram Fasteners Ltd	Virudhunagar	35.3	Chemical Sludge from WWT	17.73	LAT-9
941	13.12.2022	008548	13.12.2022	TN59CA5675	Sundram Fasteners Ltd	Virudhunagar	35.3	Chemical Sludge from WWT	18.7	LAT-9
942	15.12.2022	000667	14.12.2022	TN38BW0249	Jayachandran Alloys Pvt Ltd	Perundurai	9.1	Waste Slag	18.66	LAT-147
943	15.12.2022	008441	15.12.2022	TN67BJ6024	Sither Metal Industry	Tuticorin	9.1	Lead slag	22.55	DLF
944	15.12.2022	008174	15.12.2022	TN37BR9477	Resustainability Healthcare Solutions Ltd	Virudhunagar	37.2	Incineration Ash	9.17	DLF
945	16.12.2022	000668	15.12.2022	TN40PO275	Jayachandran Alloys Pvt Ltd	Perundurai	9.1	Waste Slag	18.29	LAT-147
946	16.12.2022	008258	16.12.2022	TN67BJ2452	K.P.R. Mills Limited	Perundurai	35.3	ETP Waste	21.89	LAT-75
947	16.12.2022	008513	16.12.2022	TN67BJ6181	K.P.R. Mills Limited	Perundurai	35.3	ETP Waste	22.11	LAT-75
948	16.12.2022	008442	16.12.2022	TN67BJ6024	K.P.R. Mills Limited	Perundurai	35.3	ETP Waste	21.24	LAT-75
949	16.12.2022	008422	16.12.2022	TN11K1747	K.P.R. Mills Limited	Perundurai	35.3	ETP Waste	23	LAT-75
950	16.12.2022	008500	16.12.2022	TN59CB8706	K.P.R. Mills Limited	Perundurai	35.3	ETP Waste	18.19	LAT-75
951	16.12.2022	008360	16.12.2022	TN23BL5836	Chemplast Sanmar Limited (Plant-III)	Salem	16.3	Brine Sludge	17.55	DLF
952	16.12.2022	008476	16.12.2022	TN67BJ6163	Chemplast Sanmar Limited (Plant-III)	Salem	16.3	Brine Sludge	17.28	DLF
953	16.12.2022	008535	16.12.2022	TN66E9714	Chemplast Sanmar Limited (Plant-III)	Salem	16.3	Brine Sludge	17.04	DLF

954	17.12.2022	000669	16.12.2022	TN38BW0249	Jayachandran Alloys Pvt Ltd	Perundurai	9.1	Waste Slag	18.58	LAT-147
955	17.12.2022	000223	16.12.2022	TN21AJ0966	AKR Industries (P) Ltd	Perundurai	35.3	ETP Sludge-Solids	17.47	LAT-75
956	17.12.2022	008477	17.12.2022	TN67BJ6163	K.P.R. Mills Limited	Perundurai	35.3	ETP Waste	20.54	LAT-75
957	17.12.2022	008423	17.12.2022	TN11K1747	K.P.R. Mills Limited	Perundurai	35.3	ETP Waste	22.94	LAT-75
958	17.12.2022	008430	17.12.2022	TN67BJ2452	K.P.R. Mills Limited	Perundurai	35.3	ETP Waste	22.74	LAT-75
959	17.12.2022	008336	17.12.2022	TN59CC7493	K.P.R. Mills Limited	Perundurai	35.3	ETP Waste	15.96	LAT-75
960	17.12.2022	008443	17.12.2022	TN67BJ6024	Chemplast Sanmar Limited (Plant-III)	Salem	16.3	Brine Sludge	17.25	DLF
961	17.12.2022	008514	17.12.2022	TN67BJ6181	Chemplast Sanmar Limited (Plant-III)	Salem	16.3	Brine Sludge	17.19	DLF
962	18.12.2022	000670	17.12.2022	TN40P0275	Jayachandran Alloys Pvt Ltd	Perundurai	9.1	Waste Slag	18.23	LAT-147
963	18.12.2022	008337	18.12.2022	TN59CC7493	K.P.R. Mills Limited	Perundurai	35.3	ETP Waste	15.97	LAT-75
964	18.12.2022	008361	18.12.2022	TN23BL5836	K.P.R. Mills Limited	Perundurai	35.3	ETP Waste	18.17	LAT-75
965	18.12.2022	008431	18.12.2022	TN67BJ2452	K.P.R. Mills Limited	Perundurai	35.3	ETP Waste	23.13	LAT-75
966	18.12.2022	008444	18.12.2022	TN67BJ6024	K.P.R. Mills Limited	Perundurai	35.3	ETP Waste	21.68	LAT-75
967	18.12.2022	008515	18.12.2022	TN67BJ6181	K.P.R. Mills Limited	Perundurai	35.3	ETP Waste	23.67	LAT-75
968	18.12.2022	008488	18.12.2022	TN45AS9097	K.P.R. Mills Limited	Perundurai	35.3	ETP Waste	16.49	LAT-75
969	19.12.2022	000671	18.12.2022	TN38BW0249	Jayachandran Alloys Pvt Ltd	Perundurai	9.1	Waste Slag	18.51	LAT-147
970	19.12.2022	008432	19.12.2022	TN67BJ2452	Chemplast Sanmar Limited (Plant-III)	Salem	16.3	Brine Sludge	17.57	DLF
971	19.12.2022	008502	19.12.2022	TN59CB8706	Chemplast Sanmar Limited (Plant-III)	Salem	16.3	Brine Sludge	17.81	DLF
972	19.12.2022	008424	19.12.2022	TN11K1747	Chemplast Sanmar Limited (Plant-III)	Salem	16.3	Brine Sludge	16.66	DLF
973	19.12.2022	008516	19.12.2022	TN67BJ6181	Chemplast Sanmar Limited (Plant-III)	Salem	16.3	Brine Sludge	17.35	DLF
974	20.12.2022	000224	19.12.2022	TN21AJ0966	AKR Industries (P) Ltd	Perundurai	35.3	ETP Sludge-Solids	17.28	LAT-75
975	21.12.2022	000672	20.12.2022	TN38BW0249	Jayachandran Alloys Pvt Ltd	Perundurai	9.1	Waste Slag	18.44	LAT-147
976	21.12.2022	008426	21.12.2022	TN11K1747	Sither Metal Industry	Tuticorin	9.1	Lead slag	23.92	DLF
977	22.12.2022	000225	21.12.2022	TN21AJ0966	AKR Industries (P) Ltd	Perundurai	35.3	ETP Sludge-Solids	17.48	LAT-75
978	23.12.2022	000673	22.12.2022	TN40P0275	Jayachandran Alloys Pvt Ltd	Perundurai	9.1	Waste Slag	18.19	LAT-147
979	24.12.2022	000674	23.12.2022	TN38BW0249	Jayachandran Alloys Pvt Ltd	Perundurai	9.1	Waste Slag	18.93	LAT-147
980	24.12.2022	000226	23.12.2022	TN21AJ0966	AKR Industries (P) Ltd	Perundurai	35.3	ETP Sludge-Solids	17.47	LAT-75
981	24.12.2022	008340	24.12.2022	TN59CC7493	Rane Brake Lining Ltd	Trichy	35.1	Gas cleaning residue	15.08	LAT-1
982	25.12.2022	000675	24.12.2022	TN38BW0249	Jayachandran Alloys Pvt Ltd	Perundurai	9.1	Waste Slag	18.58	LAT-147
983	25.12.2022	008364	24.12.2022	TN23BL5836	Rane Brake Lining Ltd	Trichy	35.1	Gas cleaning residue	16.09	LAT-1
984	26.12.2022	000676	25.12.2022	TN40P0275	Jayachandran Alloys Pvt Ltd	Perundurai	9.1	Waste Slag	18.55	LAT-147
985	26.12.2022	008435	26.12.2022	TN67BJ2452	Sundram Fasteners Ltd	Virudhunagar	35.3	Chemical Sludge from WWT	18.33	LAT-9
986	26.12.2022	008436	26.12.2022	TN67BJ2452	Sundram Fasteners Ltd	Virudhunagar	35.3	Salt	19.55	LAT-75
987	27.12.2022	000227	26.12.2022	TN21AJ0966	AKR Industries (P) Ltd	Perundurai	35.3	ETP Sludge-Solids	17.16	LAT-75
988	28.12.2022	008520	27.12.2022	TN67BJ6181	Premier Textiles Dyers	Erode	35.3	Sludge	15.19	LAT-1
989	28.12.2022	008562	28.12.2022	TN11K1747	Sither Metal Industry	Tuticorin	9.1	Lead slag	21.89	DLF
990	28.12.2022	008437	28.12.2022	TN67BJ2452	Sither Metal Industry	Tuticorin	9.1	Lead slag	23.19	DLF
991	28.12.2022	008491	28.12.2022	TN45AS9097	Sri Energy Valves Private Limited	Pudukkottai	11.4	Flue gas dust	0.94	DLF
992	29.12.2022	000228	28.12.2022	TN21AJ0966	AKR Industries (P) Ltd	Perundurai	35.3	ETP Sludge-Solids	17.03	LAT-75
993	29.12.2022	008563	29.12.2022	TN11K1747	Kals Breweries Pvt Ltd	Pudukkottai	35.3	RO Treated Sludge	1.37	LAT-1
994	29.12.2022	008564	29.12.2022	TN11K1747	Kals Breweries Pvt Ltd	Pudukkottai	35.3	ETP Sludge	9.4	LAT-5
995	30.12.2022	008492	30.12.2022	TN45AS9097	Navarang Dye Works	Karur	35.3	Salt from SEP	15.655	LAT-75
996	30.12.2022	008521	30.12.2022	TN67BJ6181	Navarang Dye Works	Karur	35.3	Salt from SEP	18.28	LAT-75
997	30.12.2022	008525	30.12.2022	TN37BR9477	Resustainability Healthcare Solutions Ltd	Virudhunagar	37.2	Incineration Ash	2.425	DLF
998	30.12.2022	008524	30.12.2022	TN37BR9477	Resustainability Healthcare Solutions Ltd	Virudhunagar	37.2	ETP Sludge	4.3	DLF
999	31.12.2022	000229	30.12.2022	TN21AJ0966	AKR Industries (P) Ltd	Perundurai	35.3	ETP Sludge-Solids	17.46	LAT-75
1000	31.12.2022	008493	31.12.2022	TN45AS9097	Sri Vigneshwara Foundry	Coimbatore	9.1	Slag	16.79	DLF
1001	31.12.2022	008583	31.12.2022	TN67BJ6024	Sri Vigneshwara Foundry	Coimbatore	9.1	Slag	17.085	DLF
1002	03.01.2023	000230	02.01.2023	TN21AJ0966	AKR Industries (P) Ltd	Perundurai	35.3	ETP Sludge-Solids	17.31	LAT-75
1003	04.01.2023	008438	03.01.2023	TN67BJ2452	Imperial Textile Dyers	Erode	35.3	Sludge	16.93	LAT-10
1004	04.01.2023	008607	04.01.2023	TN67BJ2452	Sither Metal Industry	Tuticorin	9.1	Lead Slag	24.33	DLF
1005	04.01.2023	008199	04.01.2023	TN45AS9097	Zirconium complex	Tuticorin	Schedule-2, class-C	Washed and dried slit	14.92	LAT-93
1006	04.01.2023	008200	04.01.2023	TN59CB8706	Zirconium complex	Tuticorin	Schedule-2, class-C	Washed and dried slit	16.93	LAT-93
1007	04.01.2023	008201	04.01.2023	TN67BJ6181	Zirconium complex	Tuticorin	37.1	Neutralized silt	17.67	LAT-75
1008	04.01.2023	008202	04.01.2023	TN11K1747	Zirconium complex	Tuticorin	37.1	Neutralized silt	16.05	LAT-75
1009	05.01.2023	000231	04.01.2023	TN21AJ0966	Shahi Knits Pvt Ltd	Perundurai	35.3	ETP Sludge-Solids	17.29	LAT-75
1010	05.01.2023	008585	05.01.2023	TN67BJ6024	Sundram Fasteners Ltd	Virudhunagar	35.3	Chemical Sludge from WWT	18.26	LAT-9
1011	05.01.2023	008495	05.01.2023	TN45AS9097	Sundram Fasteners Ltd	Virudhunagar	35.3	Chemical Sludge from WWT	13.62	LAT-9
1012	05.01.2023	008342	05.01.2023	TN59CC7493	Sither Metal Industry	Tuticorin	9.1	Lead Slag	16.14	DLF
1013	05.01.2023	008496	05.01.2023	TN45AS9097	Sundram Fasteners Ltd	Virudhunagar	35.3	Chemical Sludge from WWT	12.82	LAT-9

1014	05.01.2023	008586	05.01.2023	TN67BJ6024	Sundram Fasteners Ltd	Virudhunagar	35.3	ATFD Salt	20.34	LAT-75
1015	07.01.2023	000232	06.01.2023	TN21AJ0966	Shahi Knits Pvt Ltd	Perundurai	35.3	ETP Sludge-Solids	17.46	LAT-75
1016	08.01.2023	008494	07.01.2023	TN67BJ6181	Chemplast Sanmar Limited (Plant-III)	Salem	16.3	Brine Sludge	17.44	DLF
1017	08.01.2023	008587	07.01.2023	TN67BJ6024	Chemplast Sanmar Limited (Plant-III)	Salem	16.3	Brine Sludge	17.28	DLF
1018	08.01.2023	008508	07.01.2023	TN59CB8706	Green Era Recyclers	Coimbatore	B110	FL glass	2.74	LAT-197
1019	08.01.2023	008509	07.01.2023	TN59CB8706	Green Era Recyclers	Coimbatore	B110	CRT glass	1.09	LAT-198
1020	08.01.2023	008655	07.01.2023	TN45AS9097	Mcwin International	Tirupur	35.3	Chemical Sludge from WWT	0.12	LAT-134
1021	08.01.2023	008656	07.01.2023	TN45AS9097	Stylus Printers	Tirupur	35.3	Chemical Sludge from WWT	0.21	LAT-11
1022	08.01.2023	008657	07.01.2023	TN45AS9097	Print House	Tirupur	35.3	Chemical Sludge from WWT	0.3	LAT-5
1023	08.01.2023	008658	07.01.2023	TN45AS9097	D.G.K.Knit Printing	Tirupur	35.3	Chemical Sludge from WWT	0.52	LAT-1
1024	08.01.2023	008659	07.01.2023	TN45AS9097	Image Printers	Tirupur	35.3	Chemical Sludge from WWT	1	LAT-124
1025	08.01.2023	008660	07.01.2023	TN45AS9097	Phoenix(Washing Unit)	Tirupur	35.3	Chemical Sludge from WWT	0.31	DLF
1026	08.01.2023	008661	07.01.2023	TN45AS9097	Jaya Sakthi Transfer	Tirupur	35.3	Chemical Sludge from WWT	0.27	LAT-134
1027	08.01.2023	008662	07.01.2023	TN45AS9097	Jupiter Tech Prints	Tirupur	35.3	Chemical Sludge from WWT	1.07	LAT-5
1028	08.01.2023	008663	07.01.2023	TN45AS9097	Balaji Printers	Tirupur	35.3	Chemical Sludge from WWT	0.89	LAT-5
1029	08.01.2023	008664	07.01.2023	TN45AS9097	Shahi Exports Pvt Ltd	Tirupur	35.3	Chemical Sludge from WWT	0.77	LAT-1
1030	08.01.2023	008665	07.01.2023	TN45AS9097	Mirra Printographic	Tirupur	35.3	Chemical Sludge from WWT	0.86	DLF
1031	09.01.2023	008482	09.01.2023	TN67BJ6163	Chemplast Sanmar Limited (Plant-III)	Salem	16.3	Brine Sludge	17.34	DLF
1032	10.01.2023	000233	09.01.2023	TN21AJ0966	Shahi Knits Pvt Ltd	Perundurai	35.3	ETP Sludge-Solids	17.5	LAT-75
1033	11.01.2023	008608	11.01.2023	TN67BJ2452	Chemplast Sanmar Limited (Plant-III)	Salem	16.3	Brine Sludge	17.82	DLF
1034	11.01.2023	008497	11.01.2023	TN45AS9097	Chemplast Sanmar Limited (Plant-III)	Salem	16.3	Brine Sludge	17.14	DLF
1035	12.01.2023	000234	11.01.2023	TN21AJ0966	Shahi Knits Pvt Ltd	Perundurai	35.3	ETP Sludge-Solids	17.65	LAT-75
1036	12.01.2023	008588	10.01.2023	TN67BJ6024	Rane Engine Valve Ltd	Pudukkottai	5.2	Waste Containing Sludge	19.48	DLF
1037	12.01.2023	008483	11.01.2023	TN67BJ6163	Emaar Lead Company Pvt Ltd	Coimbatore	9.1	Lead Slag	18.02	DLF
1038	12.01.2023	008609	12.01.2023	TN67BJ2452	Chemplast Sanmar Limited (Plant-III)	Salem	16.3	Brine Sludge	17.59	DLF
1039	14.01.2023	000235	13.01.2023	TN21AJ0966	Shahi Knits Pvt Ltd	Perundurai	35.3	ETP Sludge-Solids	17.43	LAT-75
1040	14.01.2023	008589	13.01.2023	TN67BJ6024	Lakshmi Machine Works Ltd(Unit-1)	Coimbatore	12.5	Phosphate Sludge	0.56	LAT-11
1041	14.01.2023	008590	13.01.2023	TN67BJ6024	Lakshmi Machine Works Ltd(Unit-1)	Coimbatore	35.3	ETP Chemical Sludge	1.36	LAT-124
1042	19.01.2023	008592	19.01.2023	TN67BJ6024	Sither Metal Industry	Tuticorin	9.1	Lead Slag	22.14	DLF
1043	20.01.2023	000236	19.01.2023	TN21AJ0966	Shahi Knits Pvt Ltd	Perundurai	35.3	ETP Sludge-Solids	17.34	LAT-75
1044	15.03.2023	008593	15.03.2023	TN67BJ6024	Chemplast Sanmar Limited (Plant-III)	Salem	16.3	Brine Sludge	17.36	DLF
1045	15.03.2023	008636	15.03.2023	TN67BJ6181	Chemplast Sanmar Limited (Plant-III)	Salem	16.3	Brine Sludge	17.28	DLF
1046	15.03.2023	008612	15.03.2023	TN67BJ2452	Chemplast Sanmar Limited (Plant-III)	Salem	16.3	Brine Sludge	17.32	DLF
1047	15.03.2023	008573	15.03.2023	TN59CB8706	Chemplast Sanmar Limited (Plant-III)	Salem	16.3	Brine Sludge	18.15	DLF
1048	16.03.2023	008574	16.03.2023	TN59CB8706	Sundram Fasteners Ltd	Virudhunagar	35.3	ATFD salt	19.01	LAT-75
1049	16.03.2023	008613	16.03.2023	TN67BJ2452	Sundram Fasteners Ltd	Virudhunagar	35.3	Chemical sludge from WWT	17.45	LAT-9
1050	16.03.2023	008681	16.03.2023	TN11K1747	Chemplast Sanmar Limited (Plant-III)	Salem	16.3	Brine Sludge	17.25	DLF
1051	16.03.2023	008614	16.03.2023	TN67BJ2452	Sundram Fasteners Ltd	Virudhunagar	35.3	Chemical sludge from WWT	17.78	LAT-9
1052	16.03.2023	008575	16.03.2023	TN59CB8706	Sundram Fasteners Ltd	Virudhunagar	35.3	ATFD salt	19.15	LAT-75
1053	16.03.2023	008637	16.03.2023	TN67BJ6181	Chemplast Sanmar Limited (Plant-III)	Salem	16.3	Brine Sludge	17.69	DLF
1054	16.03.2023	008691	16.03.2023	TN45AS9097	Chemplast Sanmar Limited (Plant-III)	Salem	16.3	Brine Sludge	16.58	DLF
1055	16.03.2023	008485	16.03.2023	TN67BJ6163	Chemplast Sanmar Limited (Plant-III)	Salem	16.3	Brine Sludge	17.43	DLF
1056	16.03.2023	008716	16.03.2023	TN59CC7493	Imperial Textile Dyers	Erode	35.3	Sludge	15.12	LAT-10
1057	17.03.2023	008549	17.03.2023	TN76E7898	Sirius Zip Fasteners Pvt Ltd	Sivagangai	6.2	Zinc Dust	0.1821	LAT-103
1058	17.03.2023	008550	17.03.2023	TN76E7898	Performance Speciality Products(India) Pvt Ltd	Madurai	35.3	Chemical sludge from WWT	0.45	LAT-163
1059	17.03.2023	008638	17.03.2023	TN67BJ6181	K.P.R.Mill Limited	Erode	35.3	ETP Waste	20.06	LAT-75
1060	17.03.2023	008486	17.03.2023	TN67BJ6163	K.P.R.Mill Limited	Erode	35.3	ETP Waste	21.21	LAT-75
1061	17.03.2023	008576	17.03.2023	TN59CB8706	K.P.R.Mill Limited	Erode	35.3	ETP Waste	18.23	LAT-75
1062	17.03.2023	008692	17.03.2023	TN45AS9097	K.P.R.Mill Limited	Erode	35.3	ETP Waste	16.53	LAT-75
1063	17.03.2023	008682	17.03.2023	TN11K1747	K.P.R.Mill Limited	Erode	35.3	ETP Waste	21.94	LAT-75
1064	17.03.2023	008598	17.03.2023	TN23BL5836	Chemplast Sanmar Limited (Plant-III)	Salem	16.3	Brine Sludge	17.88	DLF
1065	17.03.2023	008727	17.03.2023	TN67BJ6024	Chemplast Sanmar Limited (Plant-III)	Salem	16.3	Brine Sludge	17.21	DLF
1066	17.03.2023	008717	17.03.2023	TN59CC7493	Chemplast Sanmar Limited (Plant-III)	Salem	16.3	Brine Sludge	15.65	DLF
1067	17.03.2023	008615	17.03.2023	TN67BJ2452	Chemplast Sanmar Limited (Plant-III)	Salem	16.3	Brine Sludge	17.47	DLF
1068	18.03.2023	008577	18.03.2023	TN59CB8706	K.P.R.Mill Limited	Erode	35.3	ETP Waste	18.28	LAT-75
1069	18.03.2023	008639	18.03.2023	TN67BJ6181	K.P.R.Mill Limited	Erode	35.3	ETP Waste	21.88	LAT-75
1070	18.03.2023	008693	18.03.2023	TN45AS9097	K.P.R.Mill Limited	Erode	35.3	ETP Waste	16.53	LAT-75
1071	19.03.2023	008719	19.03.2023	TN59CC7493	Chemplast Sanmar Limited (Plant-III)	Salem	16.3	Brine Sludge	16.13	DLF
1072	19.03.2023	008729	19.03.2023	TN67BJ6024	Chemplast Sanmar Limited (Plant-III)	Salem	16.3	Brine Sludge	17.75	DLF
1073	19.03.2023	008704	19.03.2023	TN67BJ6163	Chemplast Sanmar Limited (Plant-III)	Salem	16.3	Brine Sludge	18.21	DLF

1074	19.03.2023	008684	19.03.2023	TN11K1747	Chemplast Sanmar Limited (Plant-III)	Salem	16.3	Brine Sludge	16.64	DLF
1075	20.03.2023	008618	20.03.2023	TN67BJ2452	Sundram Fasteners Ltd	Virudhunagar	35.3	ATFD salt	22.51	LAT-75
1076	20.03.2023	008579	20.03.2023	TN59CB8706	Sundram Fasteners Ltd	Virudhunagar	35.3	ATFD salt	19.59	LAT-75
1077	20.03.2023	008601	20.03.2023	TN23BL5836	Sundram Fasteners Ltd	Virudhunagar	35.3	Chemical sludge from WWT	17.51	LAT-9
1078	20.03.2023	008695	20.03.2023	TN45AS9097	Medicare Enviro Systems	Thanjavur	37.2	Incineration Ash	9.52	DLF
1079	20.03.2023	008641	20.03.2023	TN67BJ6181	Chemplast Sanmar Limited (Plant-III)	Salem	16.3	Brine Sludge	17.66	DLF
1080	20.03.2023	008580	20.03.2023	TN59CB8706	Sundram Fasteners Ltd	Virudhunagar	35.3	ATFD salt	19.35	LAT-75
1081	20.03.2023	008730	20.03.2023	TN67BJ6024	Kovai Bio waste Management Pvt Ltd	Coimbatore	37.2	Incineration Ash	10.77	DLF
1082	20.03.2023	008731	20.03.2023	TN67BJ6024	Kovai Bio waste Management Pvt Ltd	Coimbatore	35.3	ETP Sludge	2.27	LAT-5
1083	20.03.2023	008739	20.03.2023	TN67BJ2452	Sundram Fasteners Ltd	Virudhunagar	35.3	Chemical sludge from WWT	19.5	LAT-9
1084	20.03.2023	008720	20.03.2023	TN59CC7493	Chemplast Sanmar Limited (Plant-III)	Salem	16.3	Brine Sludge	16.11	DLF
1085	21.03.2023	008012	20.03.2023	TN59CA5614	Chemplast Sanmar Ltd(Plant-2)	Salem	35.3	Chemical sludge from WWT	16.78	DLF
1086	21.03.2023	008602	21.03.2022	TN23BL5836	Sundram Fasteners Ltd	Virudhunagar	35.3	ATFD salt	21.44	LAT-75
1087	21.03.2023	008732	21.03.2023	TN67BJ6024	Sither Metal Industry	Tuticorin	9.1	Lead Slag	22.74	DLF
1088	21.03.2023	008603	21.03.2023	TN23BL5836	Sundram Fasteners Ltd	Virudhunagar	35.3	Chemical sludge from WWT	19.54	LAT-9
1089	21.03.2023	008707	21.03.2023	TN67BJ6163	Tekno therm industries	Coimbatore	35.3	ETP Sludge	2.85	LAT-11
1090	21.03.2023	008706	21.03.2023	TN67BJ6163	Tekno therm industries	Coimbatore	37.2	Incineration Ash	11.34	DLF
1091	22.03.2023	008740	21.03.2023	TN67BJ2452	Chemplast Sanmar Ltd(Plant-2)	Salem	35.3	Chemical sludge from WWT	17.48	DLF
1092	22.03.2023	008721	21.03.2023	TN59CC7493	Chemplast Sanmar Ltd(Plant-2)	Salem	35.3	Chemical sludge from WWT	15.77	DLF
1093	22.03.2023	008722	22.03.2023	TN59CC7493	Sundram Fasteners Ltd	Virudhunagar	35.3	Chemical sludge from WWT	17.48	LAT-9
1094	22.03.2023	008723	22.03.2023	TN59CC7493	Sundram Fasteners Ltd	Virudhunagar	35.3	Chemical sludge from WWT	18.72	LAT-9
1095	22.03.2023	008687	22.03.2023	TN11K1747	EID Parry(India) Limited	Pudukkottai	35.3	Chemical sludge	6	LAT-5
1096	22.03.2023	008688	22.03.2023	TN11K1747	EID Parry(India) Limited	Pudukkottai	35.3	Chemical sludge	9.15	LAT-5
1097	22.03.2023	008698	22.03.2023	TN45AS9097	Tvs Sundaram Industries Pvt Ltd	Madurai	35.3	ETP Sludge	2.2	DLF
1098	22.03.2023	008697	22.03.2023	TN45AS9097	JK Fenner India Ltd	Madurai	35.3	Chemical sludge from WWT	0.985	LAT-9
1099	23.03.2023	008582	23.03.2023	TN59CB8706	Sundram Fasteners Ltd	Virudhunagar	35.3	Chemical sludge from WWT	18.43	LAT-9
1100	23.03.2023	008709	23.03.2023	TN67BJ6163	Sundram Fasteners Ltd	Virudhunagar	35.3	Chemical sludge from WWT	18.22	LAT-9
1101	23.03.2023	008764	23.03.2023	TN59CB8706	Sundram Fasteners Ltd	Virudhunagar	35.3	Chemical sludge from WWT	18.04	LAT-9
1102	23.03.2023	008710	23.03.2023	TN67BJ6163	Sundram Fasteners Ltd	Virudhunagar	35.3	Chemical sludge from WWT	17.68	LAT-9
1103	23.03.2023	008537	23.03.2023	TN66E9714	ATC Tires Private Limited	Tirunelveli	35.3	Chemical sludge from WWT	4.94	LAT-10
1104	23.03.2023	008090	23.03.2023	TN66E9714	ATC Tires Private Limited	Tirunelveli	6.2	Zinc Dust	6.56	LAT-103
1105	23.03.2023	008689	23.03.2023	TN11K1747	Emaar Lead Company Pvt Ltd	Coimbatore	9.1	Lead Slag	21.51	DLF
1106	23.03.2023	008014	23.03.2023	TN59CA5614	Emaar Lead Company Pvt Ltd	Coimbatore	9.1	Lead Slag	20.05	DLF
1107	23.03.2023	008741	23.03.2023	TN67BJ2452	Shri Kara Engineering Private Ltd	Coimbatore	35.3	Chemical sludge from WWT	18.17	LAT-103
1108	24.03.2023	008015	24.03.2023	TN59CA5614	K.P.R.Mill Limited	Erode	35.3	ETP Waste	20.75	LAT-75
1109	24.03.2023	008690	24.03.2023	TN11K1747	K.P.R.Mill Limited	Erode	35.3	ETP Waste	22.82	LAT-75
1110	24.03.2023	008765	24.03.2023	TN59CB8706	K.P.R.Mill Limited	Erode	35.3	ETP Waste	18.05	LAT-75
1111	24.03.2023	007703	24.03.2023	TN66E9714	K.P.R.Mill Limited	Erode	35.3	ETP Waste	16.53	LAT-75
1112	24.03.2023	008711	24.03.2023	TN67BJ6163	K.P.R.Mill Limited	Erode	35.3	ETP Waste	21.48	LAT-75
1113	24.03.2023	008752	24.03.2023	TN67BJ6181	K.P.R.Mill Limited	Erode	35.3	ETP Waste	20.99	LAT-75
1114	24.03.2023	008742	24.03.2023	TN67BJ2452	K.P.R.Mill Limited	Erode	35.3	ETP Waste	20.7	LAT-75
1115	24.03.2023	008699	24.03.2023	TN45AS9097	K.P.R.Mill Limited	Erode	35.3	ETP Waste	16.45	LAT-75
1116	24.03.2023	008734	24.03.2023	TN67BJ6024	K.P.R.Mill Limited	Erode	35.3	ETP Waste	20.14	LAT-75
1117	24.03.2023	008605	24.03.2023	TN23BL5836	Hindustan Unilever Ltd	Kodaikanal	35.3	ETP Sludge	8.23	LAT-155
1118	25.03.2023	008753	25.03.2023	TN67BJ6181	Ramesh Flowers Pvt Ltd	Tuticorin	35.3	Chemical Sludge	14.98	DLF
1119	25.03.2023	008712	25.03.2023	TN67BJ6163	K.P.R.Mill Limited	Erode	35.3	ETP Waste	19.49	LAT-75
1120	25.03.2023	008725	25.03.2023	TN59CC7493	K.P.R.Mill Limited	Erode	35.3	ETP Waste	17.18	LAT-75
1121	25.03.2023	008735	25.03.2023	TN67BJ6024	K.P.R.Mill Limited	Erode	35.3	ETP Waste	21.01	LAT-75
1122	25.03.2023	008743	25.03.2023	TN67BJ2452	K.P.R.Mill Limited	Erode	35.3	ETP Waste	19.03	LAT-75
1123	25.03.2023	008775	25.03.2023	TN11K1747	K.P.R.Mill Limited	Erode	35.3	ETP Waste	22.69	LAT-75
1124	25.03.2023	008700	25.03.2023	TN45AS9097	K.P.R.Mill Limited	Erode	35.3	ETP Waste	16.64	LAT-75
1125	25.03.2023	008016	25.03.2023	TN59CA5614	K.P.R.Mill Limited	Erode	35.3	ETP Waste	20.07	LAT-75
1126	25.03.2023	008606	25.03.2023	TN23BL5836	Ence Aromatics(P)Ltd	Coimbatore	35.3	Salt from ETP	14.44	LAT-75
1127	25.03.2023	008767	25.03.2023	TN59CB8706	Hindustan Unilever Ltd	Kodaikanal	35.3	ETP Sludge	6.56	LAT-155
1128	25.03.2023	008766	25.03.2023	TN59CB8706	Hindustan Unilever Ltd	Kodaikanal	Schedule-II Class-A7	Contaminated building debris	2.76	LAT-214
1129	26.03.2023	008701	26.03.2023	TN45AS9097	K.P.R.Mill Limited	Erode	35.3	ETP Waste	16.91	LAT-75
1130	26.03.2023	008726	26.03.2023	TN59CC7493	K.P.R.Mill Limited	Erode	35.3	ETP Waste	16.7	LAT-75
1131	26.03.2023	008736	26.03.2023	TN67BJ6024	K.P.R.Mill Limited	Erode	35.3	ETP Waste	19.78	LAT-75
1132	26.03.2023	008776	26.03.2023	TN11K1747	K.P.R.Mill Limited	Erode	35.3	ETP Waste	22.76	LAT-75
1133	26.03.2023	008744	26.03.2023	TN67BJ2452	K.P.R.Mill Limited	Erode	35.3	ETP Waste	21.06	LAT-75

1134	26.03.2023	008768	26.03.2023	TN59CB8706	K.P.R.Mill Limited	Erode	35.3	ETP Waste	18	LAT-75
1135	26.03.2023	008799	26.03.2023	TN23BL5836	K.P.R.Mill Limited	Erode	35.3	ETP Waste	17.36	LAT-75
1136	26.03.2023	008713	26.03.2023	TN67BJ6163	K.P.R.Mill Limited	Erode	35.3	ETP Waste	21	LAT-75
1137	26.03.2023	008754	26.03.2023	TN67BJ6181	K.P.R.Mill Limited	Erode	35.3	ETP Waste	20.7	LAT-75
1138	26.03.2023	008017	26.03.2023	TN59CA5614	K.P.R.Mill Limited	Erode	35.3	ETP Waste	17.67	LAT-75
1139	27.03.2023	008777	27.03.2023	TN11K1747	Sundram Fasteners Ltd	Virudhunagar	35.3	Chemical sludge from WWT	16.89	LAT-9
1140	27.03.2023	008811	27.03.2023	TN59CC7493	Sundram Fasteners Ltd	Virudhunagar	35.3	Chemical sludge from WWT	17.69	LAT-9
1141	27.03.2023	008755	27.03.2023	TN67BJ6181	K.P.R.Mill Limited	Erode	35.3	ETP Waste	22.29	LAT-75
1142	27.03.2023	008745	27.03.2023	TN67BJ2452	K.P.R.Mill Limited	Erode	35.3	ETP Waste	20.3	LAT-75
1143	27.03.2023	008018	27.03.2023	TN59CA5614	K.P.R.Mill Limited	Erode	35.3	ETP Waste	18.52	LAT-75
1144	27.03.2023	008702	27.03.2023	TN45AS9097	K.P.R.Mill Limited	Erode	35.3	ETP Waste	17.1	LAT-75
1145	27.03.2023	008714	27.03.2023	TN67BJ6163	K.P.R.Mill Limited	Erode	35.3	ETP Waste	20.92	LAT-75
1146	27.03.2023	008769	27.03.2023	TN59CB8706	K.P.R.Mill Limited	Erode	35.3	ETP Waste	20.92	LAT-75
1147	27.03.2023	008812	27.03.2023	TN59CC7493	Sundram Fasteners Ltd	Virudhunagar	35.3	ATFD salt	20.54	LAT-75
1148	27.03.2023	008737	27.03.2023	TN67BJ6024	Hindustan Unilever Ltd	Kodaikanal	Schedule-II Class-A7	Contaminated building debris	17.04	LAT-214
1149	28.03.2023	008738	28.03.2023	TN67BJ6024	Sither Metal Industry	Tuticorin	9.1	Lead Slag	22.15	DLF
1150	28.03.2023	008770	28.03.2023	TN59CB8706	Sri Energy Valves Private Limited	Pudukkottai	11.4	Flue gas dust	1.57	DLF
1151	28.03.2023	008847	28.03.2023	TN59CA5614	Chemplast Sanmar Limited (Plant-III)	Salem	16.3	Brine Sludge	18.56	DLF
1152	28.03.2023	008847	28.03.2023	TN67BJ2452	Chemplast Sanmar Limited (Plant-III)	Salem	16.3	Brine Sludge	18.05	DLF
1153	28.03.2023	008835	28.03.2023	TN67BJ6163	Chemplast Sanmar Limited (Plant-III)	Salem	16.3	Brine Sludge	17.17	DLF
1154	29.03.2023	008778	28.03.2023	TN11K1747	Lakshmi Ring Travellers(CBE)Pvt Ltd	Coimbatore	35.3	Chemical sludge	6.26	DLF
1155	29.03.2023	008779	28.03.2023	TN11K1747	Genco Metal Works	Coimbatore	35.3	Chemical sludge from WWT	0.645	DLF
1156	29.03.2023	008780	28.03.2023	TN11K1747	Kentex Engineering Works Unit-II	Coimbatore	35.3	Chemical sludge from WWT	0.365	LAT-1
1157	29.03.2023	008800	28.03.2023	TN23BL5836	Jagan Knit Printer	Tiruppur	35.3	Chemical sludge from WWT	1.46	LAT-5
1158	29.03.2023	008801	28.03.2023	TN23BL5836	Amman Graphics	Tiruppur	35.3	Chemical sludge from WWT	0.08	LAT-5
1159	29.03.2023	008802	28.03.2023	TN23BL5836	Neon Knit Printss	Tiruppur	35.3	Chemical sludge from WWT	1.06	LAT-1
1160	29.03.2023	008803	28.03.2023	TN23BL5836	Dinesh Textile Mills	Tiruppur	35.3	Chemical sludge from WWT	4.58	LAT-134
1161	29.03.2023	008804	28.03.2023	TN23BL5836	Rasi Screen Printing	Tiruppur	35.3	Chemical sludge from WWT	1.1	LAT-10
1162	29.03.2023	008805	28.03.2023	TN23BL5836	Poppys Knit Wear(P) Ltd	Tiruppur	35.3	Chemical sludge from WWT	1.8	DLF
1163	29.03.2023	008747	29.03.2023	TN67BJ2452	cabot Sanmar Limited (Plant-4)	Salem	17.1	Acidic residue dust filter cake	16.66	DLF
1164	29.03.2023	008813	29.03.2023	TN59CC7493	cabot Sanmar Limited (Plant-4)	Salem	17.1	Acidic residue dust filter cake	16.46	DLF
1165	29.03.2023	008756	29.03.2023	TN67BJ6181	Chemplast Sanmar Limited (Plant-III)	Salem	16.3	Brine Sludge	17.21	DLF
1166	29.03.2023	008771	29.03.2023	TN59CB8706	Chemplast Sanmar Limited (Plant-III)	Salem	16.3	Brine Sludge	18.17	DLF
1167	29.03.2023	008859	29.03.2023	TN67BJ6024	Chemplast Sanmar Limited (Plant-III)	Salem	16.3	Brine Sludge	17.59	DLF
1168	30.03.2023	008757	30.03.2023	TN67BJ6181	Chemplast Sanmar Ltd(Plant-2)	Salem	35.3	Chemical sludge from WWT	17.19	DLF
1169	30.03.2023	008837	30.03.2023	TN67BJ6163	Malco Energy Limited	Salem	Schedule-II Class-2,5	Glass wool	7.78	DLF
1170	30.03.2023	008815	30.03.2023	TN59CC7493	Malco Energy Limited	Salem	Schedule-II Class-2,5	Glass wool	7.19	DLF
1171	30.03.2023	008814	30.03.2023	TN59CC7493	Malco Energy Limited	Salem	15.2	Discarded asbestos	2	DLF
1172	30.03.2023	008823	30.03.2023	TN59CB8706	Hi-Tech Arai Pvt Ltd(K.Pudur)	Madurai	12.5	Phosphate Sludge	0.551	LAT-161
1173	30.03.2023	008824	30.03.2023	TN59CB8706	Hi-Tech Arai Pvt Ltd(K.Pudur)	Madurai	35.3	Chemical sludge from WWT	1.029	LAT-161
1174	30.03.2023	008825	30.03.2023	TN59CB8706	Hi-Tech Arai Pvt Ltd(Kappalur)	Madurai	35.3	Chemical sludge from WWT	4.43	LAT-10
1175	30.03.2023	008826	30.03.2023	TN59CB8706	Hi-Tech Arai Pvt Ltd(Kappalur)	Madurai	12.5	Phosphate Sludge	5	LAT-157
1176	31.03.2023	008758	31.03.2023	TN67BJ6181	cabot Sanmar Limited (Plant-4)	Salem	17.1	Acidic residue dust filter cake	16.28	DLF
1177	31.03.2023	008827	31.03.2023	TN59CB8706	cabot Sanmar Limited (Plant-4)	Salem	17.1	Acidic residue dust filter cake	17.76	DLF
1178	31.03.2023	008838	31.03.2023	TN67BJ6163	Chemplast Sanmar Ltd(Plant-2)	Salem	35.3	Chemical sludge from WWT	17.2	DLF
1179	31.03.2023	008807	31.03.2023	TN23BL5836	Chemplast Sanmar Ltd(Plant-2)	Salem	36.3	Chemical sludge from WWT	17.54	DLF
1180	31.03.2023	008851	31.03.2023	TN59CA5614	Chemplast Sanmar Limited (Plant-III)	Salem	35.3	Chemical sludge from WWT	11.24	DLF
1181	31.03.2023	008850	31.03.2023	TN59CA5615	Chemplast Sanmar Limited (Plant-III)	Salem	16.3	Brine Sludge	7.18	DLF

DLF (MT)	4480.16
LAT (MT)	14198.50
Total Quantity (MT)	18678.66